Office District I	State of i	New Me	xico	Form C-10		
<u> 1311121 1</u>	Energy, Minerals a	and Natu	ral Resources	March 4, 200		
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERV	ATION	DIVISION	30-015-31432		
District III	1220 South			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe			STATE & FEE		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Saina re	, 14141 07	505	6. State Oil & Gas Lease No.		
87505						
	ICES AND REPORTS ON	WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPO				State "W"		
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM	и C-101) FC	OR SUCH	State W		
PROPOSALS.) 1. Type of Well:		RE(CEIVED	8. Well Number		
Oil Well Gas Well	Other			2		
	OCT 1 8 2005		9. OGRID Number			
2. Name of Operator	roducing Company	OOD	NESTRA	9. OGRID Number 017891		
3. Address of Operator	Toddering company	<u> </u>	As well in the contract of	10. Pool name or Wildcat		
	Midland, TX 7970	02-7340	1	Undes Frontier Hills; Strawn		
	MICHAIC, IX 1970	02-7540	,	Undes Frontier Hills; Strawn		
4. Well Location						
I Init Latter M .	660 fact from the	South	line and	660 feet from the West line		
Ont Letter M:			i inic and	integration theintegration		
Section 3	Township 2	35 R a	inge 26E	NMPM Eddy County		
	11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3312					
Pit or Below-grade Tank Application (Fo		res, a form	C-144 must be attach	(ed)		
				Distance from nearest fresh water well		
j .						
Distance from nearest surface water			Sect1w	/p		
feet from theline and _	feet from the	_line	•			
PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION		REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: P11	RILLING OPNS. PLUG AND ABANDONMENT AND D agging back		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed we or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For	state all p	COMMENCE DE CASING TEST A CEMENT JOB OTHER: P11 Detrinent details, and le Completions: A	RILLING OPNS. PLUG AND ABANDONMENT AND Signing back Signing back Address and give pertinent dates, including estimated datash wellbore diagram of proposed completic		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TO PULL OR ALTER CASING THER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/06/04 Set CIBP @ 11,455°. Test to 41/09/04 Acdz w/ 1000 gals 15% acid. 11/17/04 Set CIBP @ 10,390°. Test to 41/18/04 Acdz w/ 1500 gals 15% acid. Well is SI pending Engineering	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the second	state all por Multipor Multipor Multipor Multipor 10,308-336	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: P1u Detrinent details, and the Completions: A 10412-420, 10506-3	RILLING OPNS. PLUG AND ABANDONMENT ABANDON		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TO PULL OR ALTER CASING THER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/06/04 Set CIBP @ 11,455°. Test to 41/09/04 Acdz w/ 1000 gals 15% acid. 11/17/04 Set CIBP @ 10,390°. Test to 41/18/04 Acdz w/ 1500 gals 15% acid. Well is SI pending Engineering I hereby certify that the information	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For the second secon	state all por Multipor Multipo	REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER: P1u Detrinent details, and the Completions: A 10412-420, 10506-3 6 w/ 2 spf.	RILLING OPNS. PLUG AND ABANDONMENT AND Signing back Signing back Address and give pertinent dates, including estimated datash wellbore diagram of proposed completic		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TO PULL OR ALTER CASING THER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/06/04 Set CIBP @ 11,455°. Test to 41/09/04 Acdz w/ 1000 gals 15% acid. 11/17/04 Set CIBP @ 10,390°. Test to 41/18/04 Acdz w/ 1500 gals 15% acid. Well is SI pending Engineering Thereby certify that the information	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For the second of the sec	r state all por Multip. Perf Strawn 10,308-336 10,154'.	SUE REMEDIAL WOR COMMENCE DE CASING TEST A CEMENT JOB OTHER: Plu Detrinent details, and le Completions: A 10412-420, 10506-3 6 w/ 2 spf. est of my knowled 1, a general permit Description	RILLING OPNS. PLUG AND ABANDONMENT AND Sugging back Sugging back Sugging back Sugging back Sugging back Sugging back Proposed complete Sugging back		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TO PULL OR ALTER CASING THER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/06/04 Set CIBP @ 11,455°. Test to 41/09/04 Acdz w/ 1000 gals 15% acid. 11/17/04 Set CIBP @ 10,390°. Test to 41/18/04 Acdz w/ 1500 gals 15% acid. Well is SI pending Engineering I hereby certify that the information grade tank has been/will be constructed or	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For the second of the sec	r state all por Multip. Perf Strawn 10,308-336 10,154'.	REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER: Plu Dertinent details, and le Completions: A 10412-420, 10506-4 6 w/ 2 spf. est of my knowled 1, a general permit Compogoproductions Compog	RILLING OPNS. PLUG AND ABANDONMENT AND Sugging back Sugging back Sugging back Sugging back Sugging back Sugging back Proposed complete Sugging back		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/06/04 Set CIBP @ 11,455'. Test to 41/09/04 Acdz w/ 1000 gals 15% acid. 11/17/04 Set CIBP @ 10,390'. Test to 41/17/04 Set CIBP @ 10,390'. Test to 41/18/04 Acdz w/ 1500 gals 15% acid. Well is SI pending Engineering I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Cathy Wright (This space for State use)	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clearly ork). SEE RULE 1103. For the second of the secon	state all por Multip. Perf Strawn 10,308-336 10,154'. e to the beguidelines [ITTLE	REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER: Plu Dertinent details, and le Completions: A 10412-420, 10506-4 6 w/ 2 spf. est of my knowled 1, a general permit Compogoproductions Compog	RILLING OPNS. PLUG AND ABANDONMENT AND ABANDONMENT Augging back Adaptive pertinent dates, including estimated dattach wellbore diagram of proposed completing and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan DATE 10/14/05 ing.com 432-685-8100 Telephone No.		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/06/04 Set CIBP @ 11,455'. Test to 4 11/09/04 Acdz w/ 1000 gals 15% acid. 11/17/04 Set CIBP @ 10,390'. Test to 4 11/18/04 Acdz w/ 1500 gals 15% acid. Well is SI pending Engineering I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Cathy Wright (This space for State use)	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the second of the seco	state all por Multip. Perf Strawn 10,308-336 10,154'. e to the beguidelines [ITTLE	REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER: Plu Dertinent details, and le Completions: A 10412-420, 10506-4 6 w/ 2 spf. est of my knowled 1, a general permit Compogoproductions Compog	RILLING OPNS. PLUG AND ABANDONMENT AND Sugging back Sugging back Proposed complete states and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan DATE 10/14/05 ing.com 432-685-8100		