Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ARTESIA DISTRICARTESIA
SEP 29 20:4

FURM A	PPROVED
OMB NO	. 1004-0135
Expires: J	uly 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED to not use this form for proposals to drill or to re-enter an	5. Lease Serial No. NMNM104667
bandoned well. Use form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS KECEIVED Do not use this form for proposals to drill or to re-enter an			VED [NMNM104667 .		
abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side.				6. If Indian, Allottee	or Tribe Name	
				7. If Unit or CA/Agre	eement, Name and/or No.	
I. Type of Well ☐ Oil Well ☑ Gas Well ☐ Oth	her			8. Well Name and No TUNA 28 FEDEF		
2. Name of Operator Contact: BRIAN MAIORINO COG OPERATING LLC E-Mail: bmaiorino@concho.com				9. API Well No. 30-015-37645-0	00-S1	
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701	3b. Phon Ph: 432	e No. (include area code 2-221-0467)	10. Field and Pool, or WILDCAT	Exploratory 522F; BS/64	
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)		į.	11. County or Parish,	and State	
Sec 28 T26S R25E NENE 13	00FNL 660FEL		·	EDDY COUNT	Y, NM	
12. CHECK APPI	ROPRIAȚE BOX(ES) TO INDICA	TE NATURE OF 1	NOTICE, REI	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION		ТҮРЕ О	FACTION			
, Notice of Intent	☐ Acidize ☐ I	Deepen	☐ Productio	n (Start/Resume)	☐ Water Shut-Off	
- .	, -	Fracture Treat	☐ Reclamati	on	☐ Well Integrity	
☐ Subsequent Report	_	New Construction	Recomple Recomple	·	Other	
☐ Final Abandonment Notice		Plug and Abandon – . Plug Back	☐ Temporar ☐ Water Dis	porarily Abandon		
determined that the site is ready for fit COG Operating LLC respectfut to the Avalon Shale in the Tun MIRU Swab test 2nd Bone Spring. Esample and give to Baker. Remove wellhead & install BO Release Packer & TOH Ensure hole is full Run GR/CBL from 6330? to 20 Set CIBP @ 5400?	elly request to abandon the 1st, 2nd a 28 Federal #1 Ensure tubing volume is cleared and P.	, and 3rd Bone Spri d water is clean. Ob CEPTED FOR 10 NMOCD	ngs and recor	WIT PLUG SEE A	NESS BACK TTACHED FOR NS OF APPROVAL	
14. I hereby certify that the foregoing is Comm Name(Printed/Typed) BRIAN MA	Electronic Submission #232585 veri For COG OPERATING nitted to AFMSS for processing by J	i LLC, sent to the Ca ENNIFER MASON on	rlsbad	JAM0044SE)	711117	
Signature (Electronic S	ubmission)	Date 01/21/20)14	APPR	OVED	
	THIS SPACE FOR FEDE	RAL OR STATE (OFFICE USE			
Approved By		Title		SEP 2	4 2014 Dair/1	
Conditions of approval, if any, are attached	Approval of this notice does not warrant of table title to those rights in the subject lease to operations thereon.			BUREAU OF LAN	D MANADEMENT	
itle 18 U.S.C. Section 1001 and Title 43 U States any false, fictitious or fraudulent st	J.S.C. Section 1212, make it a crime for any attements or representations as to any matter	person knowingly and r within its jurisdiction.	willfully to make	to any department or a	agency of the United	

Additional data for EC transaction #232585 that would not fit on the form


32. Additional remarks, continued

phasing utilizing Halliburton cased hole log dated 6/21/10.
TIH w/tubing & packer. Spot acid across perfs. Set packer at 4950?
Acidize zone with 3000 gallons 15% HCl at 3 ? 5 BPM while dropping balls
Shut-in 1 hour & flow back
Swab test zone. If after load is recovered and no show of gas, will need to swab test each perf
cluster individually
Pull tubing and packer
Set frac valve & prepare for frac.
Frac well.
Shut-in well for 24 hours
Flow well back until dead.
TIH with tubing & gas lift equipment (if needed).
Place well on test

All operations will be conducted using a closed loop system.

Author:	Stroup			
Well Name	Tuna 28 Fed	Well No.	#1	
Field	Milepost	API#:	30-015-37645	
County	Eddy	Prop #:		
State	New Mexico	Zone:	Bone Spring	
Date	4/15/2013			
GL	3680'			
KB	3697'			

	<u> </u>	<u> </u>				
Description	O.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 3/8	H40	48	279	360	Surface
Inter Csg	9 5/8	J55	36	1,220	550	Surface
Prod Csg	7	P110	23	9,962	1,475	Surface
Liner						



TD @ 10000'

17 1/2" hole

13-3/8" (H40 - 48#) @ 279' w/360 sx TOC @ surface

2-3/8" N80 Tbg

12 1/4" hole

9-5/8" (J55 - 36#) @ 1220' w/550 sx TOC @ surface

DV Tool @ 3003' w/500 sx

Short Joint @ 6572'

197 jts 2 3/8" tubing

1st Bone Spring: 5449, 5502, 5556, 5614 Packer @ 5904' 2nd Bone Spring: 6003, 6057, 6130, 6206

CIBP @ 6330'

Bone Spring Charkey Sand: 6664, 6716, 6775, 6865 DV Tool @ 6985' w/550 sx 3rd Bone Spring: 7306, 7352, 7411, 7505

Wolfcamp cement plug: 7600-7820

Cement plug 9218-9522 CIBP @ 9630'

9680-82, 9686-95, 9698-9700 Morrow

8 3/4" hole

7" (P110 - 23#) @ 9962' w/425 sx TOC @ Surface

Author: Well Name	Stroup Tuna 28 Fed	Well No.	#1	
Field	Milepost		30-015-37645	
County	Eddy	Prop #:		
State	New Mexico	Zone:	Bone Spring	
Date	4/15/2013			
GL	3680'			
KB	3697'			

Description	O.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 3/8	H40	48	279	360	Surface
Inter Csg	9 5/8	J55	36	1,220	550	Surface
Prod Csg	7	P110	23	9,962	1,475	Surface
Liner						

TD @ 10000'

Proposed Wellbore

17 1/2" hole 13-3/8" (H40 - 48#) @ 279' w/360 sx TOC @ surface

2-3/8" N80 Tbg

12 1/4" hole

9-5/8" (J55 - 36#) @ 1220' w/550 sx TOC @ surface

DV Tool @ 3003' w/500 sx

Short Joint @ 6572'

Avalon Shale: 5020, 5150, 5230

CIBP @ 5400'

1st Bone Spring: 5449, 5502, 5556, 5614 Packer @ 5904'

2nd Bone Spring: 6003, 6057, 6130, 6206

CIDD @ cocci

CIBP @ 6330'

Bone Spring Charkey Sand: 6664, 6716, 6775, 6865

DV Tool @ 6985' w/550 sx

3rd Bone Spring: 7306, 7352, 7411, 7505

Wolfcamp cement plug: 7600-7820

Cement plug 9218-9522

CIBP @ 9630'

9680-82, 9686-95, 9698-9700 Morrow

8 3/4" hole

7" (P110 - 23#) @ 9962' w/425 sx TOC @ Surface

Conditions of Approval

COG Operating Tuna – 01, API 3001537645 T26S-R25E, Sec 28, 1300FNL & 660FEL September 24, 2014

- 1. A NMOCD Form C-102 "Well Location and Acreage Dedication Plat" with updated information is necessary with the notice of intent package when recompletion changes a well's Pool designation.
- 2. Before casing or a liner is added, replaced, or repaired prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Considering that the well is to be used for commercial water disposal a BLM Right of Way Agreement is to be secured before its use.
- 5. Notify BLM 575-200-7902 Eddy Co. as work begins. Some procedures are to be witnessed. If there is no response, call 575-361-2822, leave a voice mail with the API#, workover purpose, and a call back phone number
- 6. Surface disturbance beyond the existing pad must have prior approval.
- 7. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 8. Functional H₂S monitoring equipment shall be on location.
- 9. 3000 (3M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 10. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 11. The BLM PET witness is to run tbg tally and agree to cement volumes and placement.

 Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.
- 12. This procedure is subject to the next three numbered paragraphs.
- 13. Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less

- than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 1/2" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.
- 14. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.
- 15. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 16. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 6330 or below to top of cement taken with Opsig casing pressure. The CBL may be attached to a pswartz@blm.gov email. The CFO BLM on call engineer may be reached at 575-706-2779.
- 17. Should the operator not intend to produce the open Bone Spring perfs 6003-7503 with the proposed 5020-5230 Avalon Shale (within Bone Spring formation) the next two numbered paragraphs will need to be accomplished.
- 18. Tag the existing cement plug at 7525 and set a minimum 40sx Class "H" plug from this PBTD. The plug is to cover the Wolfcamp formation top of 7525. Tag the plug with tubing above or at 7475.
- 19. Set a minimum 35sx Class "C" plug from 7035 to cover the DV Tool at 6985. Tag the plug with tubing above or at 6930.
- 20. After setting the top plug and before perforating, perform a charted casing integrity test of 1000psig minimum. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 25 to 85 per cent of its full range. Verify all annular casing vents are plumbed to the surface and open during this pressure test. Call BLM 575-200-7902 and arrange for a BLM witness of that pressure test. Include a copy of the chart in the subsequent sundry for this workover.
- 21. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry. File the subsequent sundry for the frac separately if it is delayed as much as 20 days.
- 22. Submit the BLM Form 3160-4 Recompletion Report within 30 days of the date all BLM approved procedures are complete.
- 23. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

24. Submit evidence to support your determination that the well has been returned to active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies) before 12/20/2014.

25. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

PRS 09242014

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.—