Subspit I Cowy To Appropriate District Office	State of New Me		Form C-103		
District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	ON CONGERNATION PROPERTY.		30-015-26797		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
<u>District III</u> (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE S FEE		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505		6. State Oil & Gas Lease No. L-6425		
	TICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement	Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Ruby 30 State  8. Well Number		
1. Type of Well: Oil Well Gas Well Other			1		
2. Name of Operator				9. OGRID Number	
Mewbourne Oil Company		14744			
	3. Address of Operator PO Box 5270, Hobbs NM 88241			10. Pool name or Wildcat Wildcat Morrow 97565	
4. Well Location				,	
Unit Letter_ O				ie	
Section 30	Township 24S Range 29				
April 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	11. Elevation (Show whether DR, 2917' GL	RKB, RT, GR, etc.)			
12 Charl	. Aista Dan ta Indianta N	-4 CNI-4:	Daniel an Other Data		
12. Check	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data		
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CA					
PERFORM REMEDIAL WORK [	<del></del>	<del></del>	NG 🔲		
TEMPORARILY ABANDON [ PULL OR ALTER CASING [				لــا	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB   DOWNHOLE COMMINGLE					
OTHER [	]	OTHER:			
	npleted operations. (Clearly state all pwork). SEE RULE 19.15.7.14 NMAC recompletion.				
			0010001/471		
Please review the attached plugging procedure for the above captioned well.			NM OIL CONSERVATI ARTESIA DISTRICT	ON	
Approved for plugging of well bore only.  Liability under bond is retained pending receipt			MAR <b>2 4</b> 2015		
CONDITIONS OF APPROVAL ATTACHE	of C-103 (Subsequent Rep which may be found at OC		WAIL 2 4 ZUIS		
	Forms, www.cmnrd.state.n		RECEIVED		
Approval Granted providing work i		to	RECEIVED		
Completed by 3/14/2011	Rig Release Da	ite:			
<u> </u>					
I hereby certify that the information	on above is true and complete to the be	est of my knowledge	e and belief.		
SIGNATURE	Tham TITLE Regul	atory DAT	ΓΕ03/24/15		
Type or print name _Jackie Latha	n E-mail address: jlathan@mewb	ourne.comP	HONE: _575-393-5905		
For State Use Only	hold	-DS ~	2/1155 1/-1/	20	
APPROVED BY: / VOUCE TITLE HIST A CYCLON / DATE 3/24/200					
Conditions of Approval (if any):					

\* See Attached COA's

# INSTERNATION ON CONTRAPORTALLY

### **COMPLETION PROCEDURE**

Submitted By: E. McMath

Wellname: Ruby 30 State Com #1

Location: 990' FSL & 1980' FEL Sec 30, T24S, R29E 29E

Eddy Co, NM

Eddy Co, NIVI

Date: 1/12/2015

Prod Csg Set: 10120' Inter Csg Set 2760'

7" 23#, 7" 26#, & 7" 32#

Prod Csg: N-80 & S95 Inter Csg 9 %" 36# K-55

PBTD: 5100' TOC @: Surface

**Perfs:** 3312'-3472' **Tbg:** 2 1/8" 6.5# J-55


**TOC** @: 1200' **Tbg Set:** 3440'

#### Procedure:

- 1. Test anchors. MIRU BCM. ND WH & NU BOP. POOH w/tbg & LD 7 jts.
- 2. RIH w/CIBP & tbg.
- 3. Set CIBP @ 3250' (perfs @ 3312'-3472').
- 4. Spot 25 sks Class "C" cmt on top of CIBP.
- 5. POOH to 3125 and spot 13 bbl balanced mud pill.
- 6. POOH to 2810' and Spot 25 sks Class "C" cmt plug.
- 7. POOH to 2685' and spot 55 bbl balanced mud pill.
- 8. POOH to 1235' and spot 25 sks Class C plug.
- 9. POOH to 1110' and spot 18 bbl balanced mud pill.
- 10 POOH to 650' and spot 25 sks Class C plug.
- 11. POOH to 525' and spot 16 bbl balanced mud pill.
- 12. POOH to 125' and circ cmt to surface with 25 sks. POOH and top off as needed.
- 13. ND BOP & RDMO BCM.
- 14. Cut off WH & install dry hole marker @ ground level.


#### Mewbourne Oil Company

Well Name: Ruby 30 State Com #1 - Proposed Schematic



#### **Mewbourne Oil Company**

Well Name: Ruby 30 State Com #1 - Current Schematic



## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Mcwbownl	
Well Name & Number: Ruby 30 State	#/
API#: 30-015-26797	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 3/24/2015

APPROVED BY:

#### GUIDELINES FOR PLUGGING AND ABANDONMENT

#### DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement,
   whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub
  plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).