

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

OCT 19 2015  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB1529347766*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Devon Energy Production <i>10137</i>		Contact Randy Gladden	
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 575.513.9463	
Facility Name Cotton Draw Unit 89		Facility Type SWD	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-31381	

**LOCATION OF RELEASE**

Unit Letter O	Section 3	Township 25S	Range 31E	Feet from the 250	North/South Line FSL	Feet from the 1980	East/West Line FEL	County EDDY
------------------	--------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.1527913 Longitude: -103.7619791

**NATURE OF RELEASE**

Type of Release Spill Produced Water	Volume of Release 500 BBL	Volume Recovered 500 BBL
Source of Release Ruptured water tank	Date and Hour of Occurrence 10/7/15 10:30 pm	Date and Hour of Discovery 10/7/15 10:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM Mike Bratcher OCD	
By Whom? Randy Gladden	Date and Hour 10/8/15 at 2:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Water Hauler backed into load line at SWD rupturing two water tanks. 500 BBL produced water released into lined containment and 500 BBL produced water recovered.		
Describe Area Affected and Cleanup Action Taken.* Vacuum truck called out and recovered all 500 BBL of produced water. Liner was checked for holes and no holes found.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jeanette Barron	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist	
Title: Field Admin Support	Approval Date: <i>10/20/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: 10/09/15 Phone: 575.748.1813		

\* Attach Additional Sheets If Necessary.

*2RP-3347*