
۰ · ·			
Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-015-25450		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	District II – (575) 748-1283 811 S. First St. Artesia, NM 88210 OIL CONSERVATION DIVISION		
District_III - (505) 334-6178	strict III – (505) 334-6178 1220 South St. Francis Dr.		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
$\frac{1015(rr(c1V) - (505) 476-5460}{1220 \text{ S. St. Francis Dr., Santa Fe, NM}$	<u>Planet H</u> (See) in a plane		
87505	LH-1800		
SUNDRY NOTI	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC	Nº IM		
PROPOSALS.)	DiMaggio		
1. Type of Well: Oil Well	8. Well Number (O		
2. Name of Operator	9. OGRID Number		
OXY USA	16696		
3. Address of Operator	10. Pool name or Wildcat		
P.O. Box 5	Brushy Draw Delaware		
4. Well Location			
Unit Letter P :	660 feet from the South line and l	oloofeet from theline	
Section	Township 26S Range 25E	NMPM County Falar	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.		
	2422'		
		and the second	
12 Cheale	Anneonvieta Day ta Indianta Natura of Nation	Banart or Other Data	
12. Check A	Appropriate Box to Indicate Nature of Notice	, Report or Other Data	
NOTICE OF IN		SEQUENT REPORT OF:	
	PLUG AND ABANDON		
		ит јов	
OTHER:	leted operations. (Clearly stelle all pertinent details, and		
	ork). SEE RULE 19.15. NMAC. For Multiple Co		
proposed completion or rec		· · · · · · · · · · · · · · · · · · ·	
TD-5230'	-	Approved for plugging of well bore only.	
10-5230	PBTD-5185' Perfs-4978-5020'	Liability under bond is retained pending receipt	
0.5/0%.24		of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under	
	# csg @ 552' w/ 450sx, 12-1/4" hole, TOC-Surf-Circ	Forms www.mound.mound.it.	
4-1/2 11	.6# csg @ 5230', DVT @ 1990', 4002' w/ 1820sx, 7-7/	8" hole, TOC-Surf-Circ	
1 500 0			
	set CIBP @ 4928', M&P 25sx cmt to 4728'		
	5sx cmt @ 4102-3902' WOC-Tag	•	
	5sx cmt @ 2900-2700' WOC-Tag	NM OIL CONSERVATION	
	5sx cmt @ 2090-1890' WOC-Tag	ARTESIA DISTRICT	
	Osx cmt @ 602' to surface	NOVO	
	ALF between plugs	NOV 2 0 2015	
Above gro	ound steel tanks will be utilized		
[·	RECEIVED	
Spud Date:	Rig Release Date:	I TOLIVED	
well Bore must 1	Be Plugged by 11-20-2016		
	above is true and complete to the best of my knowled	ge and belief.	
		-	
		1 1	
SIGNATURE	TITLE Sr. Regulatory Advis	OT DATE (1/17/15	
Type or print name <u>David Stewa</u>	<u>rt</u> E-mail address: <u>david_stewart</u>	@oxy.com PHONE: <u>432-685-5717</u>	
For State Use Only			
(AI)	OLE	DATE 11/20/2015	
APPROVED BY:	TITLE	DATE 11/20/2015	
Conditions of Approval (if any):	Son Atterland MA:		

7




5 OXY USA Inc. - Current DiMaggio #10 API No. 30-015-28450

-

.

12-1/4" hole @ 552' 8-5/8" csg @ 552' w/ 450sx-TOC-Surf-Circ

.



NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:	OX	9		
Well Name	& Number:	DI MAGGIO	#10	
API #:		-015-28450		

A.11

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.

10. Plugs may be combined after consulting with and getting approval from NMOCD.

- 11. Minimum WOC time for tag plugs will be 4 Hrs.
- 12. 19.15.7.16 : B. In the case of a dry hole, a complete record of the well on form C-105 with the attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE:

11/20/2015

APPROVED BY:

REVISED:11/2015

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman

Ż

.

Ĕ

Ŧ,

- o Devonian
- o Morrow
- o Wolfcamp
- o Bone Spring
- o Delaware
- Any Salt Section (Plug at top and bottom)
- o Abo
- o Glorieta
- o Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).