

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-29583
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BERETTA 15 STATE COM
8. Well Number 2
9. OGRID Number 6137
10. Pool name or Wildcat Carlsbad;Morrow, South (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator Devon Energy Production Company, LP	
3. Address of Operator 333 W. Sheridan Avenue, Oklahoma City, OK 73102	
4. Well Location Unit Letter <u>G</u> : <u>2180</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>15</u> Township <u>23S</u> Range <u>26E</u> NMPM Eddy County, NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3335' KB; 3317' GL; 18' KB to GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
CLOSED-LOOP SYSTEM <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU P&A unit and equipment. Retrieve 2-3/8" production tubing and packer set in 4-1/2" liner at 11,458'.
2. Set a 4-1/2" CIBP @ 11,450'. Circulate with 10# mud. (Open Morrow perfs 11,524' - 11,600')
3. Spot 70 sx (705') CI H @ 11,450' - 10,745'. Tag TOC.
4. Perf 7" casing @ 8,680'. Pump 50 sx (140') CI H in/out @ 8,680' - 8,540'. (T.Wolfcamp @ 8,682') - WUE & TAL.
5. Perf 7" casing @ 5,540'. Pump 120 sx (430') CI C in/out @ 5,540' - 5,110'. (3000' spacer @ 5540'; T.BS @ 5200') - WUE & TAL.
6. Perf 7" casing @ 2,740'. Pump 40 sx (140') CI C in/out @ 2,740' - 2,600'. Tag TOC.
7. Perf 7" casing @ 1,945'. Pump 155 sx (540') CI C in/out @ 1,945' - 1,405'. Tag TOC. (T.Delaware @ 1,945'; B.Salt @ 1,506')
8. Perf 7" casing @ 715'. Pump 50 sx (175') CI C in/out @ 715' - 540'. Tag TOC. (T.Salt @ 716')
9. Perf 7" casing @ 140'. Pump 40 sx CI C in/out to surface.
10. Cut wellhead off 3' BGL. Set dry hole marker.

SEE SCHEMATIC FOR ADDED PLUGS  
N.M. OIL CONSERVATION  
DISTRICT  
APPROVED FOR PLUGGING OF WELLBORE  
Liability under bond is retained by the  
of C-103 (Subsequent Report of Wellbore  
Form, www.nmnr.state.nm.us

Spud Date:

Rig Release Date:

WELL MUST BE PLUGGED BY 12/19/17

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ronnie Slack TITLE Production Technologist DATE 12-14-16

Type or print name Ronnie Slack E-mail address: Ronnie.Slack@dvn.com PHONE: 405-552-4615

For State Use Only

APPROVED BY: Robert J. Buel TITLE COMPLIANCE OFFICER DATE 12/19/16  
Conditions of Approval (if any):

★ SEE ATTACHED COA-S

**DEVON ENERGY PRODUCTION COMPANY LP**

Well Name: <b>BERETTA 15 STATE COM #2</b>	Field: <b>CARLSBAD MORROW SOUTH</b>
Location: <b>2180' FNL &amp; 1980' FEL; SEC 15-T23S-R26E</b>	County: <b>EDDY</b> State: <b>NM</b>
Elevation: <b>3335' KB; 3317' GL; 18' KB to GL</b>	Spud Date: <b>1/28/98</b> Compl Date: <b>3/29/98</b>
API#: <b>30-015-29583</b> Prepared By: <b>Ronnie Slack</b>	Date: <b>12/8/16</b> Rev:

**PROPOSED PLUG & ABANDONMENT**

17-1/2" Hole  
**13-3/8", 48#, H40, ST&C, @ 610'**  
 Cmt'd w/ 435 sxs (circ 185 sxs)

12-1/4" Hole  
**9-5/8", 40#, J55, ST&C, @ 2,687'**  
 Cmt'd w/ 950 sxs (circ 126 sxs)

TOC @ 8940' (Temp survey--2/28/98)

Top of 4-1/2" Liner @ 10,857'

8-3/4" Hole  
**7", 26#, P110, LT&C, @ 11,038'**  
 Cmt'd w/ 300 sxs

**MORROW** (5/24/07)

**11,524' - 11,533'**  
**11,585' - 11,600'**

5/30/07: acidized 11524-11600 w/3500 gals 7.5%.  
 Avg 4.5 bpm, 5700 psi

Casing Leak 11660-11672' (5/22/07)

**MIDDLE MORROW B** (perfed 6/16/98)

**11,716' - 11,732'**  
**11,734' - 11,742'**

Acidized w/ 2500 gals 7-1/2% NeFe---(6/18/98)  
 Frac'd w/17700# 20/40---(6/25/98)  
 612 Mcfd, 200# FTP, 26/64",---(6/29/98)

**LOWER MORROW** (perfed 3/29/98)

**11,806' - 11,812'**

803 Mcfd, 850# TP, 14/64"---(4/1/98)

6-1/8" Hole  
**4-1/2", 13.5#, P110, LT&C, @ 12,010'**  
 Cmt'd w/ 125 sxs

10# Mud

10# Mud

10# Mud

10# Mud

10# Mud

10# Mud

**TD @ 12,012'**

Proposed  
 3. Cut wellhead off 3' bgl. Set dry hole marker.  
 2. Pmp 40 sx Cl C in/out to surface.  
 1. Perf 7" csg @ 140'.

Proposed  
 2. Pmp 50 sx (175') Cl C in/out @ 715' - 540'. Tag.  
 1. Perf 7" csg 715'. *WOC & TAG*  
 (T.Salt @ 716')

Proposed  
 2. Pmp 155 sx (540') Cl C in/out @ 1,945' - 1,405'. Tag.  
 1. Perf 7" csg @ 1,945'. *WOC & TAG*  
 (T.Delaware @ 1945'; B.Salt @ 1506')

Proposed  
 2. Pmp 40 sx (140') Cl C in/out @ ~~2,280'~~ <sup>2,687'</sup> - 2,600'. Tag.  
 1. Perf 7" csg @ ~~2,280'~~ <sup>2,687'</sup>. *WOC & TAG*

Proposed  
 2. Pmp 120 sx (430') Cl C in/out @ 5,540' - 5,110'  
 1. Perf 7" csg @ 5,540'. *WOC & TAG*  
 (3000' spacer @ 5,540'; T.BS @ 5,200')

Proposed  
 2. Pmp 50 sx (140') Cl H in/out @ ~~8,680'~~ <sup>8,730' - 8,630'</sup>  
 1. Perf 7" csg @ 8,680'. *WOC & TAG*  
 (Wolfcamp @ 8,682')

Proposed  
 2. Spot 70 sx (705') Cl H @ 11,450' - ~~10,745'~~ <sup>10,580' - COVER STRAW</sup>. Tag TOC.  
 1. Set CIBP @ 11,450'.

20' cement. 11,615' PBD (5/23/07)  
 CIBP @ 11,635' (5/23/07)

10' cement. 11,690' PBD. (5/15/07)  
 CIBP @ 11,700' (5/15/07)

Rec 19' of tcp guns & left 8' guns in hole  
 from fishing job. TOF @ 11,747'---(9/4/98)

RBP @ 11,795' (6/13/98)

*TOP STRAW (10,620')*

*10,580 - COVER STRAW*

④ PERF @ 6650'-SQ-TOE @ 6080'  
 (COVERS FIRST & SECOND BONE SPRING) ADD PLUG

③ PERF @ 8350' + SQ  
 (COVERS THIRD BONE SPRING) ADD PLUG

**DEVON ENERGY PRODUCTION COMPANY LP**

Well Name: <b>BERETTA 15 STATE COM #2</b>		Field: <b>CARLSBAD MORROW SOUTH</b>	
Location: <b>2180' FNL &amp; 1980' FEL; SEC 15-T23S-R26E</b>		County: <b>EDDY</b>	State: <b>NM</b>
Elevation: <b>3335' KB; 3317' GL; 18' KB to GL</b>		Spud Date: <b>1/28/98</b>	Compl Date: <b>3/29/98</b>
API#: <b>30-015-29583</b>	Prepared By: <b>Ronnie Slack</b>	Date: <b>12/5/16</b>	Rev:

**CURRENT WELLBORE**

17-1/2" Hole  
13-3/8", 48#, H40, ST&C, @ 610'  
 Cmt'd w/ 435 sxs (circ 185 sxs)

12-1/4" Hole  
9-5/8", 40#, J55, ST&C, @ 2,687'  
 Cmt'd w/ 950 sxs (circ 126 sxs)

TOC @ 8940' (Temp survey--2/28/98)

Top of 4-1/2" Liner @ 10,857'

8-3/4" Hole  
7", 26#, P110, LT&C, @ 11,038'  
 Cmt'd w/ 300 sxs

**MORROW** (5/24/07)

11,524' - 11,533'  
11,585' - 11,600'

5/30/07: acidized 11524-11600 w/3500 gals 7.5%.  
 Avg 4.5 bpm, 5700 psi

Casing Leak 11660-11672' (5/22/07)

**MIDDLE MORROW B** (perf'd 6/16/98)

11,716' - 11,732'  
11,734' - 11,742'

Acidized w/ 2500 gals 7-1/2% NeFe---(6/18/98)  
 Frac'd w/17700# 20/40---(6/25/98)  
 612 Mcfd, 200# FTP, 26/64",---(6/29/98)

**LOWER MORROW** (perf'd 3/29/98)

11,806' - 11,812'

803 Mcfd, 850# TP, 14/64"---(4/1/98)

6-1/8" Hole  
4-1/2", 13.5#, P110, LT&C, @ 12,010'  
 Cmt'd w/ 125 sxs

Salado--716  
 BX--1506  
 Lamar--1780  
 Bell Canyon--1945  
 Cherry Canyon--2555  
 Brushy Canyon--3610  
 Bone Spring--5200  
 Bone Spring 1st--6138  
 Bone Spring 2nd--6600  
 Bone Spring 3rd--8303  
 Wolfcamp--8682  
 Strawn--10620  
 Atoka--11006  
 Morrow--11320  
 Barnett--11920

2-3/8" Production tubing

Blanking plug set. Suspect hole in tbgs. (12/10/10)  
 Packer @ 11,458' (5/25/07)

20' cement. 11,615' PBD (5/23/07)  
 CIBP @ 11,635' (5/23/07)

10' cement. 11,690' PBD. (5/15/07)  
 CIBP @ 11,700' (5/15/07)

Rec 19' of tcp guns & left 8' guns in hole  
 from fishing job. TOF @ 11,747'---(9/4/98)

RBP @ 11,795' (6/13/98)

TD @ 12,012'

## CONDITIONS FOR PLUGGING AND ABANDONMENT

### District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, **Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.**

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. **Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.**
7. Produced water **will not** be used during any part of the plugging operation.
8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
9. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
10. **Class 'C' cement will be used above 7500 feet.**
11. **Class 'H' cement will be used below 7500 feet.**
12. **A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged**
13. **All Casing Shoes Will Be Perforated and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing**
14. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
15. **A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.**
16. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, **(WOC 4 hrs and tag).**

17. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

18. Formations to be isolated with cement plugs are:

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) **Potash---** (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, **WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.**

19. **If cement does not exist behind casing strings at recommended formation depths**, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

#### **DRY HOLE MARKER REQUIREMENTS**

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

**1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County**

#### **(SPECIAL CASES)**

##### **AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS**

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)