Submit 1 Copy To Appropriate District Office	State of New Mexico			Form C-103		
District I (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II (575) 748-1283	Energy, Minerals and Natural Resources			WELL API NO.	Revised August 1, 2011	
811 S. First St., Artesia, NM 88210	OIL CONSERV	ATION	DIVISION	5. Indicate Type o	f Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South	St. Fran	icis Dr.	STATE STATE	FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505			6. State Oil & Gas	Lease No. 17914	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		JG BACK TO A DR SUCH	7. Lease Name or Todd 2 State	Unit Agreement Name		
PROPOSALS.)	PROPOSALS.)			8. Well Number: 1	0	
2. Name of Operator	2. Name of Operator			9. OGRID Numbe	r	
Chevron USA INC				4323		
3. Address of Operator 6301 DEAUVILLE BLVD., MI	 Address of Operator 6301 DEAUVILLE BLVD., MIDLAND, TX 79706 			Shoe Bar, Strawn NE		
4. Well Location	080 fact from the	North	ling and	220 Fact from	the West line	
Section 2	Township 249		ine and	NMPM	County Eddy	
	11. Elevation (Show wh	ether DR.	RKB, RT, GR, etc.)	County Eddy	
	3,468' GL	······		<u></u>	AN COMPANY	
12. Check A	ppropriate Box to Inc	licate N	ature of Notice,	Report or Other I	Data	
NOTICE OF IN	FENTION TO:		SUB	SEQUENT REF	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	Ø	REMEDIAL WOR	K 🗍		
			COMMENCE DR		PANDA	
	MULTIPLE COMPL		CASING/CEMEIN			
		-	OTUER	TEMPORADU V		
13 Describe proposed or compl	eted operations (Clearly	state all 1	pertinent details, an	d give pertinent dates	s including estimated date	
of starting any proposed wor proposed completion or reco 6,400', Perforations 7,126'	rk). SEE RULE 19.15.7. ompletion. 11-3/4" @ 675 -7,258', 8,049'-8,196'.	14 NMAG 5' TOC S	C. For Multiple Co urface, 8-5/8'' @ 4	mpletions: Attach we 4,300' TOC Surface	ellbore diagram of , 5-1/2" @ 8,240' TOC @	
Chevron USA	A INC respectfully	reque	st to abandon	this well as fol	lows:	
1. Call and notify NMOC	1. Call and notify NMOCD 24 hrs before operations begin.					
2. MIRU, NDWH, NU BO	OPE, POOH w/ rods	& tbg.				
3. Set CIBP at 7,100', circ	MLF, test csg, spot	25 sx of	CL "C" cement	t on top of CIBP,	WOC & tag.	
4. Perf @ 4,475' and sqz 60 sx Class "C" cement f/ 4,275' t/ 4,475', WOC & tag (B.Salt, Shoe, Delaware).						
5. Perf @ 750' and sqz 210 sx Class "C" cement f/ Surface t/ 750' (T.Salt, Shoe, FW, Surf).						
6. Cut all casings & ancho Clean location	ors & remove 3' below	w grade	. <u>Verify</u> cement	to surface & weld	l on dry hole marker.	
Note: All cement plugs clas	ss "C" or "H" with cl	osed loo	op system used.			
I hereby certify that the information	bove is true and complet	e to the b	est of my knowledg	ge and belief.		
SIGNATURE		ITLE Er	igineer	DATE	8/9/17	
Type or print name <u>Howie Lucas</u>	E-mail address:	howie.	lucas@chevron.co	m PHONE: <u>(83</u>	2)-588-4044	
APPROVED BY: July 2	Byrel TITL	e Con	PLIANIE .	OFFICER DAT	TE_8/10/2017	
BELOW RROUM	O MARKER N	1660 5	TO BE IN	ISTALLED A	FTER PLUCCING	
WELL MUST	BE PLUBB	ED	34 8/10	012018	sging of well bore only receipt sging of well bore pending receipt ad is retained pending Plugging)	
SEE ATT	ACHED COA	-5		Approved index to Liability under the of C.103 (Subsection of C.103) which may be	Sound at OCD Web Page	
				Formis		

Current WBD - Todd 2 State 10

Lease	Todd 2 State	Updated	08/09/17	By. Howie Lucas
Weii #	10	Surf. Loc	1980 FNL 330	FM.
Field	Ingle Wells, Delaware	Bot. Loc	Same	
County	Eddy.	Lat & Long		
State	NM	Unit Letter	E	
Chevno	859969	Secton	2	
API #	30-015-30076	Township& Range	245 & 31E	
Slatus	Shut-in Oil Well	Survey	N.M.P.M	
Battery		Ini. Spud	04/03/98	
		Ini. Comp	06/15/98	

GR. 3468

.

÷

Surface Casing

Size: 11-3/4" Wt., Grd.: 42#, WC-40 Depth. 675' Sxs Cmt 750 sx Circulate: Yes TOC. Surface Hole Size. 14-3/4"

Intermediate Casing

Size: 8-5/8* Wt., Grd.: 24#, J-55 Depth: 4,300' Sxs Cmt: 1,425 sx Circulate: Yes TOC: Surface Hole Size, 11*

Production Casing

Size: 5-1/2" Wt., Grd: 17#, J-55 Depth. 8,240 Sxs Cmt. 600 sx Circulate: No TOC: 6,400' Hole Size: 7-7/8"

 $\frac{Perforation and Stimulation History.}{1/30/33-3/24/03}: Added perforations and addized various formations. Wellwas placed back on production with a TAC set at 6,832:$ Tubing and Rod Detail Tubing Sting Guantic (Tao Bollarin Depth) Desc 222 @(17-7041) Unitrown Grade/ThiesdWeight 2 875 OD-1 @(7041-7043) Tubing Anchor/Catcher 2 875 28 @17043-7952) Unitrown Grade/Thread/Veight 2 875 OD-

1 @(7952-7953) Seat Nipple - Standard (2 875) Cup Type-1 @(7953-7958) Perforated Tubing Sub 2 875-1 @(7958-8020) Nud Anchor 2 875-

1 @(8020-8021) Bull Plug (Unknown Type) - 2 875-

Rod Sting Quanty (Top. Bottam Depth) Desc 1 @(17-43) 1 500 (1 1/2 in) Spray Metal + 25-1 @(43-47) 0 875 (7/8 iii) (Uriknown) x 4 Rod Sup-

- 115 @(47-2922) 0 875 (7/8 in) (Unithown) + 25 Rod 90 @(2922:5172) 0 750 (3/4 in) (Unithown) + 25 Rod 8 @(5172:5372) 1 503 (1 1/2 m) (Unknown) + 25 Sinker Bar-
- 1 @(5372-5396) Rod Pump (Insert (NON-SERIALIZED) 25-160-R HBU -0-0 (Bore = 1 50)-101 @(5395-7921) 1 000 (1 in) (Unknown) × 25 Rod-

4			
1			
~<			
22	Perts		
< N	7,126 -7,169	7,252	-7,258
1	Peris		

8,049-8 1501, 8,139-8,196

Southeastern New Mexico

T. Ashy	T. Canyon
T. Sali702	T. Serve
B. Salt4397	T. Andra
T. Yana	T. Miss
T. 7 River	T. Devonina
T. Queen	T. Siberian
T. Grayburg	T. MORENYA
T. Sen Andres	T. Simpson
T. Glorieta	T. McKee
T. Paddock	T. Ellenburger
T. Blinebry	T. Gr. Wash
T. Tubb	T. Delaware Sand 4425
T. Drinkard	T. Bone Serings8254
Т. Аво	т
T. Wolfcamp	T
T. Pesso	1.
T. Cisco (Bough C)	Τ.

PBTD: 8,198 TD 8,240





CONDITIONS FOR PLUGGING AND ABANDONMENT

District II / Artesia N.M.

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 7. Produced water **will not** be used during any part of the plugging operation.
- 8. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 9. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 10. Class 'C' cement will be used above 7500 feet.
- 11. Class 'H' cement will be used below 7500 feet.
- 12. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 13. All Casing Shoes Will Be Perforated and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing
- 14. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 15. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

٠

- 17. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 18. No more than **3000' is allowed between cement plugs in cased hole and 2000' in open hole.**
- 19. Any Production Formations will be isolated with cement plugs: Some of these are:
 - A) Strawn, Fusselman, Devonian, Marrow, Atoka, Wolfcamp, Bone springs, Delaware, San Andres, Abo, Glorieta, Any Salt Section, (Potash), Grayburg, Queen, Yates, Tubb, 7-Rivers
 - B) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 20. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3. API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County

(SPECIAL CASES)

AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)