Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
Change Minarala and Matural Pagavraga	Revised July 18, 2013
District 1 - (575) 393-6161 Energy, Witnerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District H. (575) 748-1283	WELL API NO.
District II - (575) 748-1283 UC 1 1 2010 DIVISION	30-015-23998
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION District III – (505) 334-6178	5. Indicate Type of Lease
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 874 DISTRICT II-ARTE 2005 onth St. Francis Dr. Santa Fe, NM 87505	STATE FEE
District IV = (505) 476-3460 Santa Fe, NIVI 8 / 505 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 648
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Millman SB State Com
1. Type of Well: Oil Well Gas Well Other	8. Well Number 1
2. Name of Operator Vanguard Operating LLC	9. OGRID Number 258350
3. Address of Operator	10. Pool name or Wildcat
5847 San Felipe Ste 3000 Houston Texas 77057	South Millman (Morrow)
4. Well Location	
Unit Letter G: 1,980 feet from the North line and 1980 feet from the East line	
Section 16 Township 19S Range 28E NMP!	
11. Elevation (Show whether DR, RKB, RT, GR, etc.,)
3,479 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTION OF INTENTION TO:	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON ☑ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion. Notify OCD 24 hrs . prior to	
	GNY Work done.
1. Notify NWOCD 24 hrs before rigging up.	
 MIRU WS. LD production equipment. RU WL. Set CIBP at 10,751'(top perf 10,801'). Cap with 35ft of cement. 	
4. Fill casing with treated water and pressure test casing to 500 psig for thirty minutes. Record pressure chart.	
Open all casing valves (bradenhead and intermediate) during the internal pressure tests and report a flow or pressure	
change occurring immediately before, during or immediately after the 30 minute pressure test.	
5. RD WS & WL	
6. File subsequent C103 complete with chart.	us may be granted after a
Contact	iful MIT test is performed.
SO it ma	the OCD to schedule the test y be witnessed
	y be witnessed.
Spud Date: Rig Release Date:	
The description of the state of the state of the best of my knowledge and belief	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE TITLE Permian District Superintendent DATE 10/15/2018	
Type or print name <u>C.M. "Marty" Bloodworth, P.E.</u> E-mail address: <u>mbloodworth@vnrenergy.com</u> PHONE: 432-770-9738	
For State Use Only	
APPROVED BY: DATE 18-16-18	
APPROVED BY: DATE 18-16-18 Conditions of Approval (if any):	

