
Office	te of New Mexico		Form C-103 Revised July 18, 2013		
Energy, Min 1625 N. French Dr., Hobbs, NM 88240	erals and Natural Resources	WELL API NO.	Revised July 18, 201.		
District II (575) 749 1292	SERVATION DIVISION	30-015-26454			
811 S. Flist St., Altesia, NW 06210	5. Indicate Type of Lease				
District III – (505) 334-6178 1220 \$	STATE FEE				
<u>District IV</u> – (505) 476-3460 Sar	6. State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPOR	TS ON WELLS	7. Lease Name or L	Jnit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO	Foster AN				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT' PROPOSALS.)	" (FORM C-101) FOR SUCH	8. Well Number			
·	Other PMW	2			
2. Name of Operator	9. OGRID Number				
EOG Y Resources, Inc.	025575 10. Pool name or W	/ildeat			
3. Address of Operator 104 South Fourth Street, Artesia, NM 88210	N. Seven Rivers; Gl				
4. Well Location					
Unit Letter B : 660 feet from the	he North line and	1980 feet from the	ne East line		
Section 1 Township	20S Range 24E	NMPM Eddy	County		
	ow whether DR, RKB, RT, GR, e	<b></b>			
12. Check Appropriate Box	to Indicate Nature of Notic	e, Report or Other D	ata		
NOTICE OF INTENTION TO:		JBSEQUENT REPO			
PERFORM REMEDIAL WORK PLUG AND ABAN					
			AND A		
CLOSED-LOOP SYSTEM IT					
		and give pertinent dates,	including estimated d		
OTHER: Squeeze perforations and drill out CIBP 13. Describe proposed or completed operations. (C of starting any proposed work). SEE RULE 19	Clearly state all pertinent details,				
OTHER: Squeeze perforations and drill out CIBP 13. Describe proposed or completed operations. (C	Clearly state all pertinent details,				
OTHER:         Squeeze perforations and drill out CIBP           13.         Describe proposed or completed operations. (Constanting any proposed work). SEE RULE 19 proposed completion or recompletion.	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple (	Completions: Attach wel	lbore diagram of		
OTHER:         Squeeze perforations and drill out CIBP           13.         Describe proposed or completed operations. (Constrainting any proposed work). SEE RULE 19 proposed completion or recompletion.           EOG Y Resources, Inc. plans to squeeze Yeso performance	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple (	Completions: Attach wel	lbore diagram of		
OTHER: Squeeze perforations and drill out CIBP 13. Describe proposed or completed operations. (C of starting any proposed work). SEE RULE 19 proposed completion or recompletion.	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple (	Completions: Attach wel	lbore diagram of		
OTHER:         Squeeze perforations and drill out CIBP           13.         Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.           EOG Y Resources, Inc. plans to squeeze Yeso performance           follows:	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple (	Completions: Attach wel	lbore diagram of		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constrainting any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforability.</li> <li>1. MIRU any safety equipment as needed.</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple (	Completions: Attach wel	lbore diagram of		
OTHER:         Squeeze perforations and drill out CIBP           13.         Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.           EOG Y Resources, Inc. plans to squeeze Yeso performance           follows:	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod	Completions: Attach wel uce well from original Ca	lbore diagram of anyon perforations as		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso performance follows:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom performations 2206'-2226' with 4-8 sx Class "C'</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6	Completions: Attach wel uce well from original Ca 50' establish circulation.	lbore diagram of anyon perforations as Squeeze Yeso		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple of prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds.	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C" not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple of prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds.	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C" not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and (	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over to bottom perfore the section.</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( orations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production.	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over to bottom perfore the section.</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( orations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production.	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passec <b>RECEIVED</b>		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over to bottom perfore the section.</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and (	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso performance follows:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom performations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production. $\mu_{us} = \mu_{P}\mu_{us}$ $\partial_{-}17-\partial_{0}19$	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and CIBP. Push to bottom and	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed <b>RECEIVED</b> JAN 1 1 2019		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constrainting any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( orations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production.	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and CIBP. Push to bottom and	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed <b>RECEIVED</b> JAN 1 1 2019		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constrainting any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production. $\mu_{us} = \mu_{P}\mu_{us}$ $\partial_{-}17-\partial_{0}19$	Completions: Attach wel uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and CIBP. Push to bottom and	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed <b>RECEIVED</b> JAN 1 1 2019		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "Const hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production. 0 production.	Completions: Attach well uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and CIBP. Push to bottom and	lbore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passec <b>RECEIVED</b>		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached</li> <li>pud Date:</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production. $M_{M} = M_{P}M_{M}$ Rig Release Date: perplete to the best of my knowle	Completions: Attach well uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and CIBP. Push to bottom and CIBP. Push to bottom and December 19-19-19 December 19-19 December 19-19 Dece	Ibore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed <b>RECEIVED</b> JAN 1 1 2019		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "C' not hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached</li> <li>pud Date:</li> </ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production. 0 production.	Completions: Attach well uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and CIBP. Push to bottom and CIBP. Push to bottom and December 19-19-19 December 19-19 December 19-19 Dece	Ibore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed <b>RECEIVED</b> JAN 1 1 2019		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "Cont hold pressure, will repeat until pressure hold.</li> <li>4. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached TA Stationary perforations attached TA Stationary (Construction)</li> <li>bereby certify that the information above is frue and construct the info</li></ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 222 ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production. W = 2 - 17 - 2019 Rig Release Date: pmplete to the best of my knowle 	Completions: Attach well uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and <b>DIERED</b> dge and belief.	Ibore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed JAN 1 1 2019 JAN 1 1 2019		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "Constrained perforations.</li> <li>3. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached TA S44</li> <li>pud Date:</li></ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( prations, drill out CIBP and prod (222 bbls). Set work string at 22: ' cement. WOC a minimum of 6 ds. and 46' of cement at 7584' and ( o production. $M_{M} = M_{P}M_{M}$ Rig Release Date: pomplete to the best of my knowle	Completions: Attach well uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and <b>DIERED</b> dge and belief.	Ibore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed JAN 1 1 2019 JAN 1 1 2019		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "Constrained perforations 2206'-2226' with 4-8 sx Class "Constrained perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached TA \$460</li> <li>pud Date:</li></ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( 0.15.7.14 NMAC. For Multiple (	Completions: Attach well uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and CIBP. Push to bot	Ibore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed <b>RECEIVED</b> JAN 1 1 2019 JAN 1 1 2019 JAN 1 1 2019 JAN 1 1 2019		
<ul> <li>OTHER: Squeeze perforations and drill out CIBP</li> <li>13. Describe proposed or completed operations. (Constraining any proposed work). SEE RULE 19 proposed completion or recompletion.</li> <li>EOG Y Resources, Inc. plans to squeeze Yeso perforations:</li> <li>1. MIRU any safety equipment as needed.</li> <li>2. POOH with TEC and gauge.</li> <li>3. Fill casing with inhibited water to bottom perforations 2206'-2226' with 4-8 sx Class "Control hold pressure, will repeat until pressure hold.</li> <li>2. Rotate and mill through squeezed perforations Canyon perforations.</li> <li>5. Run production equipment and turn well over the Wellbore schematics attached TA State and control the perforation above is frue and control to the production of the perforation of the perforation of the perforation of the perforation of the perforations.</li> <li>5. Run production equipment and turn well over the the perforation of the perforations.</li> <li>6. Run production equipment and turn well over the performance of the performance of</li></ul>	Clearly state all pertinent details, 0.15.7.14 NMAC. For Multiple ( 0.15.7.14 NMAC. For Multiple (	Completions: Attach well uce well from original Ca 50' establish circulation. hrs. Pressure test to 500 CIBP. Push to bottom and CIBP. Push to bot	Ibore diagram of anyon perforations as Squeeze Yeso psi for 30 min. If it do I verify all junk passed <b>RECEIVED</b> JAN 1 1 2019 JAN 1 1 2019 JAN 1 1 2019 JAN 1 1 2019		



٩,

ه د

	Foste	r AN	#2		Dro	pose	.d							
COMMENTS						pose	iu							
				ļ										
					Tub			- <u> </u> ,	_		·····			
					#	Joints		Length	OD	ID	Grade	Wt (lb/ft):	Top (ftKB):	Bottom
					1 2	2 <u>36.1</u> 1	Tubing TAC	7556	2.875	2.441	L-80	6.5	0	7556
					3	7	Tubing	224.00	2.875	2.441	L-80	6.5	7,556.00	7566 7790
				1	4	1	Seating nipple	2.00	2.0/0	<b>1</b> ,44	2-00		7,790.00	7792
					5	1	Slotted Sub	4.00	2.875	2.441	L-60	6.5	7,792.00	7796
				Ì	6	1	Tubing	90.00	2.875	2.441	L-80	6.5	7,796.00	7886
					7	1	Bull Plug	2.00	2.875	0	L-80	6.5	7,886.00	7888
		1												
										ļ				
										<b></b>				
	A	-		}	-									
	^				-		<u> </u>			I				
					Rod	s								
					#	r –	Item Desc	Length	OD	Grade	Тор	Btm	ſ	
					1	1	Polished rod	22.00	1 1/4	1	0.00	22.00		
					2	?	1" D rods pony	8.00	1	D	22,00	30.00		
					3	74	1" D rods	1850.00	1	D	30.00			
					4	95 121	7/8" D rods 3/4" D rods	2375.00	7/8		1880.00			
					6	20	1.5" Sinker bar	3015.00	3/4	1 8	4255.00 7270.00			
Squeeze Perforations Perforations 2206-22	26				7 SVR Dou	1 R, Brass	25-125-RHBC-20-5-4 Nicarb Barrel with Solid nding Valve with alternate I Shield				7770.00			
	26				7 SVR Dou Use	1 8, Brass ble Star a Sand	-Nicarb Barrel with Solid nding Valve with alternate I Shield	Plunger with	a .005 tota					
	26				7 SVR Dou Use	1 R, Brass ble Star	-Nicarb Barrel with Solid nding Valve with alternate I Shield ETAIL	Plunger with e pattern Silic	a .005 tota	balls, Sir				
	26				7 SVR Dou Use	1 8, Brass ble Star a Sand	-Nicarb Barrel with Solid nding Valve with alternate I Shield ETAIL WGHT	Plunger with e pattern Silic	a .005 toti on Nitride	balls, Sir	ngle Travel			
	26				7 SVR Dou Use CAS	1 8, Brass ble Star a Sand SING DE SIZE 9 5/8	-Nicarb Barrel with Solid nding Valve with alternate I Shield ETAIL WGHT	Plunger with e pattern Silic	a .005 toti on Nitride	balls, Sir	igle Travel			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT	Plunger with e pattern Silic	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 8, Brass ble Star a Sand SING DE SIZE 9 5/8	-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT Tops	Plunger with e pattern Silic GRADE	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate Shield ETAIL WGHT Tops San Anders	Plunger with e pattern Silic GRADE	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate Shield ETAIL WGHT Tops San Anders Glorieta	Plunger with e pattern Silic GRADE 570 2182	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate Shield 	Plunger with e pattern Silic GRADE 570 2182 3394	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate ETAIL WGHT Tops San Anders Glorieta Bone springs Abo	Plunger with e pattern Silic GRADE 570 2182 3394 5183	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	E-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate ETAIL WGHT Tops San Anders Glorieta Bone springs Abo	Plunger with e pattern Silic GRADE 570 2182 3394 5183	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	E-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	E-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
erforations 2206-22	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	E-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
erforations 2206-22	26				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	E-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
2206-22 206-22 CMT 25 sx CLS H CIBP @ 7630					7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	E-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
2206-22 206-22 CMT 25 sx CLS H CIBP @ 7630'					7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	E-Nicarb Barrel with Solid ning Valve with alternate Shield ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
Perforations         2206-22           CMT 25 sx CLS H         2000000000000000000000000000000000000	/90				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
Perforations         2206-22           CMT 25 sx CLS H         2000000000000000000000000000000000000					7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
Perforations         2206-22           CMT 25 sx CLS H         2000000000000000000000000000000000000	/90				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
2206-22 206-27 2	/90				7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid inding Valve with alternate Shield	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			
erforations 2206-22 MT 25 sx CLS H SIBP @ 7630 Perforations 7680-77	/90	8,16			7 SVR Dou Use CAS	1 R, Brass ble Star a Sand SING DE SIZE 9 5/8 7	-Nicarb Barrel with Solid ding Valve with alternate ETAIL WGHT Tops San Anders Glorieta Bone springs Abo Wolfcamp	Plunger with e pattern Silic GRADE 570 2182 3394 5183 5526	a .005 toti on Nitride	balls, Sir	ngle Travel Bottom 1,086			