

(Joine 2015) Do aba	BUNDRY	UNITED STATE PARTMENT OF THE I JREAU OF LAND MANA NOTICES AND REPO s form for proposals to I. Use form 3160-3 (AF	NTERIOR GEMENT ORTS ON WE	RECEIVE OCD Artes JUN 25 LLS	ia 2019 <sup>5.</sup>	OMB NO	APPROVED D. 1004-0137 nuary 31, 2018 r Tribe Name
	SUBMIT IN 1	RIPLICATE - Other ins	tructions on p	age 2	7.	If Unit or CA/Agree	ement, Name and/or No.
1. Type of Well ☑ Oil Well □ Gas Well □ Other					8.	8. Well Name and No. WEST SHUGART 19 FED 2	
2. Name of Operator DEVON ENERGY PRODUCTION COME-Mail: Armon.Radfar@dvn.com					9.	9. API Well No. 30-015-30780-00-S1	
3a. Address 333 WEST SHERIDAN AVENUE OKLAHOMA, OK 73102			3b. Phone No. (include area code) Ph: 405-552-5014			10. Field and Pool or Exploratory Area SHUGART	
4. Location of Well <i>(Footage, Sec., T., R., M., or Survey Descri</i> Sec 19 T18S R31E NENW 510FNL 2310FWL			tion).			11. County or Parish, State EDDY COUNTY, NM	
12. CHE	ECK THE AF	PROPRIATE BOX(ES)	) TO INDICAT	E NATURE O	F NOTICE, RE	PORT, OR OTH	IER DATA
TYPE OF SUBM	UBMISSION TYPE OF ACTION						
Notice of Intent	:	Acidize	Deep		_	(Start/Resume)	□ Water Shut-Off
D Subsequent Repo	ort	<ul> <li>Alter Casing</li> <li>Casing Repair</li> </ul>	_ /	aulic Fracturing Construction	Reclamatio		Well Integrity Other
🗖 Final Abandonm	nent Notice	Change Plans	_	and Abandon	Temporaril		
	,	Convert to Injection			Water Disp	-	
15. Describe i toposed of	1. Completed Opt	the end of the end of the second of the seco	ent details, including	ng estimated startin	g date of any propo	sed work and approx	ximate duration thereof.
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. MIRU P&A unit 2. Pull rod pump a 3. Set CIBP @ 80 4. Spot 25 sx CI C 5. Spot 25 sx CI C 6. Spot 25 sx CI C 7. Spot 25 sx CI C 8. Perf at 880'. So 9. Perf @ 140'. So	deepen directiona ler which the wor n of the involved pleted. Final Ab site is ready for fi it. and 2-7/8" pr 025'. Tag. Cir C from 5750'- C from 4350'- C from 4350'- C from 1975'- queeze 25 sx	ally or recomplete horizontally k will be performed or provid operations. If the operation r bandonment Notices must be fi	, give subsurface to e the Bond No. on esults in a multiple lied only after all re ly from ~8,253'. x Cl H from 802 g @ 5734') (4324') e @ 2828') Yates @ 1919	cations and measu file with BLM/BIA completion or reco quirements, includ 25'-7825'. (Perfs 2/sa (+) ) (T/seift	red and true vertica Required subseq mpletion in a new ing reclamation, ha at @ 8088') SFF	al depths of all pertin uent reports must be interval, a Form 316 ave been completed a	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. MIRU P&A unit 2. Pull rod pump a 3. Set CIBP @ 80 4. Spot 25 sx CI C 5. Spot 25 sx CI C 6. Spot 25 sx CI C 7. Spot 25 sx CI C 8. Perf at 880'. Sc 9. Perf @ 140'. Si 10. Cut wellhead	deepen directiona er which the wor n of the involved pleted. Final Ab ite is ready for fi it. and 2-7/8" pr 025'. Tag. Cir C from 5750'- C from 4350'- C from 4350'- C from 1975'- queeze 25 sx Squeeze 35 sy l off 3' BGL. S	ally or recomplete horizontally 'k will be performed or provid operations. If the operation r nandonment Notices must be final inal inspection. 'roduction tubing assemb 'c 10# salt gel. Spot 25 s 5500'. (Top Bone Spring 4100'. (Top Delaware @ 2650'. WOC & tag. (Sho 1725'. WOC & tag. (Sho 1725'. WOC & tag. (Sho CI C from 880'-780'. Wo k CI C in/out to surface. Set dry hole marker.	, give subsurface lo e the Bond No. on esults in a multiple iled only after all re ky from ~8,253'. x CI H from 802 (@ 5734') (4324') e @ 2828') Yates @ 1919 DC & tag. (Show	cations and measu file with BLM/BIA completion or reco quirements, includ 25'-7825'. (Perfs 2/sa (+) ) (T/seift	red and true vertica . Required subseq mpletion in a new ing reclamation, ha at @ 8088') SEE CON	al depths of all pertin uent reports must be interval, a Form 316 ive been completed a ATTACHE VDITIONS (	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. MIRU P&A unit 2. Pull rod pump a 3. Set CIBP @ 80 4. Spot 25 sx CI C 5. Spot 25 sx CI C 6. Spot 25 sx CI C 7. Spot 25 sx CI C 8. Perf at 880'. So 9. Perf @ 140'. So	deepen directiona er which the wor n of the involved pleted. Final Ab site is ready for fi it. and 2-7/8" pr 025'. Tag. Cir C from 5750'- C from 5750'- C from 4350'- C from 2900'- C from 1975'- queeze 25 sx Squeeze 35 sy toff 3' BGL. S	ally or recomplete horizontally 'k will be performed or provid operations. If the operation r nandonment Notices must be final inal inspection. 'roduction tubing assemb 'c 10# salt gel. Spot 25 s 5500'. (Top Bone Spring 4100'. (Top Delaware @ 2650'. WOC & tag. (Sho 1725'. WOC & tag. (Sho 1725'. WOC & tag. (Sho CI C from 880'-780'. Wo k CI C in/out to surface. Set dry hole marker.	y give subsurface lo e the Bond No. on esults in a multiple iled only after all re v from ~8,253'. X CI H from 802 (@ 5734') 4324') e @ 2828') Yates @ 1919 DC & tag. (Shoo C & tag. (Shoo C & tag. (Shoo C & tag. (Shoo C & tag. (Shoo	by the BLM Well NCOM LP, sent A MCKINNEY	ed and true vertica Required subseq mpletion in a new ing reclamation, ha at @ 8088') SEE CON Unformation Sy to the Carlsbad on 05/28/2019 (1)	al depths of all pertin uent reports must be interval, a Form 316 ive been completed a ATTACHE VDITIONS ( CCC	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. MIRU P&A unit 2. Pull rod pump a 3. Set CIBP @ 80 4. Spot 25 sx CI C 5. Spot 25 sx CI C 6. Spot 25 sx CI C 7. Spot 25 sx CI C 8. Perf at 880'. Sc 9. Perf @ 140'. Si 10. Cut wellhead	deepen directiona er which the wor n of the involved pleted. Final Ab site is ready for fi it. and 2-7/8" pr 025'. Tag. Cir C from 5750'- C from 5750'- C from 4350'- C from 2900'- C from 1975'- cqueeze 25 sx Squeeze 35 sx I off 3' BGL. S	Ally or recomplete horizontally 'k will be performed or provid operations. If the operation r andonment Notices must be final inal inspection. 'oduction tubing assemb 'c 10# salt gel. Spot 25 s 5500'. (Top Bone Spring 4100'. (Top Delaware @ 2650'. WOC & tag. (Sho 1725'. WOC & tag. (S	y give subsurface lo e the Bond No. on esults in a multiple iled only after all re v from ~8,253'. X CI H from 802 (@ 5734') 4324') e @ 2828') Yates @ 1919 DC & tag. (Shoo C & tag. (Shoo C & tag. (Shoo C & tag. (Shoo C & tag. (Shoo	by the BLM Well Normal State	ed and true vertica Required subseq mpletion in a new ing reclamation, ha at @ 8088') SEE CON Unformation Sy to the Carlsbad on 05/28/2019 (1)	al depths of all pertin uent reports must be interval, a Form 316 ive been completed a ATTACHE VDITIONS ( CCC	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. MIRU P&A unit 2. Pull rod pump a 3. Set CIBP @ 80 4. Spot 25 sx CI C 5. Spot 25 sx CI C 6. Spot 25 sx CI C 7. Spot 25 sx CI C 8. Perf at 880'. So 9. Perf @ 140'. Si 10. Cut wellhead	deepen directiona er which the wor n of the involved pleted. Final Ab site is ready for fi it. and 2-7/8" pr 025'. Tag. Cir C from 5750'- C from 5750'- C from 4350'- C from 2900'- C from 1975'- cqueeze 25 sx Squeeze 35 sx I off 3' BGL. S	Ally or recomplete horizontally is will be performed or provid operations. If the operation r andonment Notices must be final inal inspection. Toduction tubing assemb is 10# salt gel. Spot 25 s 5500'. (Top Bone Spring 4100'. (Top Delaware @ 2650'. WOC & tag. (Sho 1725'. WOC & tag. (S	y give subsurface lo e the Bond No. on esults in a multiple iled only after all re v from ~8,253'. X CI H from 802 (@ 5734') 4324') e @ 2828') Yates @ 1919 DC & tag. (Shoo C & tag. (Shoo C & tag. (Shoo C & tag. (Shoo C & tag. (Shoo	by the BLM Well NCOM LP, sent A MCKINNEY	red and true vertica Required subseq mpletion in a new ing reclamation, ha at @ 8088') SEE CON	al depths of all pertin uent reports must be interval, a Form 316 ive been completed a ATTACHE VDITIONS ( CCC	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. MIRU P&A unit 2. Pull rod pump a 3. Set CIBP @ 80 4. Spot 25 sx CI C 5. Spot 25 sx CI C 6. Spot 25 sx CI C 7. Spot 25 sx CI C 8. Perf at 880'. So 9. Perf @ 140'. So 10. Cut wellhead 14. I hereby certify that Name (Printed/Typed,	deepen directiona er which the wor n of the involved pleted. Final Ab site is ready for fi it. and 2-7/8" pr 025'. Tag. Cir C from 5750'- C from 4350'- C from 2900'- C from 1975'- queeze 25 sx Squeeze 35 sy t off 3' BGL. S	Ally or recomplete horizontally is will be performed or provid operations. If the operation r andonment Notices must be final inal inspection. Toduction tubing assemb is 10# salt gel. Spot 25 s 5500'. (Top Bone Spring 4100'. (Top Delaware @ 2650'. WOC & tag. (Sho 1725'. WOC & tag. (S	, give subsurface lo e the Bond No. on esults in a multiple lied only after all re X CI H from 802 (@ 5734') (4324') (Pates @ 1919 (C & tag. (Shou (Sh	cations and measu file with BLM/BIA completion or reco quirements, includ 25'-7825'. (Perfs 25'-7825'. (Perfs 25'-7825'	red and true vertica Required subseq mpletion in a new ing reclamation, ha at @ 8088') SEE CON Unformation Sy to the Carlsbad on 05/28/2019 (11 EER	al depths of all pertin uent reports must be interval, a Form 316 ive been completed a ATTACHE VDITIONS ( CCC rstem 9DLM0492SE)	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. MIRU P&A unit 2. Pull rod pump a 3. Set CIBP @ 80 4. Spot 25 sx CI C 5. Spot 25 sx CI C 6. Spot 25 sx CI C 7. Spot 25 sx CI C 8. Perf at 880'. So 9. Perf @ 140'. Si 10. Cut wellhead	deepen directiona er which the wor n of the involved pleted. Final Ab site is ready for fi it. and 2-7/8" pr 025'. Tag. Cir C from 5750'- C from 4350'- C from 2900'- C from 1975'- queeze 25 sx Squeeze 35 sy t off 3' BGL. S	Ally or recomplete horizontally is will be performed or provid operations. If the operation re- andonment Notices must be fi- inal inspection. oduction tubing assemb is 10# salt gel. Spot 25 s 5500'. (Top Bone Spring 4100'. (Top Delaware @ 2650'. WOC & tag. (Sho 1725'. WOC & tag. (Sho 1725'. WOC & tag. (Sho 1725'. WOC & tag. (Sho 1725'. WOC & tag. (Top is CI C from 880'-780'. Wo is CI C in/out to surface. Set dry hole marker. <b>I (egg.)</b> (Complete the tag.) True and correct. Electronic Submission tag. For DEVON ENERGY (true and correct. Electronic Submission tag.) (true and correct. Block of the tag.) Submission)	, give subsurface lo e the Bond No. on esults in a multiple iled only after all re X CI H from 802 (@ 5734') (4324') (Pates @ 1919 (C & tag. (Shou (C & tag. (	cations and measu file with BLM/BIA completion or reco quirements, includ 25'-7825'. (Perfs 25'-7825'. (Perfs 25'-7825'	red and true vertica Required subseq mpletion in a new ing reclamation, ha at @ 8088') SEE CON Unformation Sy to the Carlsbad on 05/28/2019 (11 EER	al depths of all pertin uent reports must be interval, a Form 316 ive been completed a ATTACHE VDITIONS ( CCC rstem 9DLM0492SE)	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. MIRU P&A unit 2. Pull rod pump a 3. Set CIBP @ 80 4. Spot 25 sx CI C 5. Spot 25 sx CI C 6. Spot 25 sx CI C 7. Spot 25 sx CI C 8. Perf at 880'. So 9. Perf @ 140'. So 10. Cut wellhead 14. I hereby certify that Name (Printed/Typed, Signature	deepen directiona ler which the wor n of the involved ipleted. Final Abb site is ready for fi it. and 2-7/8" pr 025'. Tag. Cir C from 5750'- C from 4350'- C from 2900'- C from 1975'- iqueeze 25 sx Squeeze 35 sy doff 3' BGL. S <b>QCOUPT</b> t the foregoing is <b>Commi</b> d) ARMON F (Electronic S	ally or recomplete horizontally is will be performed or provid operations. If the operation re- andonment Notices must be fi- inal inspection. oduction tubing assemb- is 10# salt gel. Spot 25 s 5500'. (Top Bone Spring 4100'. (Top Delaware @ 2650'. WOC & tag. (Sho 1725'. WOC & tag. (Sho 1725'. WOC & tag. (Sho 1725'. WOC & tag. (Sho is Cl C from 880'-780'. Wo is Cl C in/out to surface. Set dry hole marker. <b>Lectronic Submission a</b> For DEVON ENERG itted to AFMSS for process RADFAR Submission) THIS SPACE F A Approval of this notice doen itable title to those rights in th	s not warrant or	cations and measu file with BLM/BLA completion or reco quirements, includ 25'-7825'. (Perfs 2/sa (+) 2') CT/SeJ4 2' (CT/SeJ4 2') CT/SeJ4 2' (CT/SeJ4 2	red and true vertica Required subseq mpletion in a new ing reclamation, ha at @ 8088') SEE CON LINFORMATION Sy to the Carlsbad on 05/28/2019 (11) ER DIP DFFICE USE	al depths of all pertin uent reports must be interval, a Form 316 ive been completed a ATTACHE VDITIONS ( CCC rstem 9DLM0492SE)	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has D FOR DF APPROVAL



Cevor - Internal



Devon - Internat

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat 'Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses.** Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least <sup>1</sup>/<sub>4</sub> inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.** 

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>**Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u></u> From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted</u>**