Form 3160-5

	UNITED STATES EPARTMENT OF THE D	S Carisbad F NTERIOR GEMENT OCD A	ield Office	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
SUNDRY	NOTICES AND REPO	RTS ON WELLS	Ttesia 5. Lease Ser	nai No.		
abandoned we	nis form for proposals to ell. Use form 3160-3 (AP	D) for such proposals.	6. If Indian,	Allottee or Tribe Name		
SUBMIT IN	SUBMIT IN TRIPLICATE - Other instructions on page 2  7. If Unit or CA/Agreement, Name and/or N					
Type of Well     ☐ Gas Well ☐ O	ther		8. Well Nam GLOCK	e and No. 17-16 W0DA FED COM 3H		
Name of Operator     MEWBOURNE OIL COMPAN	Contact: NY E-Mail: jlathan@m	JACKIE LATHAN ewbourne.com		9. API Well No. 30-015-43411-00-X1		
3a. Address P O BOX 5270 HOBBS, NM 88241	,	3b. Phone No. (include area code) Ph: 575-393-5905  10. Field and Pool or Exploratory Are RUSSELL WILDCAT-WOLFCAMP				
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description	)	11. County	or Parish, State		
Sec 18 T20S R29E NWNW 8	24FNL 582FWL		EDDY (	COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE, REPORT,	OR OTHER DATA		
TYPE OF SUBMISSION		TYPE	OF ACTION			
□ Notice of Intent	☐ Acidize	Deepen	☐ Production (Start/Re	sume)		
_	☐ Alter Casing	☐ Hydraulic Fracturing	g Reclamation	nation		
Subsequent Report	□ Casing Repair	■ New Construction	□ Recomplete	Other		
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temporarily Abando	Drilling Operations		
	☐ Convert to Injection	Plug Back	□ Water Disposal			
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for a 5/26/19 TD 17 1/2" hole @ 980'. Ran w/additives. Mixed @ 13.5#/g yd. Displaced w/143 bbls FW BOPE to 5000# & Annular to FIT test to 9.5 PPG EMW. Draw	ally or recomplete horizontally, it will be performed or provide d operations. If the operation restandonment Notices must be filefinal inspection.  967' of 13 3/8" 54.5# J55 w/1.76 yd. Tail w/200 sks w/1.76 yd. Tail w/200 sks 2500#. At 11:00 A.M. 05/2 lled out with 12 1/4" bit.	give subsurface locations and mea the Bond No. on file with BLM/B sults in a multiple completion or re ed only after all requirements, inclu- ST&C Csg. Cemented with Class C w/0.5% CaCl2. Miz 5/26/19. Circ 220 sks of cmt 17/19, tested csg to 1500# for	sured and true vertical depths of IA. Required subsequent report completion in a new interval, a uding reclamation, have been conference of the conference o	f all pertinent markers and zones. ts must be filed within 30 days Form 3160-4 must be filed once		
Bond on file: NM1693 nationv	vide & NMB000919	Accepted for record . NW	OCD	JUL 2 3 2019		
		Werehan	DIST	RICTII-ARTESIAO.C.D.		
14. I hereby certify that the foregoing is	Electronic Submission #4 For MEWBOUF	168733 verified by the BLM W RNE OIL COMPANY, sent to to ssing by PRISCILLA PEREZ	he Carlsbad	E)		
Name (Printed/Typed) JACKIE L	ATHAN	Title AUTH	ORIZED REPRESENTAT	TIVE		
Signature (Flectronic	Submission)	Date 06/12/	2010			

THIS SPACE FOR FEDERAL OR STATE OFFICE USE JUN 1 8 2019 Accepted for Record Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Jonathon Shepard Carlsbad Field Office Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# MAN WELDING SERVICES, INC.

Company MEWBOURNE Date 5.26.19
Lease Glock 17-16 WODA FED Com 3H County Eddy Co MM
Drilling Contractor Patterson 250 Plug & Drill Pipe Size 22 4/21F/XT-39
Accumulator Pressure: 3000 Manifold Pressure: 1500 Annular Pressure: 1100
Accumulator Function Test - OO&GO#2
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
  - 1. Open HCR Valve. (If applicable)
  - 2. Close annular.
  - 3. Close all pipe rams.
  - 4. Open one set of the pipe rams to simulate closing the blind ram.
  - 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
  - 6. Record remaining pressure 1425 psi. Test Fails if pressure is lower than required.
    - a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)
  - 7. If annular is closed, open it at this time and close HCR.

### To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
  - a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
  - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
  - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
  - 3. Record pressure drop / psi. Test fails if pressure drops below minimum.
- Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}

#### To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
  - 1. Open the HCR valve, {if applicable}
  - 2. Close annular
  - 3. With pumps only, time how long it takes to regain the required manifold pressure.
  - 4. Record elapsed time no Jsu Test fails if it takes over 2 minutes.
    - a. [950 psi for a 1500 psi system] b. [1200 psi for a 2000 & 3000 psi system)



## WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Lovington, NM • 575-398-4540

Pg. \_\_\_\_\_ of \_\_\_\_

c	ompany :	MEMPOURNE		Deta:	5.24	g · 19 Involce # BD92863
	esse: <u>G</u>	<del></del>	COM 3H			PA+terson = 250
•	Mug Size 8	128"CD2	_ Drill Pipe Size	47	B IF/X	T39 TOSTOT: Will KydER
	tequired (			installe	id BOP:	* Check Valve Must Be Open/Disabled To Tost Kill Line Valves *
	*Approprise	Cesing Valvo Must Be Open During BOP Test				CHARLE MIRE OF CHARLES IN 1921 KIII THE ASIARS
***************************************	t \	Pipe Rams #12	226 22 20 20 20 20 20 20 20 20 20 20 20 20 2	13 P. S.	* <b>©</b> 1	Stand Pipe Valve #24 Top Drive #22 #23 TTW Valve #17
#27	#11 #10 #11 #10		#1 #25 Super Ch	#8B Mud Gauge Valve 	•	Monusi IBOP Pump Valve Pump Valve #21
	TEST •	. ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	. REMARKS
		TRIKY TEXT	Inlin	250	572	Fass
	a =	96				
	2	20.21.22,23	10/10	250	5000	FAILED-WOOKED VALUE
	3	20,21,22,23	10/10	250	5000	FAILED-WORKED VALUE
	3	20,21,22,23	10/10	250 250	5000 5000 5000	1 7
	3 4 5	20,21,22,23	10/10	250 250 250 250	5000 5000 5000	1 7
	3 4 5	20,21,22,23 20,21,22,23 24 19	10/10	250 250 250 250	5000 5000 5000 5000 5000	Pass Pass
5"	2345		10/10	250 250 250 250 250	5000 5000 5000 5000 5000	PASS PASS PASS
<b>5</b> "	23 4 5 67 8		10/10 10/10 10/10 10/10	250 250 250 250 250 250	5000 5000 5000 5000 5000 5000	PASS PASS PASS
5 5	23 4 5 67 8 9		10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250	5000 5000 5000 5000 5000 5000 5000	PASS PASS PASS PASS TASS 4/2 IF
5"5"5"	7.		10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250	5000 5000 5000 5000 5000 5000 3500	PASS PASS PASS PASS TASS TASS 4/2 IF PASS (7") 4/2 IF - 2500/8
5 5 5	7° 8 9 10	16 12,10,1,2,6,88,29 12, <b>3</b> ,8 9 14 15,9,8	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250	The same	PASS PASS PASS PASS TASS TASS 4/2 IF  PASS 4/2 IF  PASS 4/2 IF  PASS 4/2 IF
5 5	7 8 9 10 11	16 12,10,1,2,6,88,29 12, 3,8 9 14 15,9,8	10/10 10/10 10/10 10/10 10/10 10/10	250 250	5000)	PASS PASS PASS TASS TASS TASS 4/2 IF PASS TASS 4/2 IF PASS TASS TASS TASS TASS TASS TASS TASS
55555 5555 5735 5735 5735	7 8 9 10 11 12	16 12,10,1,2,6,88,29 12, <b>3</b> ,8 9 14 15,9,8	10/10 10/10 10/10 10/10 10/10 10/10 10/10	250 250 250	500) 3500	PASS PASS PASS PASS TASS TASS 4/2 IF  PASS 4/2 IF  PASS 4/2 IF  PASS XT-39  TASS XT-39
5 5 5	7 8 9 10 11 12	12,0,1,2,6,86,29 12,0,1,2,6,86,29 14 15,9,8 12,9,7,18,22,27 15,9,7,18	10/10 10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250	5000 3500 5000	PASS PASS PASS PASS PASS TASS TASS 4/2 IF PASS 4/2 IF PASS 4/2 IF PASS XT 39 PASS XT 39 PASS XT-39 PASS XT-39
55555 5555 5735 5735 5735	7 8 9 10 11 12	16 12,10,1,2,6,86,29 12,0,8 9 14 15,9,8 12,9,7,18,22,27 15,9,7,18	iolip	250 250 250 250 250	5000 5000 5000	PASS PASS PASS PASS TASS TASS TASS TASS
55555 5555 5735 5735 5735	7 8 9 10 11 23 14 15	10 12,10,1,2,6,83,29 12,9,8,9 14 15,9,8 12,9,7,18,22,27 15,9,7,18 19	10/10 10/10 10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250	5000 3500 5000	PASS PASS PASS PASS PASS TASS TASS TASS
55555 5555 5735 5735 5735	789101231456	12,0,1,2,6,88,29 12,0,1,2,6,88,29 14,5,9,8 12,9,7,18,22,27 15,9,7,18 19 18	10/10	250 250 250 250 250 250	5000 5000 5000 5000 5000	Pass Pass Pass Pass Tass Tass Tass Tass
55555 5555 5735 5735 5735	7 8 9 10 11 23 14 15	10 12,10,1,2,6,83,29 12,9,8,9 14 15,9,8 12,9,7,18,22,27 15,9,7,18 19	10/10	250 250 250 250 250 250	5000 5000 5000	PASS PASS PASS PASS PASS TASS TASS TASS











