0.00	State of New	Mexico	Form C-103
Office District I	Energy, Minerals and l	Natural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	23,		WELL API NO.
District II	OIL CONSERVAT	ION DIVISION	30-015-20100
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE X
District IV	Santa Fe, NN	A 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	ES AND REPORTS ON WE	CLLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA			McDonald JB
DIFFERENT RESERVOIR. USE "APPLICA"			THE CAME OF THE CA
PROPOSALS.)			8. Well Number
1. Type of Well:			1
Oil Well Gas Well	Other P&A	RECEIVED	O OCRUDAL 1
2. Name of Operator			9. OGRID Number
Yates Petroleum Corporation		MAY 0 2 2005	025575
3. Address of Operator	r 9931A	ORD:ARTESIA	10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM	1 88210	A CONTRACTOR OF THE PROPERTY OF	Penasco Draw San Andres Yeso
4. Well Location	C (C 41 N	41 11 1 0	
Unit Letter A : 990	feet from the N	orth line and 9	90 feet from the <u>East</u> line
Section 32	Township 199	Panaa 26E	NMPM Eddy County
k	Township 18S 11. Elevation (Show whether		
		3395'GR	
Pit or Below-grade Tank Application (For p			d)
	-		Distance from nearest fresh water well
Distance from nearest surface water	Below-grade Tank Location	ULSectTwp	Rng;
feet from theline and	feet from theline		
	propriate Box to Indica		
NOTICE OF INT	FNTION TO:	a ka Tre fa van da SUB	SEQUENT REPORT OF:
			K ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ALTERING CASING
PERFORM REMEDIAL WORK			ALTERING CASING LILLING OPNS. PLUG AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON	REMEDIAL WOR	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE	COMMENCE DRI	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	REMEDIAL WOR	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE	COMMENCE DRI	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	COMMENCE DRICEMENT JOB OTHER:	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Led operations. (Clearly state	CASING TEST AI CEMENT JOB OTHER:	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT ND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Led operations. (Clearly state	CASING TEST AI CEMENT JOB OTHER:	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly states). SEE RULE 1103. For M	CASING TEST AI CEMENT JOB OTHER:	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT ND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly states). SEE RULE 1103. For M	CASING TEST AI CEMENT JOB OTHER:	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT ND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state a). SEE RULE 1103. For M BP at 2408'.	COMMENCE DRICASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT ND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state at 1 103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to s	REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At	ALTERING CASING LLING OPNS. PLUG AND X ABANDONMENT ND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state at 1 103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to s	REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At	ALTERING CASING PLUG AND ABANDONMENT ABANDONMENT d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state at 1 103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to s	REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At	ALTERING CASING PLUG AND ABANDONMENT ABANDONMENT d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state at 1 103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to s	COMMENCE DRICASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At 1261'. surface leaving 5-1/2" casin	ALTERING CASING PLUG AND ABANDONMENT ABANDONMENT d give pertinent dates, including estimated date tach wellbore diagram of proposed completion g full. Installed dry hole marker. WELL IS
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state at 1 103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to s	COMMENCE DRICASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At 1261'. surface leaving 5-1/2" casin	ALTERING CASING PLUG AND ABANDONMENT ABANDONMENT d give pertinent dates, including estimated date trach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly states). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 150'. Squeezed 20 sx cement to st. L REPORT.	COMMENCE DRICASING TEST AI CEMENT JOB OTHER: e all pertinent details, and fultiple Completions: At 1261'. Surface leaving 5-1/2" casing	ALTERING CASING CLLING OPNS. PLUG AND ABANDONMENT D d give pertinent dates, including estimated date tach wellbore diagram of proposed completion ag full. Installed dry hole marker. WELL IS
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA I hereby certify that the information above the set of the property of the	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly states). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to st. LREPORT.	CASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At surface leaving 5-1/2" casing	ALTERING CASING Comparison of proposed completion Comparison of proposed comparison of proposed comparison of proposed completion Comparison of proposed c
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA I hereby certify that the information above the set of the property of the	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly states). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 150'. Squeezed 20 sx cement to st. L REPORT. Sove is true and complete to beed according to NMOCD guidely.	COMMENCE DRICASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At surface leaving 5-1/2" casing the best of my knowledgines, a general permit	ALTERING CASING Comparison of proposed completion Comparison of proposed comp
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA I hereby certify that the information above the set of the property of the	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly states). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 150'. Squeezed 20 sx cement to st. L REPORT. Sove is true and complete to beed according to NMOCD guidely.	COMMENCE DRICASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At surface leaving 5-1/2" casing the best of my knowledgines, a general permit	ALTERING CASING Comparison of proposed completion Comparison of proposed comparison of proposed comparison of proposed completion Comparison of proposed c
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 - Began P&A procedures. Set CII 4/22/05 - Circulated 10# mud. 4/25/05 - Spotted 25 sx cement at 2408'-2 4/26/05 - Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA I hereby certify that the information at grade tank has been/will be constructed or cli	CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state at). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20' sx cement at 1 10' sx cement at 1 10	CASING TEST AI CEMENT JOB OTHER: e all pertinent details, and fultiple Completions: At surface leaving 5-1/2" casing the best of my knowledge lines, a general permit	ALTERING CASING CASING PLUG AND X ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 - Began P&A procedures. Set CII 4/22/05 - Circulated 10# mud. 4/25/05 - Spotted 25 sx cement at 2408'-2 4/26/05 - Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA I hereby certify that the information at grade tank has been/will be constructed or cle	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly states). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 150'. Squeezed 20 sx cement to st. L REPORT. Sove is true and complete to beed according to NMOCD guidely.	CASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At surface leaving 5-1/2" casing the best of my knowledge lines, a general permit	ALTERING CASING CASING PLUG AND X ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA I hereby certify that the information at grade tank has been/will be constructed or cli SIGNATURE: Type or print name Tina Huerta	CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state at). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20' sx cement at 1 10' sx cement at 1 10	CASING TEST AI CEMENT JOB OTHER: e all pertinent details, and fultiple Completions: At surface leaving 5-1/2" casing the best of my knowledge lines, a general permit	ALTERING CASING CASING PLUG AND X ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 - Began P&A procedures. Set CII 4/22/05 - Circulated 10# mud. 4/25/05 - Spotted 25 sx cement at 2408'-2 4/26/05 - Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA I hereby certify that the information at grade tank has been/will be constructed or cl. SIGNATURE: Type or print name Tina Huerta (This space for State use)	PLUG AND ABANDON: CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly states). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to st. REPORT. Sove is true and complete to seed according to NMOCD guidely TITLE: E-mail a	REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At 261'. Surface leaving 5-1/2" casing the best of my knowledge lines, a general permit Regulatory Compliance of the surface standards: tinah@ypcnm	ALTERING CASING Comparison
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 4/21/05 – Began P&A procedures. Set CII 4/22/05 – Circulated 10# mud. 4/25/05 – Spotted 25 sx cement at 2408'-2 4/26/05 – Tagged at 1009'. Perforated at 6 PLUGGED AND ABANDONED. FINA I hereby certify that the information at grade tank has been/will be constructed or cli SIGNATURE: Type or print name Tina Huerta	CHANGE PLANS MULTIPLE COMPLETION Ted operations. (Clearly state at). SEE RULE 1103. For M BP at 2408'. 158'. Spotted 25 sx cement at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20 sx cement to state at 1 10'. Squeezed 20' sx cement at 1 10' sx cement at 1 10	REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: e all pertinent details, an fultiple Completions: At 261'. Surface leaving 5-1/2" casing the best of my knowledge lines, a general permit Regulatory Compliance of the surface standards: tinah@ypcnm	ALTERING CASING CASING PLUG AND X ABANDONMENT

mailed to OCD 5-31-06

NEW MEXICO ENERGY, MINER NATURAL RESOURCES DEPA

GARY E. JOHNSON

Governor Betty Rivera Cabinet Secretary

> Location Grade ck. No 13 1/8 " csg fow.

> > Yates Petroleum Corporation 105 South 4th Street Artesia, New Mexico 88210

OK TO Release 6/6/06

e-submit

Lori Wrotenbery Director Oil Conservation Division

RECEIVED

Form C-103 Report of Plugging for your McOcard JB+1- Sec 327185 R261 - 36-075 20100 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Precise check each here it, the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

1. All pits have been fil	led and leveled
---------------------------	-----------------

2. Rat hole and cellar have been filled and leveled.

3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)

4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.

The dead men and tie downs have been cut and removed."

o. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more that one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Van Barton

Accepted for recorded Rep. II