Form 3160-5 (August 1999)

United States Department of the Interior Bureau Of Land Management

Sundry Notices And Reports on Wells

Do not use this form for proposals to drill or to re-enter an Abandoned well. Use form 3160-3 (APD) for such proposals.

Form Approved
OMB No. 1004-0135
Expires November 30, 2000

	Empired Froveniers 50, 2005			
	5. Lease Serial No.			
	NM14293			
	6. If Indian, Allottee or Tribe Name			
	7. If Unit or CA/Agreement, Name and/or No.			
	8. Well Name and No.			
76				

		526272					
SUBMIT IN TRIPLICATE - Other Instructions On reverse side 20 25 26 20 8. Well Name and No.							
1. Type of Well:	8						
Oil Well Gas Well Other			Slayton Federal #1				
2. Name of Operator				9. API Well No.			
Pecos River Operating	7	30-005-61101					
3. Address of Operator) <u>}</u>	0. Field and Pool,	or Exploratory Area				
400 W. Illinois, Ste 1070 Midland,	IA G	Pecos Slope Abo					
3b. Phone No. (Include trea code) 400 W. Illinois, Ste 1070 Midland, Texas 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 5. Phone No. (Include trea code) 620-8480 CS/4 660 FNL & 660 FWL, Sec 1, T8S, R26E, Unit N Chaves Co, NM Chaves Co, NM							
660' FNL & 660 FWL, Sec 1, T8S,	R26E, Unit N	1813	. 68/				
Chaves Co, NM							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
Type Of Submission	Type Of Action						
	☐ Acidize	☐ Deepen	☐ Produc	tion (Start/Resume)	□ Water Shut-Off		
☑ Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclar	nation	☐ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recom	plete	☐ Other ———		
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temp	orarily Abandon			
	☐ Convert to Injection	☐ Plug Back	☐ Water	Disposal			

13. Describe proposed or completed operations. (clearly state all pertinent details, starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Notify BLM 24 hrs before starting.

- 1. Load hole w/9.8# mud spot 100' plug @ 4810' (perf @ 4816 to 25) WOC tag.
- 2. Cut & pull 4 1/2 casing from 3500.
- 3. RIH spot 100' plug across stub 50' in 50' out WOC tag.
- 4. Spot 100' plug @ 2250 to 2150.
- 5. Spot 100' plug @ 1180 (8 5/8 shoe @ 1130) WOC tag.
- 6. Spot 60' plug from 60' to surface.
- 7. Cut off wellhead install dry hole marker.

14. I hereby certify that the foregoing in the and correct Name (Printed/Typed) William R. Huck	Title VP – Engr. & Operations	<u> </u>					
William K. Fluck	Title VF - Eligi. & Operations						
Signature / LUMBEL	Date 7/25/03						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	Title	Date					
Conditions of approval, if y, are attached. Approval of this notice does not warrant or							
Certify that the applicant holds legal or equitable title to those rights in the subject lease							
Whick would entitle the applicant to conduct operations thereon.	Office	ř.					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, Make it a crime for any person knowingly and willfully to make to any department or agency of the United State any flase, fictitous or fraudulent statements or representations as to any matter within its jurisdiction.