- 1. Dump 35' of cement on existing CIBP @ 11150'.
- 2. Spot 50 sx cement plug from 8891' to 9091". 9358'
- 3. Spot 25 sx cement plug from 3866' to 6966'.
- 4. Spot 25 sx cement plug from 3386' to 3486'. Tag.
- 5. Cut and pull 5 1/2" casing @ +/- 2500'.
- 6. Spot 25 sx cement plug from 2450' to 2550'. Tag.
- 7. Spot 25 sx cement plug from 335' to 435'. Tag.

I hereby certify that the information above is true and co	implete to the best of	my knowledge and belief. I fur	ther certify that any p	it or below-
grade tank has been/will be constructed or closed according to NM				
SIGNATURE Stan Way	TITLE	Regulatory Analyst	DATE <b>6</b>	/18/07
	E-mail addr	ess:		
Type or print name Stan Wagner		To	elephone No. 432-	-686-3689
•				

For State Use Only

Harken. APPROVED BY Conditions of Approval, if any:

TITLE Complane office

To any work done.

	State of New Me	XICO	Form C-103			
Office District I	Energy, Minerals and Natur		May 27, 2004			
1625 N French Dr , Hobbs, NM 87240		i	API NO.			
District II 1301 W. Grand Ave., Artesia, NM 88210  OIL CONSERVATION DIVISION 1220 G. et al. Co. F.			30-015-30493			
District III 1220 South St. Francis Dr.		iicis Di.	5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8'		STATE X FEE			
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. Stat	e Oil & Gas Lease No.			
SUNDRY NOTIC	ES AND REPORTS ON WEL	LS 7. Lea	se Name or Unit Agreement Name:			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		OR PLUG BACK TO A				
PROPOSALS.)	CATION FOR PERMIT (FORM C-10	SIW 2	5 State Com			
1. Type of Well:		8. Wel	l Number			
Oil Well 🗶 Gas Well 🗌	Other		11			
2. Name of Operator		9. OGF	AID Number			
EOG Resources Inc.			7377			
3. Address of Operator			10. Pool name or Wildcat			
P.O. Box 2267 Midland, Text	kas 79702	Sand 1	Ounes (Pennsylvanian, Upper)			
4. Well Location						
Unit Letter <u>E</u> :	1980 feet from the Nor	th line and 660	feet from the West line			
Section 25		Range <b>29E</b> NMPN				
	11. Elevation (Show whether I					
Pit or Below-grade Tank Application or Closure						
Pit type _Steel Depth to Groundwater	Distance from nearest fresh	water well Distance from	nearest surface water			
Pit Liner Thickness: mil	Below-Grade Tank: Volume_	bbls; Construction Materia	d			
NOTICE OF INTE	PLUG AND ABANDON 🗓	SUBSEQU REMEDIAL WORK	ENT REPORT OF:  ALTERING CASING			
NOTICE OF INTE	ENTION TO:	SUBSEQU	ENT REPORT OF:  ALTERING CASING   S. PLUG AND			
NOTICE OF INTE	ENTION TO: PLUG AND ABANDON X	SUBSEQU REMEDIAL WORK	ENT REPORT OF:  ALTERING CASING			
NOTICE OF INTERPERSON TEMPORARILY ABANDON	ENTION TO: PLUG AND ABANDON X CHANGE PLANS	SUBSEQU REMEDIAL WORK COMMENCE DRILLING OPN CASING TEST AND	ENT REPORT OF:  ALTERING CASING   S. PLUG AND			
NOTICE OF INTERPERSON REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed	ENTION TO: PLUG AND ABANDON X CHANGE PLANS MULTIPLE COMPLETION D d operations. (Clearly state all per	SUBSEQU REMEDIAL WORK COMMENCE DRILLING OPN CASING TEST AND CEMENT JOB OTHER: tinent details, and give pertinent	ENT REPORT OF:  ALTERING CASING  S. PLUG AND ABANDONMENT			
NOTICE OF INTERPERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THE STATE OF	ENTION TO: PLUG AND ABANDON X  CHANGE PLANS  MULTIPLE COMPLETION  di operations. (Clearly state all per SEE RULE 1103. For Multiple  from surface to 100'.  on P&A marker, Clean and the	SUBSEQU REMEDIAL WORK COMMENCE DRILLING OPN CASING TEST AND CEMENT JOB OTHER: tinent details, and give pertinent Completions: Attach wellbord	ENT REPORT OF:  ALTERING CASING  S. PLUG AND ABANDONMENT  The dates, including estimated date			
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  8. Spot 25 sx cement plug  9. Cut off wellhead, weld  Pump 9 ppg mud between	ENTION TO: PLUG AND ABANDON X  CHANGE PLANS  MULTIPLE COMPLETION  di operations. (Clearly state all per SEE RULE 1103. For Multiple  from surface to 100'.  on P&A marker, Clean and 1 all plugs.	SUBSEQU REMEDIAL WORK COMMENCE DRILLING OPN CASING TEST AND CEMENT JOB OTHER: tinent details, and give pertine Completions: Attach wellbord restore location.	ENT REPORT OF:  ALTERING CASING  B. PLUG AND ABANDONMENT  Int dates, including estimated date ediagram of proposed completion  ef. I further certify that any pit or below-			
NOTICE OF INTER PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  8. Spot 25 sx cement plug  9. Cut off wellhead, weld  Pump 9 ppg mud between	ENTION TO: PLUG AND ABANDON X  CHANGE PLANS  MULTIPLE COMPLETION  di operations. (Clearly state all per SEE RULE 1103. For Multiple  from surface to 100'.  on P&A marker, Clean and 1 all plugs.	SUBSEQU REMEDIAL WORK COMMENCE DRILLING OPN CASING TEST AND CEMENT JOB OTHER: tinent details, and give pertine Completions: Attach wellbord restore location.	ENT REPORT OF:  ALTERING CASING  B. PLUG AND ABANDONMENT  Int dates, including estimated date ediagram of proposed completion  ef. I further certify that any pit or below-			
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  8. Spot 25 sx cement plug  9. Cut off wellhead, weld  Pump 9 ppg mud between	ENTION TO: PLUG AND ABANDON X  CHANGE PLANS  MULTIPLE COMPLETION  di operations. (Clearly state all per SEE RULE 1103. For Multiple  from surface to 100'.  on P&A marker, Clean and 1 all plugs.	SUBSEQU REMEDIAL WORK  COMMENCE DRILLING OPN CASING TEST AND CEMENT JOB  OTHER: tinent details, and give pertinent Completions: Attach wellbord restore location.	ENT REPORT OF:  ALTERING CASING  B. PLUG AND ABANDONMENT  ABANDONMENT			
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  8. Spot 25 sx cement plug 9. Cut off wellhead, weld Pump 9 ppg mud between  I hereby certify that the information all grade tank has been/will a constructed or center.	ENTION TO: PLUG AND ABANDON X  CHANGE PLANS  MULTIPLE COMPLETION  di operations. (Clearly state all per SEE RULE 1103. For Multiple  from surface to 100'.  on P&A marker, Clean and a all plugs.  bove is true and complete to the closed according to NMOCD guidelines.	SUBSEQU REMEDIAL WORK  COMMENCE DRILLING OPN CASING TEST AND CEMENT JOB  OTHER: tinent details, and give pertinent Completions: Attach wellbord restore location.	ENT REPORT OF:  ALTERING CASING  B. PLUG AND ABANDONMENT  ABANDONMENT			

APPROVED BY\_\_\_\_\_\_ TITLE\_\_\_\_\_ DATE \_\_\_\_\_

For State Use Only

Conditions of Approval, if any:

Form C-103

## WELLBORE SCHEMATIC

