## M-CARLSBAD FIELD OF

Form 3160-5 (August 1999)

Type of Well

Name of Operator

Hobbs, NM

Oil Well Gas Well Other

3a. Address P.O. Box 1708

660' FSL & 760' FWL

Lynx Petroleum Consultants,

88241

Section 13, T-19S, R-31E

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

TERIOR	FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000
EMENT	5. Lease Serial No.
rs on wells	NMNM09003
ill or to re-enter an for such proposals.	6. If Indian, Allottee or Tribe Name
lions on reverse side	7. If Unit or CA/Agreement, Name and/or No.
	NM 71152
	8. Well Name and No.
nc.	Sweeney Federal No. 1
	9. API Well No. 30-015-10397
3b. Phone No. (include area code) 575-392-6950	10. Field and Pool, or Exploratory Area
	Lusk Delaware
FEB 19 2008	11. County or Parish, State
OCD-ARTESIA	Eddy, NM
NDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF ACTION	
Deepen Production (Start	(Resume) Water Shut-Off
Fracture Treat Reclamation	☐ Well Integrity
New Construction Recomplete	• Other
Plug and Abandon Temporarily Ab	andon
Plug Back	
at details, including estimated starting date of any proposed work and approximate duration thereof. give subsurface locations and measured and true vertical depths of all pertinent markers and zones. e the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days sults in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once illed only after all requirements, including reclamation, have been completed, and the operator has	
hate hole w/gelled	mud laden fluid. Spot
5') plug across	dediate shoe @ 4001'
2" csg. /2" stub (3100 -0330 csg.	ACCEPTED FOR RECORD
/8" stub (1850) -1750 3/8" shoe (20'-620'	(1) - FEB 2:0 2008
	Gerry Guye, Deputy Field Inspecto
t off and or and of	Can 100MOCD-Digtriet II A Drimer

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF N TYPE OF AC TYPE OF SUBMISSION Deepen ☐ Acidize ☐ Prod Notice of Intent ☐ Alter Casing Fracture Treat Casing Repair New Construction Subsequent Report Change Plans Plug and Abandon Tem Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and meas Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMI following completion of the involved operations. If the operation results in a multiple completion or re testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including the strength of the proposal strength of the strength of the proposal strength o MIRU. NU BOP. 1. Circulate hole w/ge 2. TIH to CIBP @ 4820'. 5 sx (75') plug on Pull up and spot 25 375') plug across 3. (4176'-3801'). 1/2" Cut and recover csq. 4. 1/2" stub 5. Spot 25 sx plus 5/8" csq. 5/8" stub Spot 60 sx Q1 Nacross 13 3/8" 8. at surface. Spot 60 sx pc Cut off anchors and Erect dry hole marker. 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Larry R. President Date January 7, THIS SPACE FOR FEDERAL OR STATE OFFICE USE Dat <del>2 200</del>8 Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Lynx Petroleum Consultants, Inc. NMNM09003; Sweeney Federal #1 660' FSL & 760' FWL Section 13, T. 19 S., R. 31 E. Eddy County, New Mexico

RE: Plugging and Abandonment, Conditions of Approval

TIH to 4,820', circulate hole w/gelled mud laden fluid. Spot a 60 sack balanced plug on top of the CIBP. This will cover the top of the Delaware and the intermediate casing shoe at 4,001' - 3,951'

Cut and recover 3,000' of 4.5" casing.

Spot a 130' balanced plug across the 4.5" stub at 3,000' (3,065'-2935'). WOC and tag no lower than 2,935'.

Spot a 120' balanced plug across the base of the salt (2,258') and the DV tool (2,261') from 2,308'-2,188'.

Cut and recover 1,800' of 8.625" casing.

Spot a 100' balanced plug across the 8.625" stub (50' in/out) from 1,850' - 1,750'. WOC and tag no lower than 1,750'.

Spot a 100' balanced plug across the top of salt (923') from 973' – 873".

Spot a 100' balanced plug across the 13.375" casing shoe (670') from 720' - 620'. WOC and tag no lower than 620'.

Spot a plug from 60' to surface.

Erect a dry hole marker. Cut off anchors and clean location.

If you have any questions, please contact Jim Amos at 505-234-5909.

J. Amos, 2/13/08