Submit I Copy To Appropriate District State of New Mexico	Form C-103	
Office Energy Minorals and Natural Pagauras		
District I 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
District II	30-015-23169	
1301 W. Grand Ave., Artesia, NW 86210	5. Indicate Type of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE S-	
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number	
PROPOSALS.)	8. Well Number	
1. Type of Well: Oil Well Gas Well Other		
2. Name of Operator	9. OGRID Number	
Yates Petroleum Corporation  3. Address of Operator	025575 \( \square \) 10. Pool name or Wildcat	
3. Address of Operator 105 South Fourth Street, Artesia, NM 88210	10. Pool name or Wildcat Eagle Creek San Andres	
	Lagie Creek San Andres	
4. Well Location		
Unit Letter L :1650 feet from the South line and	990 feet from the West line	
Section 13 Township 17S Range 25		
11. Elevation (Show whether DR, RKB, RT, G	R, etc.)	
3460' GR	A STATE OF THE PARTY OF THE PAR	
12. Check Appropriate Box to Indicate Nature of N	lotice, Report or Other Data	
	•	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIA	L WORK ALTERING CASING [	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMEN	CE DRILLING OPNS. □ P AND A [	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/O	CEMENT JOB	
DOWNHOLE COMMINGLE	<b>Notify OCD 24 hrs. prior</b>	
<del>-</del> '	TO CIDY WORK CORE	
OTHER: OTHER:	To any work done.	
13. Describe proposed or completed operations. (Clearly state all pertinent det	tails, and give pertinent dates, including estimated of	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multi	tails, and give pertinent dates, including estimated of	
13. Describe proposed or completed operations. (Clearly state all pertinent det	tails, and give pertinent dates, including estimated of	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multi proposed completion or recompletion.	tails, and give pertinent dates, including estimated of	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of rface. This will fill the entire well bore up from the	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular.</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular.</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular.</li> </ol> SEE ATTACHED CONDITIONS OF	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular.</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular.</li> </ol> SEE ATTACHED CONDITIONS OF	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of rface. This will fill the entire well bore up from the	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular.</li> </ol> SEE ATTACHED CONDITIONS OF	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular SEE ATTACHED CONDITIONS OF APPROVAL</li> </ol>	tails, and give pertinent dates, including estimated in the completions: Attach wellbore diagram of a reface. This will fill the entire well bore up from the collations.	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular SEE ATTACHED CONDITIONS OF APPROVAL</li> </ol>	tails, and give pertinent dates, including estimated of iple Completions: Attach wellbore diagram of a rface. This will fill the entire well bore up from the collations.	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regunsely.  SEE ATTACHED  CONDITIONS OF  APPROVAL  Spud Date:  Rig Release Date:	rface. This will fill the entire well bore up from the ulations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regunser.</li> </ol> SEE ATTACHED CONDITIONS OF APPROVAL Spud Date: Rig Release Date:	rface. This will fill the entire well bore up from the ulations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.</li> <li>MIRU WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug.</li> <li>Cut off wellhead and install dry hole marker. Clean up location as per regular SEE ATTACHED CONDITIONS OF APPROVAL</li> </ol>	rface. This will fill the entire well bore up from the ulations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regunstrated by the surface of the surface. WOC and tag plug.  SEE ATTACHED CONDITIONS OF APPROVAL  Spud Date:  Rig Release Date:	rface. This will fill the entire well bore up from the ulations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA  nowledge and belief.	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regunstrated by the surface of the surface. WOC and tag plug.  SEE ATTACHED CONDITIONS OF APPROVAL  Spud Date:  Rig Release Date:	rface. This will fill the entire well bore up from the ulations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA  nowledge and belief.	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multi proposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regular SEE ATTACHED CONDITIONS OF APPROVAL  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my kn SIGNATURE  TITLE Regulatory Com	rface. This will fill the entire well bore up from the allations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA  DOWNledge and belief.  Repliance Technician DATE May 12, 2011	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multi proposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regular SEE ATTACHED CONDITIONS OF APPROVAL  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my kn SIGNATURE  TITLE Regulatory Com  Type or print name Craig Aton E-mail address: caton@yate	rface. This will fill the entire well bore up from the ulations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA  Repliance Technician DATE May 12, 2011	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multi proposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regular SEE ATTACHED CONDITIONS OF APPROVAL  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my kn SIGNATURE  TITLE Regulatory Com	rface. This will fill the entire well bore up from the allations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA  Repliance Technician DATE May 12, 2011	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regular set.  SEE ATTACHED CONDITIONS OF APPROVAL  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my kn  SIGNATURE  TITLE Regulatory Com  Type or print name  Craig Aton  E-mail address: caton@yate  For State Use Only  APPROVED BY:  TITLE	rface. This will fill the entire well bore up from the alations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA  Lowledge and belief.  PHONE:575-748-4385	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regular set.  SEE ATTACHED CONDITIONS OF APPROVAL  Spud Date:  Rig Release Date:  TITLE Regulatory Com  Type or print name Craig Aton E-mail address: caton@yate  For State Use Only  APPROVED BY:  TITLE	rface. This will fill the entire well bore up from the alations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA  Lowledge and belief.  PHONE:575-748-4385	
13. Describe proposed or completed operations. (Clearly state all pertinent det of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiproposed completion or recompletion.  1. MIRU WSC. Rig up any safety equipment as necessary. 2. Set a CIBP at 1269'. Spot a 90 sx class "C" cement plug from 1269' to sur CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regular SEE ATTACHED CONDITIONS OF APPROVAL  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my kn SIGNATURE  TITLE Regulatory Com  Type or print name  Craig Aton  E-mail address: caton@yate  For State Use Only	rface. This will fill the entire well bore up from the alations.  RECEIVED  MAY 13 2011  NMOCD ARTESIA  Lowledge and belief.  PHONE: 575-748-4385	

		ection 13-17S-25E Eddy	OO., 14101	
GL: 3,460' ZERO: KB: SPUD DATE: 8/31/81 COMPLETION DATE: 9/28/81			CASING PROGRAM	
COMMENTS: API No.:		DATE. 9120/01		
J. J. T.	. 00 0 10 20 100		10-3/4" 40.5#	3,43
			7" 20#	1,224
7				
{ \ \ \ \			4-1/2" 9.5#	1,491
4-1/2" Hole		(/)	1	<u> </u>
(\ \				-
{/\/		1/		<u>Sefore</u>
			=	<u>iciole</u>
\.\		10-3/4° @ 343' w/170 sx (Circ)		
[ ]				
1/1				
9-7/8" Hole				
	( )			TOPS
		7" @ 1,224 w700 1"ed to surf w/335 sx	SA	748'
		Ted to suit widdo sx		
	A			
	$\langle \langle       \rangle \rangle$			
6-1/4" Hole	<b>ハ</b>			
•	A = A			
,				
	(           )			
	)\  \( \( \)			
	1/4	- SA Perfs: 1,319-1,433'		
	$\langle \cdot   \cdot   \cdot \rangle$			
	TD 4 500'			Not to Scale 4/8/11
	TD: 1,500'	4-1/2 @ 1,491 w/175 sx (Circ)		DC/Hill

