

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO.
30-015-01479

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2178

7. Lease Name or Unit Agreement Name

Red Lake Sand Unit

8. Well No.
19

9. Pool name or Wildcat
Red Lake Shores; Grayburg

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER Injection

RECEIVED

2. Name of Operator
Mack Energy Corporation

MAR - 9 2004

3. Address of Operator
P.O. Box 960, Artesia, NM 88211-0960

OCD-ARTESIA

4. Well Location

Unit Letter N : 330 Feet From The South Line and 2310 Feet From The West Line

Section 20 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3862' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug and abandon well as follows:

1. Notify OCD 24 hours prior to starting plugging operations.

2. Set 100' cement plug from 1792-1692', WOC and tag.

3. Circulate hole w/mud gel.

4. Perforate @ 575' squeeze 100' plug 50' above and below 8 5/8 casing. WOC and tag.

5. Perforate @ 200' squeeze 100' plug back to 100'.

6. Perforate @ 60' circulate cement to surface.

7. Install dry hole marker.

← WOC 24 Hrs - Tag & Top of c as necessary

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 3/8/2004

TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO.

(This space for State Use)

APPROVED BY Mike Brall TITLE Compliance Officer DATE 3/17/04

CONDITIONS OF APPROVAL, IF ANY: WOC 24 Hrs on surface plug

MACK ENERGY CORPORATION
RED LAKE SAND UNIT #19
Sec 20 T17S R28E 1650FSL 2310FEL

'8 5/8"-28#

1. Notify OCD 24 hrs. prior to any work done.
 2. Set 100' cmt plug 1792-1692' and tag.
 3. Circ hole with mud gel.
 4. Perf @ 575' squeeze 100' cmt plug 50' above & below 8 5/8" and tag.
 5. Perf @ 200' squeeze 100' cmt plug back to 100'
 6. Perf @ 60' circ cmt to surface
 7. Install Dry Hole Marker
- ← woc 24 Hrs - TAG & Top off as necessary

8 5/8"-28# Set @ 525' w/25sks

7" 20# @ 1742' C/w 50sks

OPEN HOLE 1742'-1882'