# Submit 3 Copies to Appropriate District Office

# State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs NM 88240	OIL CONSERVATION DIVISION		WELL API NO.	
	2040 South Pacheco		30-015-01480	
DISTRICT II 811 South First, Artesia, NM 88210	Santa Fe, New N	Mexico 87505	5. Indicate Type of Lease  STATE FEE  FEE	
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410		6. State Oil & Gas Lease No.		
		B-2178		
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).			7. Lease Name or Unit Agreement Name	
1. Type Of Well: OIL GAS WELL WELL	OTHER Injection	RECEIVED	Red Lake Sand Unit	
2. Name of Operator		MAR - 9 2004	8. Well No.	
Mack Energy Corporation	· · · · · · · · · · · · · · · · · · ·	OCD-ARTESIA	17	
3. Address of Operator  D.O. Doy 060, Astronia NIM 89211	0060	AICOIA	9. Pool name or Wildcat	
P.O. Box 960, Artesia, NM 88211-	-0960		Red Lake Shores;Grayburg	
	Feet From The Sou	th Line and 99	90 Feet From The West Line	
Section 20	Township 17S	Range 28E	NMPM Eddy County	
		nether DF, RKB, RT, GR, etc.) 3562' GR		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF IN			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB	
OTHER:		OTHER		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
Mack Energy Corporation proposes to plug and abandon well as follows:				
1. Notify OCD 24 hours prior to starting plugging operations.				
2. Set 100' cement plug from 1726-1626', WOC and tag.				
3. Circulate hole w/mud gel.				
4. Perforate @ 537' squeeze 100' plug 50' above and below 8 5/8 casing. WOC and tag				
5. Perforate @ 60' circulate cement to surface. WOC 24 hrs - Tag & Top off as necessary 6. Install dry hole marker.				
<b>,</b>				
I hereby certify that the information above is true	and complete to the best of my knowledge	ge and belief.		
SIGNATURE Jerry W.	Shenall	TITLE Producti	on Clerk 3/8/2004	
TYPE OR PRINT NAME	Jerry W	. Sherrell	TELEPHONE NO.	
(This space for State Use)				
APPROVED BY Mike BRAZE CONDITIONS OF APPROVAL, IF ANY: WOC	<u>'</u>	TITLE Compliance	Officer DATE 3/17/04	
CONDITIONS OF APPROVAL, IF ANY: WOC	24 ths on surf	ace Aleg		
		V ·		

### STATE

## MACK ENERGY CORPORATION **RED LAKE SAND UNIT #17** Sec 20 T17S R28E 330FSL 990FWL

'8 5/8"-28#

- 1. Notify OCD 24 hrs. prior to any work done.
- 2.Set 100' cmt plug 1726-1626' and tag.
- 3.Circ hole with mud gel.
- 4.Perf @ 537' squeeze 100' cmt plug 50' above & below 8 5/8" and tag.
- 5. Perf @ 60' circ cmt to surface

6. Install Dry Hole Marker

-woe 24hrs - Tag & Top off as necessary

8 5/8"-28# Set @ 487' w/50sks

7" -20# Set @ 1676' w/25sks

OPEN HOLE 1676-1863'