



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

Underground Injection Control Program

"Protecting Our Underground Sources of Drinking Water"

16-Mar-04

DEVON ENERGY PRODUCTION COMPANY, LP

20 N BROADWAY

STE 1500

OKLAHOMA CITY OK 73102-0000

NOTICE OF VIOLATION and SHUT-IN DIRECTIVE **Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

WEST RED LAKE UNIT No.017

30-015-00788-00-00

M-5-18S-27E

Active Injection - (All Types)

Test Date: 3/16/2004 2:22:24 PM

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 5/31/2004

Test Type: Bradenhead Test

FAIL TYPE: No Company Rep to Witn

FAIL CAUSE:

Comments on MIT: Well must be shut-in pending reschedule.

PATON FEDERAL No.002

30-015-00800-00-00

N-6-18S-27E

Active Injection - (All Types)

Test Date: 3/16/2004 2:19:46 PM

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 5/31/2004

Test Type: Bradenhead Test

FAIL TYPE: No Company Rep to Witn

FAIL CAUSE:

Comments on MIT: Well must be shut-in pending reschedule.

WEST RED LAKE UNIT No.013

30-015-00804-00-00

A-7-18S-27E

Active Injection - (All Types)

Test Date: 3/16/2004 2:17:53 PM

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 5/31/2004

Test Type: Bradenhead Test

FAIL TYPE: No Company Rep to Witn

FAIL CAUSE:

Comments on MIT: Well must be shut-in pending reschedule.

WEST RED LAKE UNIT No.007			30-015-00805-00-00 B-7-18S-27E
Active Injection - (All Types)			
Test Date:	3/16/2004 2:17:03 PM	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/31/2004
Test Type:	Bradenhead Test	FAIL TYPE: No Company Rep to Witn	FAIL CAUSE:
Comments on MIT: Well must be shut-in pending reschedule.			
WEST RED LAKE UNIT No.008			30-015-00806-00-00 G-7-18S-27E
Active Injection - (All Types)			
Test Date:	3/16/2004 2:16:10 PM	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/31/2004
Test Type:	Bradenhead Test	FAIL TYPE: No Company Rep to Witn	FAIL CAUSE:
Comments on MIT: Well must be shut-in pending reschedule.			
WEST RED LAKE UNIT No.025			30-015-00819-00-00 A-8-18S-27E
Active Injection - (All Types)			
Test Date:	3/16/2004 2:14:05 PM	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/31/2004
Test Type:	Bradenhead Test	FAIL TYPE: No Company Rep to Witn	FAIL CAUSE:
Comments on MIT: Well must be shut-in pending reschedule.			
WEST RED LAKE UNIT No.026			30-015-00821-00-00 I-8-18S-27E
Active Injection - (All Types)			
Test Date:	3/16/2004 2:03:51 PM	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/31/2004
Test Type:	Bradenhead Test	FAIL TYPE: No Company Rep to Witn	FAIL CAUSE:
Comments on MIT: Well must be shut-in pending reschedule.			
WEST RED LAKE UNIT No.019			30-015-00826-00-00 E-8-18S-27E
Active Injection - (All Types)			
Test Date:	3/16/2004 2:10:08 PM	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/31/2004
Test Type:	Bradenhead Test	FAIL TYPE: No Company Rep to Witn	FAIL CAUSE:
Comments on MIT: Well must be shut-in pending reschedule.			
WEST RED LAKE UNIT No.018			30-015-00828-00-00 D-8-18S-27E
Active Injection - (All Types)			
Test Date:	3/16/2004 2:11:09 PM	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/31/2004
Test Type:	Bradenhead Test	FAIL TYPE: No Company Rep to Witn	FAIL CAUSE:
Comments on MIT: Well must be shut-in pending reschedule.			
WEST RED LAKE UNIT No.015			30-015-10174-00-00 H-7-18S-27E
Active Injection - (All Types)			
Test Date:	3/16/2004 2:15:10 PM	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/31/2004
Test Type:	Bradenhead Test	FAIL TYPE: No Company Rep to Witn	FAIL CAUSE:
Comments on MIT: Well must be shut-in pending reschedule.			
WEST RED LAKE UNIT No.050			30-015-26428-00-00 C-8-18S-27E
Active Injection - (All Types)			
Test Date:	3/16/2004 2:12:05 PM	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/31/2004
Test Type:	Bradenhead Test	FAIL TYPE: No Company Rep to Witn	FAIL CAUSE:
Comments on MIT: Well must be shut-in pending reschedule.			

WEST RED LAKE UNIT No.035**Active Injection - (All Types)**

Test Date: 3/16/2004 1:57:49 PM
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Well must be shut-in pending reschedule.

Permitted Injection PSI:
Test Result: F
FAIL TYPE: No Company Rep to Witn

Actual PSI:
Repair Due: 5/31/2004
FAIL CAUSE:

30-015-27473-00-00
D-9-18S-27E

WEST RED LAKE UNIT No.036**Active Injection - (All Types)**

Test Date: 3/16/2004 2:04:50 PM
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Well must be shut-in pending reschedule.

Permitted Injection PSI:
Test Result: F
FAIL TYPE: No Company Rep to Witn

Actual PSI:
Repair Due: 5/31/2004
FAIL CAUSE:

30-015-27474-00-00
H-8-18S-27E

WEST RED LAKE UNIT No.044**Active Injection - (All Types)**

Test Date: 3/16/2004 2:21:36 PM
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Well must be shut-in pending reschedule.

Permitted Injection PSI:
Test Result: F
FAIL TYPE: No Company Rep to Witn

Actual PSI:
Repair Due: 5/31/2004
FAIL CAUSE:

30-015-28444-00-00
N-5-18S-27E

WEST RED LAKE UNIT No.047**Active Injection - (All Types)**

Test Date: 3/16/2004 2:07:59 PM
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Well must be shut-in pending reschedule.

Permitted Injection PSI:
Test Result: F
FAIL TYPE: No Company Rep to Witn

Actual PSI:
Repair Due: 5/31/2004
FAIL CAUSE:

30-015-28471-00-00
G-8-18S-27E

WEST RED LAKE UNIT No.057**Active Injection - (All Types)**

Test Date: 3/16/2004 2:18:52 PM
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Well must be shut-in pending reschedule.

Permitted Injection PSI:
Test Result: F
FAIL TYPE: No Company Rep to Witn

Actual PSI:
Repair Due: 5/31/2004
FAIL CAUSE:

30-015-28539-00-00
P-6-18S-27E

WEST RED LAKE UNIT No.043**Active Injection - (All Types)**

Test Date: 3/16/2004 2:23:16 PM
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Well must be shut-in pending reschedule.

Permitted Injection PSI:
Test Result: F
FAIL TYPE: No Company Rep to Witn

Actual PSI:
Repair Due: 5/31/2004
FAIL CAUSE:

30-015-28564-00-00
7-4-18S-27E

WEST RED LAKE UNIT No.061**Active Injection - (All Types)**

Test Date: 3/16/2004 2:02:30 PM
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Well must be shut-in pending reschedule.

Permitted Injection PSI:
Test Result: F
FAIL TYPE: No Company Rep to Witn

Actual PSI:
Repair Due: 5/31/2004
FAIL CAUSE:

30-015-28709-00-00
C-9-18S-27E

WEST RED LAKE UNIT No.063**Active Injection - (All Types)**

Test Date: 3/16/2004 2:05:58 PM
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Well must be shut-in pending reschedule.

Permitted Injection PSI:
Test Result: F
FAIL TYPE: No Company Rep to Witn

Actual PSI:
Repair Due: 5/31/2004
FAIL CAUSE:

30-015-28733-00-00
H-8-18S-27E

WEST RED LAKE UNIT No.062**30-015-28734-00-00**

D-9-18S-27E

Active Injection - (All Types)**Test Date:** 3/16/2004 1:59:35 PM**Permitted Injection PSI:****Actual PSI:****Test Reason:** Annual IMIT**Test Result:** F**Repair Due:** 5/31/2004**Test Type:** Bradenhead Test**FAIL TYPE:** No Company Rep to Witn**FAIL CAUSE:****Comments on MIT:** Well must be shut-in pending reschedule.**WEST RED LAKE UNIT No.060****30-015-28781-00-00**

N-5-18S-27E

Active Injection - (All Types)**Test Date:** 3/16/2004 2:20:37 PM**Permitted Injection PSI:****Actual PSI:****Test Reason:** Annual IMIT**Test Result:** F**Repair Due:** 5/31/2004**Test Type:** Bradenhead Test**FAIL TYPE:** No Company Rep to Witn**FAIL CAUSE:****Comments on MIT:** Well must be shut-in pending reschedule.**WEST RED LAKE UNIT No.071****30-015-28940-00-00**

B-8-18S-27E

Active Injection - (All Types)**Test Date:** 3/16/2004 2:13:11 PM**Permitted Injection PSI:****Actual PSI:****Test Reason:** Annual IMIT**Test Result:** F**Repair Due:** 5/31/2004**Test Type:** Bradenhead Test**FAIL TYPE:** No Company Rep to Witn**FAIL CAUSE:****Comments on MIT:** Well must be shut-in pending reschedule.**WEST RED LAKE UNIT No.072****30-015-28941-00-00**

F-8-18S-27E

Active Injection - (All Types)**Test Date:** 3/16/2004 2:09:02 PM**Permitted Injection PSI:****Actual PSI:****Test Reason:** Annual IMIT**Test Result:** F**Repair Due:** 5/31/2004**Test Type:** Bradenhead Test**FAIL TYPE:** No Company Rep to Witn**FAIL CAUSE:****Comments on MIT:** Well must be shut-in pending reschedule.**WEST RED LAKE UNIT No.074****30-015-28943-00-00**

G-8-18S-27E

Active Injection - (All Types)**Test Date:** 3/16/2004 2:07:01 PM**Permitted Injection PSI:****Actual PSI:****Test Reason:** Annual IMIT**Test Result:** F**Repair Due:** 5/31/2004**Test Type:** Bradenhead Test**FAIL TYPE:** No Company Rep to Witn**FAIL CAUSE:****Comments on MIT:** Well must be shut-in pending reschedule.

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,


Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.