## Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103	
Revised 1-1-89	1

District Office
DISTRICT I P.O. Box 1980, Hobbs, NI
DISTRICT II

DISTRICT I	OII CONSEDUATION	ON DIVICION	* <u>*</u>	<u> </u>	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240  OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.			
DISTRICT II P.O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexico 87504-2088		30=015-05044			
		5 Indicate Type of Lease	TATE XX FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410					
1000 RD B12206 Rd., A2260, 19M1 8/410			6. State Oil & Gas Lease	No.	
CUMPRY MOT	OFC AND DEPOSITS ON WE		B-2613		
SUNDAY NOT	CES AND REPORTS ON WE	LLS			
( DO NOT USE THIS FORM FOR PRO	RVOIR. USE "APPLICATION FOR PE	N OH PLUG BACK TO A	7. Lease Name or Unit Ag	greement Name	
	-101) FOR SUCH PROPOSALS.)	21 1170 1			
1. Type of Well:			-		
OIL WELL XX	OTHER		State BGK		
2. Name of Operator	- Onex		<del></del>		
Mack Enrgy Corporation	_		8. Well No.		
3. Address of Operator	.1		9. Pool name or Wildcat		
•	NW 00211 (EOE) 7/0 1	200	9. Poor name or windcat		
4. Well Location	<u>, NM 88211 (505) 748-1</u>	288	L		
	50 South	00	10	<b>.</b> .	
Unit Letter : 10	50 Feet From The South	Line and99	Feet From The	East Line	
2	- 17 G	01 =			
Section 2	Township 17-S R		NMPM Eddy	County	
<i>\(\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	10. Elevation (Show whether	Dr, KKB, KI, GK, elc.)			
	Appropriate Box to Indicate				
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPO	RT OF:	
				<u></u>	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTER	RING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GOPNS. L PLUG	AND ABANDONMENT XX	
PULL OR ALTER CASING CASING TEST AND CEMENT JOB				_	
OTHER:		OTHER:	Ŕ	mtID-3 [	
		<u> </u>			
12. Describe Proposed or Completed Operat	ions (Clearly state all pertinent details, a	ınd give pertinent dates, inclu	ding estimated date of starting	any proposed	
work) SEE RULE 1103.	_		4/	-26-9k	
1) Set 2-7/8" CIBP @ 36	00' Cap W35' cement			P+ A	
2) dat 2 // 6 6 2000 dhable to pail out of hole					
3) Spot 100' cement @ 2	2-7/8, cut @ 2050' W.O	.C. Tag cement @	1 <b>890'</b>		
4) Cut 2-7/8 @ 1000' Sp	oot 28 sacks cement plus plug @ 378' 7-5/8" si : @ 315'	ug	1. 15:		
5) Spot 28 sacks cement	: plug @ 378' 7-5/8" s!	hoe W.O.C. Tag c	ement @-315'		
Spot 25 sacks cement	: @ 315 <b>'</b>				
6) Load with cement fro			ADD 1	l 6 <b>1996</b>	
7) Job completed 3-22-9			AFN	1 0 1000	
<ol><li>Hole was loaded with</li></ol>	. mud				
			OIL CO	N. DIV.	
				- - T 2	
=			M <sub>a</sub> sti	· · · · · · · · · · · · · · · · · · ·	
I hereby certify that the information above is true	and complete to the best of my knowledge an	d belief.		. /	
SKONATURE 6 K Klack	П	ne Oest Secty		re 4-10-96	
TYDE OR DEDIT NAME		σ		Treatouri Mo	

CONDITIONS OF AFFROVAL, IF ANY: