

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED
OFFICE FOR MANDATE
OF OILS RETAINING
(Other instructions on re-
verse side)

NM Roswell District
Modified Form No.
NR60-3160-4

c/sf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ NIW SJS		5. LEASE DESIGNATION AND SERIAL NO. LC-029395-8	
2. NAME OF OPERATOR Socorro Petroleum Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 38, Loco Hills, NM 88255		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		8. FARM OR LEASE NAME Turner "A"	
14. PERMIT NO.		9. WELL NO. 11	
15. ELEVATIONS (Show whether of, station, etc.) 660' FSL & 660' FEL		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson	
16. ELEVATIONS (Show whether of, station, etc.) 3695 GL		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA 18-17S-31E	
17. COUNTY OR PARISH Eddy		18. STATE NM	

APR 26 1991

O. C. D.

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER Casing	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHUT OR ACIDIZE	☒	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHUTTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. REPAIRING PROVIDED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to bleed the injection tbg down. Release pkr. POH w/injection tbg. Clean out well bore. Treat if necessary to remove scale to increase injectivity. Place well back on injection. To accomplish this work it will be necessary to dig a pit to contain well effluent during workovers. All excess wtr will be trucked. Following this workover the working pit will be ~~covered~~ **filled-in**

SJS

APR 18 9 47 AM '91
CARETAKER
AREA

RECEIVED

I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Consultant

DATE 4/16/91

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE

DATE 4/23/91

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side