Drauen - Dra	•
A PRINCE CTATES SUBMIT IN TRIPLICATES	Form approved. Budget Bureau No. 42-R1424.
DEPARTMENT OF THE INTERIOR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
FEB 18 1983 GEOLOGICAL SURVEY	NM 0555569  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  ARTESIA OF 19 Use "APILICATION FOR PERMIT—" for such proposals.)	O. IF INDIAN, ALLOTTED OR IRISE NAME
AKIESM	7. UNIT AGREEMENT NAME
OIL GAS WELL OTHER Injection	Green Federal
NAME OF OPERATOR	8. FARM OR LEASE NAME
DeltaUS Corporation	Green Federal 9. WELL NO.
3. ADDRESS OF OPERATOR	7
3100-C North A Street Midland, TX 79701  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	Artesia QGSA
990' FNL and 1650' FEL Unit B	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	Sec. 31 T17S, R29E_
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
3635' GL	Eddy NM
Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:	JENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT  MULTIPLE COMPLETE  FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL CHANGE PLANS (Other) (Note: Report results	of multiple completion on Well
(Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work. If well is directionally drilled, give subsurface locations and measured and true vertice nent to this work.)*	including estimated date of starting any all depths for all markers and zones perti-
Intent to plug per NMOCD recommendation:	
1. Run CBL from 2350' to surface. 2. Set 30 sx plug from 2630'-2420' w/a retainer at 2420'. 3. Set a 50 sx plug in and out from 1610'-1510' w/perfs at 4. Set 50 sx plug in and out from 900'-500' w/perfs at 900 5. Set 75 sx plug at 380'. 6. Set 30 sx plug at surface. 7. Set a permanent marker at surface, clean and restore 16	O', retainer at 800'.
*Note: This report filed for record only. Well was plugg	ed 7/21/84.
18. I hereby certify that the foregoing is true and correct	1/20/05
18. I hereby certify that the foregoing is true and correct  SIGNED TITLE Sr. Engineer	DATE 1/30/85
	DATE 1/30/85

Subject to Like Approval