




Failed 5 year MIT-1995  
Repaired Lubing. Tested OK.

BR