NO. OF COPIES RECEIVED 4	Form C. 100
DISTRIBUTION	Form C-103 Supersedes Old
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE /	Effective 1-1-65
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	
OPERATOR /	State A Fee 5. State Oil & Gas Lease No.
Of DEng.	B 1266,
	, b 1200,
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL OTHER-	7. Unit Agreement Name
2. Name of Operator	7
Tenneco Oil Company	8. Farm or Lease Name
3. Address of Operator	G-J West Coop. Unit
Box 1031 Midland Toxog 70701	9. Well No.
Box 1031, Midland, Texas 79701	29
	10. Field and Pool, or Wildcat
UNIT LETTER I 660 FEET FROM THE east LINE AND 2130 FEET FROM	Grayburg-Jackson
THE SOUTH LINE, SECTION 21 TOWNSHIP 17-S RANGE 29-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	or Doto
NOTICE OF INTENTION TO:	REPORT OF:
30E3EQ5EN1	REPORT OF:
PERFORM REMEDIAL WORK	
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING
BULL OR ALTER CARINE	PLUG AND ABANDONMENT
CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Tay Trust alle	1: 0P
OTHER TOTAL ALAN	ural lay
	/
	, —————————————————————————————————————
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including e	stimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including emork) SEE RULE 1603. DDOODDIDE.	stimated date of starting any proposed
PROCEDURE:	stimated date of starting any proposed
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit.	stimated date of starting any proposed
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. \top \tag{\psi}	stimated date of starting any proposed
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. \tilde{\psi} Set retrievable bridge plug and wire line at 2584'.	•
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ₩ Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7	•
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ★ Set retrievable bridge plug and—wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW.	•
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ₩ Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night.	5,000# 20-40 sand and
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ** Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p	5,000# 20-40 sand and
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ₩ Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night.	5,000# 20-40 sand and
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ** Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump.	5,000# 20-40 sand and lug.
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ** Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump.	5,000# 20-40 sand and lug.
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ** Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. ** The steach of the fellowing intervals 2253,64,84,89,93,2309,21,	5,000# 20-40 sand and lug.
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ** Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump.	5,000# 20-40 sand and lug. 24,43,47,57,6/ EGEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. **A / hole at each g The fallowing intervals 2253,64,84,89,93,2309,21,	5,000# 20-40 sand and lug.
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ** Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. ** The steach of the fellowing intervals 2253,64,84,89,93,2309,21,	5,000# 20-40 sand and lug. 24,43,47,57,6/ EGEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ** Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. ** The steach of the fellowing intervals 2253,64,84,89,93,2309,21,	5,000# 20-40 sand and lug. 24,43,47,57,6/ EGEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. ** Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. ** The steach of the fellowing intervals 2253,64,84,89,93,2309,21,	5,000# 20-40 sand and lug. 24,43,47,57,6/ EGEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. **A / hole at each g The fallowing intervals 2253,64,84,89,93,2309,21,	5,000# 20-40 sand and lug. 24,43,47,57,6/ EGEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. **A / hole at each g The fallowing intervals 2253,64,84,89,93,2309,21,	5,000# 20-40 sand and lug. 24,43,47,57,6/ EGEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p. 6. Ran tbg. and rods and put on pump. ***X / Isla Aleach g The fellowing intensits 2253 64, 84, 89, 93, 2309, 21, 15, 90, 95, 2401, 06, 2522, 27 + 2562	5,000# 20-40 sand and lug. 24,43,47,57,6/ EGEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. **A / hole at each g The fallowing intervals 2253,64,84,89,93,2309,21,	5,000# 20-40 sand and lug. 24,43,47,57,6/ EGEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. *** Ask aleach of the fellowing intervals 2253 64, 84, 89, 93, 2309, 21, 15, 90, 95, 2401, 06, 2522, 27 + 2562* 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	5,000# 20-40 sand and lug. 24,43,47,57,6/ ECEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p. 6. Ran tbg. and rods and put on pump. ***X / Isla Aleach g The fellowing intensits 2253 64, 84, 89, 93, 2309, 21, 15, 90, 95, 2401, 06, 2522, 27 + 2562	5,000# 20-40 sand and lug. 24,43,47,57,6/ ECEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. *** Ask aleach of the fellowing intervals 2253 64, 84, 89, 93, 2309, 21, 15, 90, 95, 2401, 06, 2522, 27 + 2562* 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	5,000# 20-40 sand and lug. 24,43,47,57,6/ ECEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge performed to the following intimals 2253 64,84,89,93,2309,21,25,90,95,2401,06,2522,27 +2562 18. Thereby certify that the information above is true and complete to the best of my knowledge and belief. 18. Thereby certify that the information above is true and complete to the best of my knowledge and belief. 3. F. Carnes TITLE District Production Engineer	5,000# 20-40 sand and lug. 24,43,47,57,6/ ECEIVED
PROCEDURE: 1. Pulled rods and tubing. Moved off pulling unit. 2. Perforated at 2253' - 2562' w/20 3/8" jets. * Set retrievable bridge plug and wire line at 2584'. 3. Frac down csg. w/500 gals. acid and 50,000 gals. gelled water and 7 4 perforation sealers. Overflushed w/10 BW. 4. Shut-in over night. 5. Bled off pressure, ran tbg. w/retrievable head & recovered bridge p 6. Ran tbg. and rods and put on pump. *** Ask aleach of the fellowing intervals 2253 64, 84, 89, 93, 2309, 21, 15, 90, 95, 2401, 06, 2522, 27 + 2562* 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	5,000# 20-40 sand and lug. 24,43,47,57,6/ ECEIVED