Submit 3 Copies to Appropriate District Office

State of New Mexico Enc. 69, Minerals and Natural Resources Department

Form C-103

DISTRICT I P.O. Box 1980, Hobbs NM 88240

OIL CONSERVATION DIVISION

CISK
WELL API NO.

Revised 1-1-89

2040 South Pacheco	30-015-20126	
DISTRICT II Santa Fe, New Mexico 87505 811 South First, Artesia, NM 88210	5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	STATE FEE 6. State Oil & Gas Lease No.	
1000 NO DIMEOS NO, TELOS, NATO OTTO	B-255	
SUNDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name	
(FORM C-101) FOR SUCH PROPOSALS).		
1. Type Of Well: OIL GAS OTHER	G J West Coop Unit	
2. Name of Operator	8. Well No.	
MACK ENERGY CORPORATION	49	
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960 (505) 748-1288	9. Pool name or Wildcat Grbg Jackson SR Q Grbg SA	
4. Well Location (303) 748-1268	Glog Jackson SK Q Glog SA	
Unit Letter M: 660 Feet From The South Line and 6	60 Feet From The West Line	
Section 16 Township 17S Range 29E	NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3589 GL		
Check Appropriate Box to Indicate Nature of Notice, R	eport or Other Data	
	SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND CI	EMENT JOB	
OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.		
1. Set CIBP 100' above perfs at 2153' with 35' cement		
1. Set CIBP 100' above perts at 2153' with 35' cement		
2. Set 100' cement plug 738-538' tag. 2. Perforate 41/2" esq 2 865. Squeege		
2. Set 100' cement plug 738-538' tag. 2. Perforate 41/2" csg 2 865. Squeez 100' cement Plug inside + outside 41/2" csg. TAG 3. Perf 4 1/2" csg at 288' squeeze 100' cement plug in-out 4 1/2" csg and tag. 463'	Art British	
	OCO CEIVED	
4. Set 60' surface plug.	TRIESIA 35/	
5. Install dry hole marker.	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
	100 25 25 25 10 2 10 2 10 2 10 2 10 2 10	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	on Analyst	
SIGNATURE TITLE PRODUCTION	DATE	
TYPE OR PRINT NAME Crissa D. Carter	TELEPHONE NO. (505) 748-1288	
(This space for State Use)		
APPROVED BY Mile 5 William IIILE Field Rep. II	DATE 5/15/2000	