

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN 1 LOCATED
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SIGNERY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. LEASE DESIGNATION AND SERIAL NO.

LC-028784-C

2. IF INDIAN, ALLOTTEE OR TRIBE NAME

3. UNIT AGREEMENT NAME

4. FARM OR LEASE NAME

Keely "C" Federal

5. WELL NO.

47

6. FIELD AND POOL, OR WILDCAT

Gb/Jackson SR-Q-Gb-SA

7. SEC. T., R., N., OR B.L. AND
SURVEY OR AREA

Sec. 13, 17-S, 29-E

8. COUNTY OR PARISH

Eddy

9. STATE

NM

10.

11. TYPE OF NOTICE

RECEIVED

12. NAME OF COMPANY

Phillips Petroleum Company

APR 10 1992

13. ADDRESS OF OPERATOR

4001 Penhook Street, Odessa, Texas 79762 O. C. D.

14. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 15.)

Unit G, 1980' FNL, 1980' FEL

15. PERMIT NO.

30-015-200

16. ELEVATIONS (Show whether OF, BY, OR, etc.)

3644' RKB - 3624' GL

17.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

18. OF INTENTION TO:

19. TYPE OF NOTICE

20. EFFECTIVE DATE

21. CLOSURE DATE

22. REPAIR WELL

(Other)

23. PULL OR ALTER CASING

24. MULTIPLE COMPLETE

25. ABANDON

26. CHANGE PLANS

27. SUBSEQUENT REPORT OF:

28. WATER SHUT-OFF

29. FRACTURE TREATMENT

30. SHOOTING OR ACIDIZING

(Other) Set CIBP & TA wellbore

31. REPAIRING WELL

32. ALTERING CASING

33. ABANDONMENT

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

19. DESCRIPTION OF WORK OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed well, and in directionally drilled, give subsurface locations and measured and true vertical depths for all markers and casing ports.)

03-23-92: 1. Run scraper on 2-3/8 workstring, set at 2458'. POOH.
2. Set 4-1/2 CIBP on workstring. CIBP set at 2420'. Circulate hole
with 36 bbl total fluid. Press up on system and run chart test.
3. Hold press on chart for 15 min. Test ok. BLM rep. witness test.
4. Pull with workstring. Temp. drop from report. Request permit to
abandon wellbore for one year.

APPROVED FOR 12 MONTH PERIOD

DATE 3/22/93

Approval of Temporary
Abandonment Expires

3/22/97

NMOCD

20. I hereby certify that the foregoing is true and correct

SIGNED

M. Sanders

TITLE

Supv., Reg./Proration

(915) 368-1488

DATE

03-24-92

(This space for signature of State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Supv., Reg./Proration

DATE

4/1/92

*See Instructions on Reverse Side

RECEIVED

APR 11 1992

O. C. D.
FACIA DESIGN

