

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2080  
SANTA FE, NEW MEXICO

RECEIVED BY  
AUG 12 1985  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
E-6353-

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CELEBRATE PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1.  OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Harvey E. Yates Company

3. Address of Operator  
P. O. Box 1933, Roswell, New Mexico 88201

4. Location of Well  
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660' FEET FROM  
THE West LINE, SECTION 8 TOWNSHIP 17S RANGE 29E

7. Unit Agreement Name

8. Name of Lease Name  
Arco 8 State Com

9. Well No.  
1

10. Field and Pool, or Wildcat  
Cave Grayburg-San Andres

11. Elevation (Show whether DF, RT, GR, etc.)  
3639 GL

12. County  
Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/26/85 Set CIBP @ 2950'. Dump 35' cmt on top of CIBP. Pump 100' plug from 2600-2700'.

7/27/85 Pump 100' plug from 800-900'.

7/29/85 Pump 100' plug @ 416'. Pump 60' plug from 60' to surface. Install Dry Hole Marker. P & A complete 7/29/85.

Post FD-2  
8-23-85  
P+A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. M. Young TITLE Drilling Superintendent DATE 8/8/85

APPROVED BY Danell Moore TITLE Geologist DATE 10/1/86

CONDITIONS OF APPROVAL, IF ANY: