

+
cjs
bp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-03382
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-6570-23

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
 OIL WELL GAS WELL OTHER Water Inj. Well

Name of Operator
YATES PETROLEUM CORPORATION

Address of Operator
105 South 4th St., Artesia, NM 88210

Well Location
Unit Letter H : 1650 Feet From The North ~~Side~~ O. C. D. and 990 Feet From The East Line
Section 11 Township 18S Range 29E NMPM Eddy County

7. Lease Name or Unit Agreement Name
WLHU G4S Tract

8. Well No.
35-2

9. Pool name or Wildcat
Loco Hills Queen Grayburg

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REMOVE OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <u>Repair casing</u> <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Yates Petroleum Corporation proposes to repair casing and temporarily abandon as follows:

- Moving in and rig up pulling unit and POOH with tubing and packer.
- RIH w/bit and scraper and tubing and clean out to 2543'. POOH.
- Run cement bond log to determine top of cement.
- GIH w/CIBP and set at 2490'. Dump 35' of cement on top of plug.
- If top of cement is not above the top of the Queen at ~~2165'~~ will GIH with perforating gun and perforate 4 holes at ~~2165'~~. POOH with perforating gun and GIH w/cement retainer on 2-3/8" tubing and set retainer at 2115'. Squeeze Queen with 50 sacks Class "C" 2% CaCl2. 2192
- Pressure test 7" casing to 500 psi.
- If casing does not hold, RIH w/RBP and packer and locate holes. If holes are above the base of the Salt (965'), GIH w/perforating gun and perforate 4 holes at 965'. POOH.

CONTINUED - Page 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Rusty Klein TITLE Production Clerk DATE Feb. 19, 1993
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)
APPROVED BY [Signature] TITLE Paul Reg DATE 2/26/93
CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-03382
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-6570-23
7. Lease Name or Unit Agreement Name WLHU G4S Tract
8. Well No. 35-2
9. Pool name or Wildcat Loco Hills Queen Grayburg San

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
OIL WELL GAS WELL OTHER Water Inj. Well

Name of Operator
YATES PETROLEUM CORPORATION

Address of Operator
105 South 4th St., Artesia, NM 88210

Well Location
Unit Letter H : 1650 Feet From The North Line and 990 Feet From The East Line
Section 11 Township 18S Range 29E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

RECEIVED
FEB 19 1993
O. C. D.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Repair casing</u> <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONTINUED FROM PAGE 1:

7. GIH w/cement retainer on 2-3/8" tubing and cement cement retainer at 915'. Squeeze Base of Salt with 50 sacks Class C 2% CaCl2. Dump 35' of cement on top. POOH.

8. If possible, repair remaining holes in casing and pressure test casing to 500 psi.

If holes cannot be repaired, propose to plug and abandon the well as follows:

1. Cut and pull 7" casing at 460'.
2. GIH w/cement retainer on 2-3/8" tubing and set retainer at 410'. Squeeze top of Salt with 50 sacks Class "C" 2% CaCl2. Dump 35' of cement on retainer and POOH.
3. Pressure test 8-5/8" casing to 500 psi. If casing tests, RIH with perforate gun & perforate 4 holes at 250' Attempt to circulate. If casing does not test, RIH with packer and locate holes.
4. Attempt to establish circulation down casing. After circulation is established,

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Feb. 19, 1993

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

CONTINUED - PAGE 3:
APPROVED BY [Signature] TITLE [Signature] DATE 2/26/93

(This space for State Use)
APPROVED BY [Signature] TITLE [Signature] DATE 2/26/93
CONDITIONS OF APPROVAL, IF ANY:

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
100 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-03382

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
B-6570-23

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

WLHU G4S Tract

Type of Well:
OIL WELL GAS WELL OTHER Water Inj. Well

Name of Operator
YATES PETROLEUM CORPORATION

8. Well No.
35-2

Address of Operator
105 South 4th St., Artesia, NM 88210

9. Pool name or Wildcat
Loco Hills Queen Grayburg San

Well Location
Unit Letter H : 1650 Feet From The North Line and 990 Feet From The East Line

Section 11 Township 18S Range 29E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
DRILL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Repair casing</u> <input checked="" type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONTINUED FROM PAGE 2:

- pump 50-100 sacks Class "C" and leave 100' of cement in casing. WOC. If circulation is not established, pump 50 sacks Class "C" out of holes and leave 100' of cement in casing. WOC.
- RIH & tag plug at 150' or higher.
- Set cement abandonment marker with 15 sack plug (at least 50').

NOTE: Mud (min 25# gel per 1 barrel water) will be placed between all plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Feb. 19, 1993

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE Bill Rep DATE 2/26/93

CONDITIONS OF APPROVAL, IF ANY: