

|                        |    |
|------------------------|----|
| NO. OF COPIES RECEIVED | 4  |
| DISTRIBUTION           |    |
| SANTA FE               | 1  |
| FILE                   | 1- |
| U.S.G.S.               |    |
| LAND OFFICE            |    |
| OPERATOR               | 2  |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
S-8071

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER-

2. Name of Operator  
Sunray DX Oil Company

3. Address of Operator  
P. O. Box 1416 Roswell, New Mexico

4. Location of Well  
UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 19S RANGE 29E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3322 DF

7. Unit Agreement Name

8. Farm or Lease Name  
New Mexico State #9

9. Well No.  
1

10. Field and Pool, or Wildcat  
N. Burton - Penn. Gas.  
Bone Springs

12. County  
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

|  |  |   |   |
|--|--|---|---|
| NOTICE OF INTENTION TO:                        |  | SUBSEQUENT REPORT OF:                               |   |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>                       | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Load hole with mud.
2. Spot 100 foot plug from 10,850-950.
3. Spot 100 foot plug from 7325-7425.
4. Spot 100 foot plug from 5100-5200.
5. Spot 100 foot plug from 3400-3500.
6. Place plug in base of 9 5/8" csg. at 2950'.
7. Place surface plug w/marker. (include all pertinent data on marker)
8. Clean up location.

RECEIVED

DEC 2 1966  
D. C. F.  
ASTORIA, OREGON

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don Farris TITLE Production Engineer DATE November 30, 1966

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE DEC 2 1966

CONDITIONS OF APPROVAL, IF ANY: