Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSEE. Drawer DD Artesia, NM 88210

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993 5. Lease Designation and Serial No.

	OF LAND MANAGEMENT	NM-0556859-A
this form for proposals t	CES AND REPORTS ON WELLS to drill or to deepen or reentry to a different N FOR PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
SUE	BMIT IN TRIPLICATE	Nash Unit
Type of Well  Gas  Gas		8. Well Name and No.
Name of Operator		Nash Unit #13
Strata Production Company		30-015-27316
Address and Telephone No.	(505)50	2-1127 10. Field and Pool, or Exploratory Area
P.O. Box 1030, Roswell, No Location of Well (Footage, Sec., T., R., M., or Su	EM HCX160 GOLDE	Nash Draw Brushy Canyon
		11. County or Parish, State
Contion 12	& 1746' FWL -23S-29E	Eddy County, New Mexico
CHECK APPROPRIATE I	BOX(s) TO INDICATE NATURE OF NOTI	CE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE	OF ACTION
Notice of Intent	Abandonment	Change of Plans
Notice of Intell	Recompletion	New Construction Non-Routine Fracturing
XX Subsequent Report	XXI Plugging Back  Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
Final Adandonment Notice	XX Other <u>Set CIRP</u>	Dispose Water  (Note: Report results of multiple completion on Well  Completion or Recompletion Report and Log (orm.)
Development or Completed Operations (Clear)	ly state all pertinent details, and give pertinent dates, including estimate	ated date of starting any proposed work. If well is directionally drilled.
6/11/93: MIRU. Release	packer and TOH. TIH with retriev to RBP at 6879' and TOH. RU Comce 20' cement on top. TOH with b	ing head. Circulate with 2% putalog. TIH with CIBP and set
at 6970'. Pla		
	g and set at 6952'. TIH with pum e on test. Well placed on produc	p and rods. Space out and hang
	and sot at 6952' TIH with pum	p and rods. Space out and hang tion.
	and sot at 6952' TIH with pum	p and rods. Space out and hang tion.
	and sot at 6952' TIH with pum	p and rods. Space out and hang tion.
	g and set at 6952'. TIH with pum e on test. Well placed on produc	p and rods. Space out and hang tion.
	g and set at 6952'. TIH with pum e on test. Well placed on produc	and rods. Space out and hang stion.
	g and set at 6952'. TIH with pum e on test. Well placed on produc	and rods. Space out and hang stion.
	g and set at 6952'. TIH with pum e on test. Well placed on produc	and rods. Space out and hang stion.
6/12/93: TIH with tubin well on. Place	g and set at 6952'. TIH with pum e on test. Well placed on produc	and rods. Space out and hang stion.
6/12/93: TIH with tubin well on. Place  4. I hereby cerufy that the foregoing is true and con Signed And Andrews Signed Andrew	g and set at 6952'. TIH with pum e on test. Well placed on produc	and rods. Space out and hang stion.
4. I hereby cerufy that the foregoing is true and consigned	g and set at 6952'. TIH with pum e on test. Well placed on produc	and rods. Space out and hang stion.
4. I hereby cerufy that the foregoing is true and consigned	g and set at 6952'. TIH with pum e on test. Well placed on production.  Title Production Records	3  Manager  Date 12/7/94