

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
811 S. 1st Street
Artesia, NM 88210-2534

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Gas
☒ Well ☐ Well ☐ Other

2. Name of Operator

STRATA PRODUCTION COMPANY

3. Address and Telephone No.

P. O. Box 1030
Roswell, New Mexico 88202-1030 505-822-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1230' FNL & 1350' FWL
Section 18-23S-30E

5. Lease Designation and Serial No.

NM-0556857

6. If Indian, Allottee or Tribe Name

If Unit or CA, Agreement Designation

Nash Unit

Well Name and No.

Nash Unit #20

9. API Well No.

30-015-27877

10. Field and Pool, or Exploratory Area

Nash Draw Brushy Canyon

11. County or Parish, State

Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ OTHER

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU. ND wellhead. TOH with rods and pump. NU BOP. TOH with tubing.
2. Perforate 4 .42 holes at 6254'-6257'.
3. Acidize with 1000 gallons acid. Swab test and evaluate.
4. Frac with 4600 gallons gel and 3000# 16/30 sand. Swab test and evaluate.
5. Perforate 8 .42 holes at 5497'-5509'.
6. Acidize with 1500 gallons acid. Swab test and evaluate.
7. Frac with 5800 gallons gel and 5000# 16/30 sand. Swab test and evaluate.
8. Perforate 9 .42 holes at 5319'-5331'.
9. Acidize with 1500 gallons acid. Swab test and evaluate.
10. Frac with 4400 gallons gel and 3000# 16/30 sand. Swab test and evaluate.
11. TOH with tools. TIH with production string. ND BOP. Flange up wellhead.
12. TIH with pump and rods. Hang on. Start pumping. Release rig. RDMO.
13. Place on production.

14. I hereby certify that the foregoing is true and correct

Signed Carol J. Garcia Title Production Records Manager Date 4/6/2001

(This space for Federal or State office use)

Approved by (ORIG. SGD.) DAVID R. GLASS Title PETROLEUM ENGINEER Date APR 13 2001

Conditions of approval, if any: