

Submit 3 Copies to Appropriate District Office

State of New Mexico  
Encl Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISF  
DP  
✓

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

Attn: Gary Williams  
FEB 24 1994

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-4956

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name SRC State
---

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
--

8. Well No. 1-Y
-----------------

2. Name of Operator Parker & Parsley Development Co.
---

9. Pool name or Wildcat Eddy Undesig. Wolfcamp Gas
---

3. Address of Operator P. O. Box 3178 Midland, Texas 79702
---

4. Well Location Unit Letter 0 : 660 Feet From The South Line and 1990 Feet From The East Line
---

Section 16 Township 26S Range 30E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) RKB - 3085 GR-3056

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>
OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF:
REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Start (3-14-94)

- Set cmt ret @ 11,055', squeeze Wlf pfs 11,105-12,158 w/375 sx & dump 35' cmt T/rtnr. Spot SW mud back to 10,700;
- Spot 25 sx from 10,721 back to 10,621 (T/Wolfcamp).
- Determine F.P. on 7 5/8" csg. If above 7328', spot 25 sk plugs @ 9710 & 7378' (2).
- Cut & pull 7 5/8" csg. Spot & tag 50 sk stub plug.
- Spot 75 sx for 9 5/8" shoe @ 4070' and tag. If 7 5/8" pulled here, combine req'd plugs.
- Spot cmt plug 3583 to 3150 to cover T/Delaware, 13 3/8" shoe & B/salt. (175 sx).
- Spot cmt plug across T/salt, from 938-838' ~~to tag~~. (50 sx).
- Spot cmt plug from 350' to surface for 20" csg shoe & surface plugs. (125 sx).
- Set D.H. marker, rip location surface & re-seed exposed area.

\* Mud Between AK Plugs *Plugging* (\*950 sx estimated)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bob Yeates TITLE Consultant DATE 2-21-94

TYPE OR PRINT NAME Bob Yeates Direct (915) 571-1237 TELEPHONE NO. 915 683-4768

(This space for State Use)

APPROVED BY [Signature] TITLE State Rep DATE 3/1/94

CONDITIONS OF APPROVAL, IF ANY: