

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-147
Revised April 3, 2017

Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment*
Type of action: ☐ Permit ☐ Registration
☐ Modification ☒ Extension
☐ Closure ☐ Other (explain) _____

* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: Enduring Resources, LLC (For multiple operators attach page with information) OGRID #: 372286
Address: 200 Energy Court, Farmington, NM 87401
Facility or well name (include API# if associated with a well): KWU 2309 19K Water Recycle Facility
OCD Permit Number: 3RF-43 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr NW/4 SW/4 Section 19 Township 23N Range 9W County: San Juan
Surface Owner: ☒ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☒ **Recycling Facility:**

Location of recycling facility (if applicable): Latitude 36.210825 Longitude -107.831105 NAD83

Proposed Use: ☒ Drilling* ☒ Completion* ☒ Production* ☒ Plugging *

**The re-use of produced water may NOT be used until fresh water zones are cased and cemented*

☐ Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.

☒ **Fluid Storage**

☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____

☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____

☐ For multiple or additional recycling containments, attach design and location information of each containment

☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.

☒ **Recycling Containment:**

☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)

Center of Recycling Containment (if applicable): Latitude 36.210825 Longitude -107.831105 NAD83

☐ For multiple or additional recycling containments, attach design and location information of each containment

☐ Lined ☒ Liner type: Thickness 45 mil ☒ LLDPE ☐ HDPE ☐ PVC ☐ Other _____

☒ **String-Reinforced**

Liner Seams: ☒ Welded ☒ Factory ☐ Other _____ Volume: 213.698 bbl Dimensions: L 500' x W 240' x D 25'

☐ Recycling Containment Closure Completion Date: _____

From: [Smith, Cory, EMNRD](#)
To: ["James McDaniel"; Enviro, OCD, EMNRD](#)
Cc: [Lacey Granillo](#)
Subject: RE: Enduring 3RF-43 Subsequent Determination of Cessation of Operation Variance Request
Date: Thursday, July 9, 2020 11:18:00 AM
Attachments: [image001.png](#)

Mr. McDaniel,

The Oil Conservation Division (OCD) has reviewed the determination of cessation of operations extension request for KWU 2309 19K Water Recycling Facility 3RF-43, received from Enduring Resources LLC OGRID 372286 on 6/12/2020. The cessation for operations extension and variance request is approved with the following conditions of approval.

- 3RF-43 was originally submitted on January 11, 2019 the permit is set to expire on January 11, 2024 at which time it must apply for renewal or close per 19.15.34.10.C NMAC
- Enduring Resources must recycle at least 170,959 BBL of produced water no later than January 1, 2021 to be considered in operations.
- Enduring Resources will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. Enduring Resources may maintain a higher liquid level if they choose. Please provide the minimum liquid level calculation and the minimum liquid level to be maintained to the OCD no later than August 10, 2020
- Enduring Resources will provide written notice to the OCD (email to ocd.enviro@state.nm.us) at least 72 hours, but no more than one week, prior to the recommencement of operations. Recommencement of recycling operations means that the operator plans to resume moving fluids through the containment and discharging fluids from the containment.
 - At the resumption of recycling operations, Enduring Resources is required to perform an incremental fluid level test for containment liquid levels above the minimum liquid level.
 - Enduring Resources will fill the containment. Enduring Resources will pause filling operations at every 10% of total fluid capacity above the minimum level.
 - Enduring Resources will maintain the liquid level for each 10% volume increase for 24 hours and inspect and operation the leak detection system at the end of the 24-hour period.
 - ❖ If there are no liquids present in the leak detection system, Enduring Resources may proceed to fill the next 10% volume and repeat the process until the containment full design capacity minus the 3-feet of freeboard is reached. eat the process until the containment full de reached.

- ❖ If liquids are present, Enduring Resources should immediately cease the incremental fill test and perform a liner inspection. Enduring Resources should provide written notice of the fluid detection and liner inspection findings to the OCD (email to ocd.enviro@state.nm.us) using a C-147 (long form) with the “Other” box checked and “Notice of fluid detection” written as the explanation of “Other.”
 - If the detected fluid is confirmed to be condensation, the OCD will issue a written approval to proceed with the incremental fluid level test.
 - If the detected fluid is confirmed to be produced water, Enduring Resources must comply with 19.15.34.13 NMAC. Enduring Resources must provide written notification (email to ocd.enviro@state.nm.us) on the actions taken to comply with 19.15.34.13 NMAC. If produced water is detected in the leak detection system, the incremental fill test cannot continue until after a written approval to proceed is issued by the OCD.
- ❖ Enduring Resources must submit copies of the detailed containment inspection records for the prior three (3) months and a report detailing the incremental fluid level test process and results to the OCD. Enviro mailbox using a C-147 (long form) with the “Other” box checked. “Recommendation of Operations - Incremental Fluid Level Test” should be written as the explanation of “Other.” Form C-147 must be completed and include information in sections 1 General Information, 2 Recycling Facility, 3 Recycling Containment, 4 Bonding, and 10 Operator Application Certification. Section 9 Recycling Facility and/or Containment Checklist may also need to be partially completed. Operators should verify that the resumption of operations notification does not result in any changes to the recycling containment operating and maintenance plan or the closure plan. If the recommendation of operations will affect the operating and maintenance plan or closure plan, operators should check those boxes in section 9 and provide updated plans or plan addendums as attachments to the C-147.
 - If there was no produced water detected in the leak detection system and there are **no** changes to the operating and maintenance plan or closure plan, Enduring Resources may proceed with the resumption of operations.
 - If there was produced water detected in the leak detection system or there were changes to the operating and maintenance plan or closure plan, Enduring Resources cannot proceed with the resumption of operations until OCD approves the C-147.
- Enduring Resources will continue to operate, maintain, and close the KWU 2309 19K Water Recycling Facility 3RF-43 in compliance with 19.15.34 NMAC, to include but not limited to: detailed inspection records, removal of trash/oil from containment, and

monthly C-148 reporting (even if there is zero activity).

- Water reuse and recycling from KWU 2309 19K Water Recycling Facility 3RF-43 is limited to wells owned or operated by Enduring Resources LLC 372286
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times during operations.
- Enduring Resources should notify the surface owner of the cessation of operations extension request by August 10, 2020
- Enduring Resources may request a variance for an additional extension to the determination of cessation of operations, which will be reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of six months. Additional requests must be submitted (email to ocd.enviro@state.nm.us) on a Form C-147 (long form) as an Extension request and should include a variance request and summary per 19.15.34.16 NMAC and the detailed inspection records for the prior three (3) months. The extension request should be submitted no later than December 1, 2020

Please keep a copy of this electronic communication for your files, as no paper copy of the approval will be delivered. The signed C-147 will be saved in 3RF-43 electronic file on the OCD website.

Cory Smith
Environmental Specialist
Oil Conservation Division
Energy, Minerals, & Natural Resources
1000 Rio Brazos, Aztec, NM 87410
(505)334-6178 ext 115
cory.smith@state.nm.us

From: James McDaniel <JMcDaniel@enduringresources.com>

Sent: Friday, June 12, 2020 11:24 AM

To: Enviro, OCD, EMNRD <OCD.Enviro@state.nm.us>; Smith, Cory, EMNRD
<Cory.Smith@state.nm.us>

Cc: Lacey Granillo <LGranillo@enduringresources.com>

Subject: [EXT] Enduring 3RF-43 Subsequent Determination of Cessation of Operation Variance Request

Attached is an Operations Variance Request for Recycling Containment 3RF-43, Kimbeto 2309 19K.
Thank you.

James McDaniel
HSE Supervisor
Enduring Resources

CSP #30009

CHMM #15676

CIT #13805

Office: 505-636-9731

Cell: 505-444-3004

jmcdaniel@enduringresources.com



4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 8' Tall Chain Link Fencing

6.

Signs:

- ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☒ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

- ☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.
- If a Variance is requested, it must be approved prior to implementation.**

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting

Ground water is less than 50 feet below the bottom of the Recycling Containment.

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

Recycling Facility and/or Containment Checklist:*Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.*

- ☐ Design Plan - based upon the appropriate requirements.
☐ Operating and Maintenance Plan - based upon the appropriate requirements.
☐ Closure Plan - based upon the appropriate requirements.
☐ Site Specific Groundwater Data -
☐ Siting Criteria Compliance Demonstrations -
☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): James McDaniel Title: HSE Supervisor
 Signature:  Date: 6/12/2020
 e-mail address: jmcDaniel@enduringresources.com Telephone: 505-636-9731

11.

OCD Representative Signature:  Approval Date: 7/9/2020
 Title: Environmental Specialist OCD Permit Number: 3RF-43

- ☐ OCD Conditions
☒ Additional OCD Conditions on Attachment

Sent via Email/Attached also

REQUEST FOR EXTENSION

Cory Smith
New Mexico Oil Conservation Division
Aztec Office
1000 Rio Brazos Rd.
Aztec, NM 87410

Re: Variance Request for Kimbeto 2309 19K – 3RF-43

Enduring Resources is requesting variance on the cessation of operation closure requirements in 19.15.31.13 NMAC based on the current climate surrounding the COVID-19 pandemic regarding the Kimbeto 2309 19K Recycling Facility, 3RF-43. The Pandemic has reduced our ability to organize work, receive products and equipment, and receive approvals for activities. Due to these difficulties, Enduring would like to request an extension on the cessation closure date requirements for the Kimbeto 2309 19K Facility. Based on the date of last use of water recycled for beneficial use from the facility of February 28, 2020, the cessation closure date of the site would be August 28, 2020. Enduring would like to request a six-month extension on the August 28, 2020 required closure date to February 28, 2021.

Sincerely,

A handwritten signature in black ink, appearing to read 'James McDaniel', with a stylized flourish at the end.

James McDaniel

HSE Supervisor

Enduring Resources, San Juan Operations

ATTACHMENTS:

Form C-147

Weekly Inspection Summary

Weekly Inspections (3 Months)

WEEKLY INSPECTION SUMMARY

3/2/2020

- WL @ 11' in Pond
- No measurable water in LD

3/9/2020

- WL @ 11' in Pond
- No measurable water in LD

3/17/2020

- WL @ 12' in Pond
- 0.1' of rainwater in LD. Not enough water to be removed.

3/23/2020

- WL @ 13' in Pond
- 0.1' of rainwater in LD. Not enough water to be removed

4/2/2020

- WL @ 14' in Pond
- Inspector took wrong water level meter, did not reach all the way to bottom. No water up to 96' in LD.

4/6/2020

- WL @ 14' in Pond
- 0.2' of rainwater in LD. Not enough water to be removed

4/13/2020

- WL @ 14' in Pond
- 0.3' of rainwater in LD. Not enough water to be removed

4/22/2020

- WL @ 14' in Pond
- 0.4' of rainwater in LD. Not enough water to be removed

4/30/2020

- WL @ 15' in Pond
- 0.15' of rainwater in LD. Not enough water to be removed

5/4/2020

- WL @ 15' in Pond
- 0.4' of rainwater in LD. Not enough water to be removed

5/11/2020

- WL @ 15' in Pond
- 0.4' of rainwater in LD. Not enough water to be removed

5/19/2020

- WL @ 15' in Pond
- 0.4' of rainwater in LD. Not enough water to be removed

5/28/2020

- WL @ 15' in Pond
- No water detected in LD

6/1/2020

- WL @ 15' in Pond
- 0.3' of rainwater in LD. Not enough water to be removed



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: 14W4 2309-191C Permit Number: 63-4301 7002

Qtr./Qtr. Or Lot: _____ Section: 19 Township: 23N Range: 9W

Date of Inspection: 3/2/20 Inspector: Sam BARAGT

Time arrived on location: 1130 Time left location: 1330

General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Fencing is in good condition and functional	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Gates are closed and locked ²	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Signage visible & compliant	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
No signs of surface water run on	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Containment has at least three feet of freeboard	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>LVL AT 11 FT</u>
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Liner above waterline shows no evidence of damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Leak detection system was checked and shows no sign of leak via fluid present	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
If fluid is present in leak detection system, it was removed and volume recorded	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	UPPER: Pond vertical depth (ft): <u>103.1 ft</u> Leak detection diagonal depth (ft): <u>103.1 ft</u> Pump run time (hours): <u>8</u> Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action			Personnel	Date
<u>LKL AT BOTTOM OF L.D. INFORMED JAMES</u>			<u>S. BARNETT</u>	<u>3/2/20</u>



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
All visual deterrents in good working order and operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Any repairs or replacements of deterrents from previous inspections have been completed ²	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.					
² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: KUSA 2309-19K Permit Number: SJ-4301 2002

Qtr./Qtr. Or Lot: NW/SE Section: 19 Township: 23N Range: 9W

Date of Inspection: 3/9/20 Inspector: SAM BARRETT

Time arrived on location: 1000 Time left location: 1130

General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	/			
Fencing is in good condition and functional	/			
Gates are closed and locked ²	/			
Signage visible & compliant	/			
No signs of surface water run on	/			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	/			
Containment has at least three feet of freeboard	/			LV2 AT 11ft
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	/			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	/			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Liner above waterline shows no evidence of damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Leak detection system was checked and shows no sign of leak via fluid present	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
If fluid is present in leak detection system, it was removed and volume recorded	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	UPPER: Pond vertical depth (ft): <u>103.1 ft</u> Leak detection diagonal depth (ft): <u>103.1 ft</u> Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel Date
LVL AT Bottom of L.D. INSPECTED JAMES				S. BARRETT 3/9/20



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating	/				
All visual deterrents in good working order and operating	/				
Any repairs or replacements of deterrents from previous inspections have been completed ²	/				
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	/				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	/				
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: KWU 2309-19K Permit Number: SS-4301 P002
Qtr./Qtr. Or Lot: NE/8W Section: 29 Township: 23N Range: 9W
Date of Inspection: 3/17/20 Inspector: Sam BARRETT
Time arrived on location: 1245 Time left location: 1400
General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	/			
Fencing is in good condition and functional	/			
Gates are closed and locked ²	/			
Signage visible & compliant	/			
No signs of surface water run on	/			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	/			
Containment has at least three feet of freeboard	/			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	/			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	/			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	/			
Liner above waterline shows no evidence of damage	/			
Leak detection system was checked and shows no sign of leak via fluid present	/			
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): <u>103.1 ft</u> Leak detection diagonal depth (ft): <u>103 ft</u> Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	/			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	/			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action			Personnel	Date
<u>Water Lvl AT Bottom of LD INFORMED James</u>			<u>S. BARRETT</u>	<u>3/12/20</u>



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
All visual deterrents in good working order and operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Any repairs or replacements of deterrents from previous inspections have been completed ²	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.					
² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



**ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET**

Recycling Containment: 1654 2309-19K Permit Number: SS-4301 P002
Qtr./Qtr. Or Lot: 26/SW Section: 19 Township: 23N Range: 9W
Date of Inspection: 3/23/20 Inspector: SAM BARRETT
Time arrived on location: 1000 Time left location: _____
General Comments: _____

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Fencing is in good condition and functional	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Gates are closed and locked ²	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Signage visible & compliant	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
No signs of surface water run on	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Containment has at least three feet of freeboard	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>LVL AT 13ft</u>
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



**ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET**

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Liner above waterline shows no evidence of damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Leak detection system was checked and shows no sign of leak via fluid present	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
If fluid is present in leak detection system, it was removed and volume recorded	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	UPPER: Pond vertical depth (ft): <u>103.1 ft</u> Leak detection diagonal depth (ft): <u>103 ft</u> Pump run time (hours): <u>0</u> Volume removed (gallons): <u>0</u> LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action			Personnel	Date
LVL AT BOTTOM OF L.D. INFORMED TAMES			S. BARNETT	3/23/20



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating					
All visual deterrents in good working order and operating					
Any repairs or replacements of deterrents from previous inspections have been completed ²					
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury					
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory					
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.					
² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: Kimbeta Wash 2309-19K Permit Number: 3RF-43
Qtr./Qtr. Or Lot: NE 1/4 SW 1/4 Section: 19 Township: 23N Range: 9E
Date of Inspection: 4-2-2020 Inspector: Chad Snel
Time arrived on location: 10:00 Time left location: 10:55
General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	✓			
Fencing is in good condition and functional	✓			
Gates are closed and locked ²		✓		NO Locks on 4 Gates
Signage visible & compliant	✓			
No signs of surface water run on	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action			Personnel	Date
Will get locks and put on			Chad	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	✓			
Containment has at least three feet of freeboard	✓			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	✓			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action			Personnel	Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	✓			
Liner above waterline shows no evidence of damage	✓			
Leak detection system was checked and shows no sign of leak via fluid present	✓			checked to 96' need longer meter
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): <u>14'</u> Leak detection diagonal depth (ft): <u> </u> Pump run time (hours): <u>N/A</u> Volume removed (gallons): <u>N/A</u> LOWER: Pond vertical depth (ft): <u>N/A</u> Leak detection diagonal depth (ft): <u>N/A</u> Pump run time (hours): <u>N/A</u> Volume removed (gallons): <u>N/A</u>
Fluid was not present within leak detection two consecutive days in a row	✓			Kicked on pump No water
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			✓	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating	✓				
All visual deterrents in good working order and operating	✓				
Any repairs or replacements of deterrents from previous inspections have been completed ²	✓				
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	✓				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory			✓		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.					
² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



**ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET**

Recycling Containment: KWU 2309-19K Permit Number: 3RF-43
Qtr./Qtr. Or Lot: NE1/4 SE1/4 Section: 19 Township: 23N Range: 9W
Date of Inspection: 4-6-20 Inspector: Chad Smith
Time arrived on location: 9:15 am Time left location: 10:15 am

General Comments:

No issues found, added 1 bird ball

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	✓			@ 14'
Fencing is in good condition and functional	✓			
Gates are closed and locked ²	✓			
Signage visible & compliant	✓			
No signs of surface water run on	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² only applicable if site is unattended by authorized personnel.				
Corrective Action				Personnel
				Date

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	✓			
Containment has at least three feet of freeboard	✓			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	✓			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel
				Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	✓			
Liner above waterline shows no evidence of damage	✓			
Leak detection system was checked and shows no sign of leak via fluid present	✓			Water Level meter off @ 103.9
If fluid is present in leak detection system, it was removed and volume recorded	✓			UPPER: Pond vertical depth (ft): 10.5 14' Leak detection diagonal depth (ft): 104.1 Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	✓			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			X	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



**ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET**

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating	✓				
All visual deterrents in good working order and operating	✓			added 1 bell	
Any repairs or replacements of deterrents from previous inspections have been completed ²	✓				
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	✓				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory			✓		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: KUU 2309 194 Permit Number: 3RF-43
Qtr./Qtr. Or Lot: NE/4, SW/4 Section: 19 Township: 23N Range: 9W
Date of Inspection: 4-13-20 Inspector: Chad Small
Time arrived on location: 1:05 pm Time left location: 1:50 pm
General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	✓			
Fencing is in good condition and functional	✓			
Gates are closed and locked ²	✓			
Signage visible & compliant	✓			
No signs of surface water run on	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	✓			
Containment has at least three feet of freeboard	✓			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	✓			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	✓			
Liner above waterline shows no evidence of damage	✓			
Leak detection system was checked and shows no sign of leak via fluid present	✓			@ 103.8
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): <u>25</u> Leak detection diagonal depth (ft): <u>104.1</u> Pump run time (hours): <u>—</u> Volume removed (gallons): <u>—</u> LOWER: Pond vertical depth (ft): <u> </u> Leak detection diagonal depth (ft): <u> </u> Pump run time (hours): <u> </u> Volume removed (gallons): <u> </u>
Fluid was not present within leak detection two consecutive days in a row	✓			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			✓	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating	✓				
All visual deterrents in good working order and operating	✓				
Any repairs or replacements of deterrents from previous inspections have been completed ²	✓				
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	✓				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory			✓		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: KW 2309 19K Permit Number: 32F-43
Qtr./Qtr. Or Lot: NE1/4 SW1/4 Section: 19 Township: 23N Range: 9W
Date of Inspection: 4-22-20 Inspector: Thad Snell
Time arrived on location: 12:45 pm Time left location: 2:00 pm
General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	✓			Q 14 ft
Fencing is in good condition and functional	✓			
Gates are closed and locked ²	✓			
Signage visible & compliant	✓			
No signs of surface water run on	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² only applicable if site is unattended by authorized personnel.				
Corrective Action				Personnel
				Date

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	✓			
Containment has at least three feet of freeboard	✓			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	✓			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel
				Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	✓			
Liner above waterline shows no evidence of damage	✓			
Leak detection system was checked and shows no sign of leak via fluid present	✓			@ 103.7
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): <u>25</u> Leak detection diagonal depth (ft): <u>104.1</u> Pump run time (hours): <u>—</u> Volume removed (gallons): <u>—</u> LOWER: Pond vertical depth (ft): <u>—</u> Leak detection diagonal depth (ft): <u>—</u> Pump run time (hours): <u>—</u> Volume removed (gallons): <u>—</u>
Fluid was not present within leak detection two consecutive days in a row	✓			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			✓	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating	✓			
All visual deterrents in good working order and operating	✓			added 3 Balls
Any repairs or replacements of deterrents from previous inspections have been completed ²	✓			
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	✓			
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory			✓	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action	Personnel			Date



**ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET**

Recycling Containment: KWU 2309 19K Permit Number: 3RF-43
Qtr./Qtr. Or Lot: NEA SW/4 section: 19 Township: 23N Range: 9W
Date of Inspection: 4/30/2020 Inspector: J. McDaniel
Time arrived on location: 1:10 PM Time left location: 2:04 PM

General Comments: Aerators working. Site in good condition

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	X			
Fencing is in good condition and functional	X			
Gates are closed and locked ²	X			
Signage visible & compliant	X			
No signs of surface water run on	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	X			
Containment has at least three feet of freeboard	X			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			X	No water in or out currently
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage	X			Pond level @ 15'
Leak detection system was checked and shows no sign of leak via fluid present	X			only 2" in LD
If fluid is present in leak detection system, it was removed and volume recorded				<p>UPPER: Pond vertical depth (ft): <u> </u> Leak detection diagonal depth (ft): <u> </u> Pump run time (hours): <u> </u> Volume removed (gallons): <u> </u></p> <p>LOWER: Pond vertical depth (ft): <u>101.05'</u> Leak detection diagonal depth (ft): <u>101.3'</u> Pump run time (hours): <u> </u> Volume removed (gallons): <u> </u></p> <p>Approx 2" in LD</p>
Fluid was not present within leak detection two consecutive days in a row			X	
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			X	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	
Too little to pump out				



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating	X				
All visual deterrents in good working order and operating	X			Added 2 Big Balls	
Any repairs or replacements of deterrents from previous inspections have been completed ²			X		
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory			X	None Found	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: KWU 2309 19h Permit Number: 3RF-43
Qtr./Qtr. Or Lot: NE/4 S-1/4 Section: 19 Township: 23N Range: 9W
Date of Inspection: 5-4-20 Inspector: Chad Swell
Time arrived on location: 9:15 am Time left location: 10:10 am
General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids	✓			15 SA
Fencing is in good condition and functional	✓			
Gates are closed and locked ²	✓			
Signage visible & compliant	✓			
No signs of surface water run on	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² only applicable if site is unattended by authorized personnel.				
Corrective Action				Personnel
				Date

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	✓			
Containment has at least three feet of freeboard	✓			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	✓			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel
				Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	✓			
Liner above waterline shows no evidence of damage	✓			
Leak detection system was checked and shows no sign of leak via fluid present	✓			@ 103.8
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): <u>25</u> Leak detection diagonal depth (ft): <u>101.2</u> Pump run time (hours): <u>—</u> Volume removed (gallons): <u>—</u> LOWER: Pond vertical depth (ft): <u>—</u> Leak detection diagonal depth (ft): <u>—</u> Pump run-time (hours): <u>—</u> Volume removed (gallons): <u>—</u>
Fluid was not present within leak detection two consecutive days in a row	✓			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			✓	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating	/				
All visual deterrents in good working order and operating	/				
Any repairs or replacements of deterrents from previous inspections have been completed ²	/				
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	/				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	/		/		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name KWD 2309-194 Permit Number 2RF-43
Section 19 Township 23N Range 9W County Seneca State NY
Time Inspection Began 1:15pm Time Inspection Ended 2:00pm
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<input type="text"/>			
Depth to Water in ULD (ft)	<input type="text"/>			
Height of Water in ULD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in LLD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<u>104.2</u>			
Depth to Water in LLD (ft)	<u>103.8</u>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Chad Smith

Date 5-11-20

Name (Signature) [Signature]

Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name KWU 2309-19K Permit Number 3RF-43
Section 19 Township 23N Range 9W County San Juan State NM
Time Inspection Began 12:00 PM Time Inspection Ended 1:15 PM
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header <u>none @ this time</u>	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<input type="text"/>			
Depth to Water in ULD (ft)	<input type="text"/>			
Height of Water in ULD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<u>104.2</u>			
Depth to Water in LLD (ft)	<u>103.8</u>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was Inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

added bird balls.
Audio not working due to capacitor being down. Personnel was contacted to fix issue.

Name (Print) Chad Small

Date 5-19-20

Name (Signature) [Signature]

Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name Kuu 2809 19K Permit Number 3RF-43
Section 19 Township 23N Range 9W County San Juan State NM
Time Inspection Began 10:10 am Time Inspection Ended _____
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15.4

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header <u>None @ this time</u>	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>104.1</u>			
Depth to Water in ULD (ft)	<u>104.1</u>			
Height of Water in ULD	<u>—</u>			
Gallons of Water Removed	<u>—</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>—</u>			
Depth to Water in LLD (ft)	<u>—</u>			
Height of Water in LLD	<u>—</u>			
Gallons of Water Removed	<u>—</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

ND on Leak detection

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

cell phone is down due to No fuel Gas

COMMENTS

Name (Print) Chad Snell

Date 5-28-20

Name (Signature) [Signature]

Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name KWW 2369-19K Permit Number 3RF-43
Section 19 Township 23N Range 9W County San Juan State NM
Time Inspection Began 1:10pm Time Inspection Ended 2:30
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header <u>None @ this time</u>	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>104.1</u>		
Depth to Water in ULD (ft)		<u>103.4</u>		
Height of Water in ULD		<u>3.4</u>		
Gallons of Water Removed		<u>—</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Not enough to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

CopStone should be on early this week to get Bird Audio working

COMMENTS

Name (Print) Chad Small

Date 6-1-20

Name (Signature) [Signature]

Company —