Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resour	rces May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u>	OIL CONSERVATION DIVISIO	30-045-31877
1301 W. Grand Ave., Artesia, NM 88210		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	, and the second	FEE
87505		
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEY OR PLUG BACK TO CATION FOR PERMIT" (FORM \$301) FOR SUCH 200	Allison Unit Com
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM (\$101) FOR SUCH 200	
		8. Well Number #144S
1. Type of Well: Oil Well	Gas Well Other	
2. Name of Operator		9. OGRID Number 14538
Burlington Resources Oil & Gas C	ompany LP	
3. Address of Operator	الروث المراجعة	10. Pool name or Wildcat
3401 E. 30 th Street, Farmington, N	M 87402	Basin Fruitland Coal
4. Well Location	عرض في الله الله الله الله الله الله الله الل	
Unit Letter D :	040 foot from the North line or	nd 020 fact from the West line
	940feet from theNorth line an	
Section 31	Township 32N Range 6W	NMPM San Juan County
	11. Elevation (Show whether DR, RKB, RT,	GR, etc.)
Pit or Below-grade Tank Application 🔲 o	r Closure 🔲	
Pit type Depth to Groundw	aterDistance from nearest fresh water well	Distance from nearest surface water
·· ——		
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction Material
12. Check A	Appropriate Box to Indicate Nature of N	Notice, Report or Other Data
		, .
NOTICE OF IN	ITENTION TO:	SUBSEQUENT REPORT OF:
NOTICE OF IN PERFORM REMEDIAL WORK □	ITENTION TO: PLUG AND ABANDON ☐ REMEDIA	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIA	AL WORK ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIA COMMEN	AL WORK ALTERING CASING ALTERING ALTER
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIA COMMEN	AL WORK ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING THER:	PLUG AND ABANDON	AL WORK ALTERING CASING ALTERING ALTERIN
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TO PULL OR ALTER CASING TO OTHER: 13. Describe proposed or compostarting any proposed we	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING THER:	PLUG AND ABANDON	AL WORK ALTERING CASING ALTERING ALTERIN
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TO PULL OR ALTER CASING TO OTHER: 13. Describe proposed or compostarting any proposed we	PLUG AND ABANDON	AL WORK ALTERING CASING ALTERING ALTERIN
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DULL OR STATE TO THE TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR AL	PLUG AND ABANDON	AL WORK ALTERING CASING ALTERING ALTERI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DULL OR Starting any proposed or compof starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 a	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O OTHER: eleted operations. (Clearly state all pertinent decork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. To	AL WORK ALTERING CASING ALTERING CASING ALTERING OPNS. PAND A CEMENT JOB Spud Notice Squared dates, including estimated date ions: Attach wellbore diagram of proposed completion COOH. TIH w/4 jts 9 5/8" 32.3# H-40 STC csg. set @
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THE TEMPORARILY ABANDON TEMPORARILY ABAND	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O OTHER: letted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. Tent w/20% fly ash (81cu ft). Cmt did not circ to	AL WORK ALTERING CASING ALTERI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THE TEMPORARILY ABANDON TEMPORARILY ABAND	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O OTHER: eleted operations. (Clearly state all pertinent decork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. To	AL WORK ALTERING CASING ALTERI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THE TEMPORARILY ABANDON TEMPORARILY ABAND	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O OTHER: letted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. Tent w/20% fly ash (81cu ft). Cmt did not circ to	AL WORK ALTERING CASING ALTERI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THE TEMPORARILY ABANDON TEMPORARILY ABAND	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O OTHER: letted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. Tent w/20% fly ash (81cu ft). Cmt did not circ to	AL WORK ALTERING CASING ALTERING CASING ALTERING OPNS. PAND A CEMENT JOB Spud Notice Stails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion OPOOH. TIH w/4 jts 9 5/8" 32.3# H-40 STC csg. set @ o surface. WOC. SDFN.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO THER: 13. Describe proposed or composed or starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°.	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O DIeted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. The cent w/20% fly ash (81cu ft). Cmt did not circ to Circ 15 sxs of Type I-II cmt to surface. WOC	AL WORK ALTERING CASING ALTERI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO THER: 13. Describe proposed or composed or starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°.	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O OTHER: letted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. Tent w/20% fly ash (81cu ft). Cmt did not circ to	AL WORK ALTERING CASING ALTERING CASING ALTERING OPNS. PAND A CEMENT JOB Spud Notice Stails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion of State of S
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO THER: 13. Describe proposed or composed or starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°.	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O DIeted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. The cent w/20% fly ash (81cu ft). Cmt did not circ to Circ 15 sxs of Type I-II cmt to surface. WOC	AL WORK ALTERING CASING ALTERI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO THER: 13. Describe proposed or composed or starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°.	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O DIeted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. The cent w/20% fly ash (81cu ft). Cmt did not circ to Circ 15 sxs of Type I-II cmt to surface. WOC	AL WORK ALTERING CASING ALTERING CASING ALTERING OPNS. PAND A CEMENT JOB Spud Notice Stails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion of State of S
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO THER: 13. Describe proposed or composed or starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°.	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O DIeted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. The cent w/20% fly ash (81cu ft). Cmt did not circ to Circ 15 sxs of Type I-II cmt to surface. WOC	AL WORK ALTERING CASING ALTERI
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO THER: 13. Describe proposed or composed or starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°.	PLUG AND ABANDON REMEDIA CHANGE PLANS COMMEN MULTIPLE COMPL CASING/O DIeted operations. (Clearly state all pertinent de ork). SEE RULE 1103. For Multiple Completi .m. on 8/2/04. Drill to 140'. Circ hole clean. The cent w/20% fly ash (81cu ft). Cmt did not circ to Circ 15 sxs of Type I-II cmt to surface. WOC	AL WORK ALTERING CASING ALTERING CASING ALTERING OPNS. PAND A CEMENT JOB Spud Notice Stails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion of STOOH. TIH w/4 jts 9 5/8" 32.3# H-40 STC csg. set @ o surface. WOC. SDFN.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO THER: 13. Describe proposed or compost of starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°. Casing pressure test will be conducted.	PLUG AND ABANDON	AL WORK ALTERING CASING DICE DRILLING OPNS. PAND A SEMENT JOB Spud Notice Stails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion of STOOH. TIH w/4 jts 9 5/8" 32.3# H-40 STC csg. set @ o surface. WOC. SDFN. C. Rig down, Rig released.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO STATE THE TEMPORARILY ABANDON TO THER: 13. Describe proposed or compost of starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°. Casing pressure test will be conducted the conducted t	PLUG AND ABANDON	AL WORK ALTERING CASING ALTERING CASING ALTERING DRILLING OPNS. PAND A CEMENT JOB Spud Notice Stails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion COOH. TIH w/4 jts 9 5/8" 32.3# H-40 STC csg. set @ o surface. WOC. SDFN. C. Rig down, Rig released. Il show on next report.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO STATE THE TEMPORARILY ABANDON TO THER: 13. Describe proposed or compost of starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°. Casing pressure test will be conducted the conducted t	PLUG AND ABANDON	AL WORK ALTERING CASING ALTERING CASING ALTERING OPNS. PAND A CEMENT JOB Spud Notice Stails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion of State of S
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DULL OR STATE OF THE CASING DULL OR ALTER CASING DUL	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING TO STATE THE TEMPORARILY ABANDON TO THER: 13. Describe proposed or compost of starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°. Casing pressure test will be conducted the conducted t	PLUG AND ABANDON	AL WORK ALTERING CASING ALTERING CASING ALTERING DRILLING OPNS. PAND A CEMENT JOB Spud Notice Stails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion COOH. TIH w/4 jts 9 5/8" 32.3# H-40 STC csg. set @ o surface. WOC. SDFN. C. Rig down, Rig released. Il show on next report.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°. Casing pressure test will be conducted in the conducted of the constructed or SIGNATURE	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°. Casing pressure test will be conducted to the constructed or SIGNATURE Type or print name on Glark	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°. Casing pressure test will be conducted in the conducted of the constructed or SIGNATURE	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR A	PLUG AND ABANDON	AL WORK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 8/2/04 MIRU. Spud well at 8:00 at 137°. Cmtd w/50 sxs Type I-II cem 8/3/04 Install PVC, tag cmt @ 38°. Casing pressure test will be conducted to the constructed or SIGNATURE Type or print name on Glark	PLUG AND ABANDON	AL WORK