

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Name and No. GCU 196
2. Name of Operator BP AMERICA PRODUCTION CO		9. API Well No. 30-045-11569-00-C1
3a. Address 200 ENERGY CT FARMINGTON, NM 87402		10. Field and Pool, or Exploratory BASIN FRUITLAND COAL
3b. Phone No. (include area code) Ph: 281.366.4491 Fx: 281.366.0700		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 19 T28N R12W SWSW 1110FSL 1090FWL 36.64327 N Lat, 108.15729 W Lon		11. County or Parish, and State SAN JUAN COUNTY, NM


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input checked="" type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Please reference BLM letter of 03/04/2004 & Sundry NOI of 04/13/2004.

BP request permission to abandon the Dakota formation in the subject well and return the well to production as a single Fruitland Coal producer per the attached procedure.



14. I hereby certify that the foregoing is true and correct. Electronic Submission #50091 verified by the BLM Well Information System For BP AMERICA PRODUCTION CO, sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 10/19/2004 (05SXM0032SE)	
Name (Printed/Typed) MARY CORLEY	Title AUTHORIZED REPRESENTATIVE
Signature (Electronic Submission)	Date 10/15/2004

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By STEPHEN MASON	Title PETROLEUM ENGINEER	Date 10/19/2004
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

NMOCD

GALLEGOS CANYON UNIT 196
Dakota Plugback Procedure

Plug and abandon Dakota horizon and complete as a Fruitland Coal well.

Procedure

1. Contact Federal and State agencies 48 hours prior to starting P&A work (NMOCD: Charlie Perrin, 505-334-6178 X16 & BLM: Steve Mason, 505-599-6364)
2. Check location for anchors. Install if necessary. Test anchors. Check wellhead ID; if earth pit is required have One Call made 48 hours prior to digging.
3. RU slickline unit or wireline unit. RIH and set **two** barriers (CIBP, tbg collar stop w/plug, or plug set in nipple) for isolation.
4. MIRU workover unit. Check and record tubing, casing, and bradenhead pressures.
5. Blow down and kill well with 2% KCl water only if necessary. Check all casing strings to ensure no pressure exist on any annulus.
6. ND wellhead, NU BOP and diversion spool with minimum of two 2 1/16" outlets and 3" blow line(s) to the blow tank. Pressure test BOPs to 200 psi above BHP. Monitor flowing casing pressure with gauge (with casing flowing to blow tank) throughout workover. The pressure must stay below 10 psi while tripping.
7. TOH w/ 2 3/8" tubing, using approved "Under Balance Well Control Tripping Procedure". Stop and kill the well when within 10 stands of being out of the hole.
8. TIH w/ bit & scraper to top of Dakota perforations and clean out if necessary.
9. RIH with CIBP and set at a top-set depth of 6000'.
10. Spot 19 sxs of cement on top of CIBP @ 6000' from 6000' to 5800' (includes 50' excess)
11. TIH w/ completion string (mule shoe, 1 jt. 2 3/8" 4.7# tubing, bell nipple, "F" profile nipple, and 2 3/8" 4.7# tubing) w/ plugs in profile. Land end of tubing @ 1555'.
12. ND BOP. NU wellhead. RDMO plugging unit.
13. RU wireline and pull profile plugs

Gallegos Canyon Unit 196

Dakota

API # 30-045-11569

G.L. 5875'
K.B. 5887'

