			5. Lease
UNITED STATES			NMMM-03381
DEPARTMENT OF THE INTERIOR			[NIVIXIVI-03361
BUREAU OF LAND MANAGEMENT			
\mathscr{J}			6. If Indian, Allottee or Tribe Name
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different			7. Unit Agreement Name
reservoir. Use "APPLICATION FOR PERMIT" for such proposals 2			1 36
1. Oil Well [] Gas Well [] Other []			8. Well Name and No.
GAS WELL RECEIVE			DREECH D 147
2. Name of Operator: 070 FARMING 9 APLWEII No.			
Caulkins Oil Company 3. Address of Operator: (505) 324 4222			30-039-27330-00S1 10. Field and Pool, Exploratory Area
(505) 534-4323			· • •
1409 W. Aztec Blvd. Ste B7, Aztec, NM 87410 4. Location of Well (Footage, Sec., Twp., Rge.)			BASIN DAKOTA, TOCITO 11. Country or Parish, State
1995' F/N 2005' F/E SEC, 7-26N-6W			
1995' F/N 2005' F/E SEC, 7-26N-6W Rio Arriba Co., New Mexico 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER D			
TYPE OF SUBMISSION TYPE OF ACTION			
[X] Notice of I		[] Abandonment	[X] Change of Plans
[] Subsequent Report [] Final Abandonment Notice		[]Recompletion	[] New Construction
		[] Plugging Back	[] Non-Routine Fracturing
		[] Casing Repair	[] Water Shut-Off
		[] Altering Casing	[] Conversion to Injection
17 December Representation Completed Competitions		[X] Other <u>TA Dakota Zone & F</u>	rirst Delivery [] Dispose Water
17. Describe Proposed or Completed Operations:			
8-24-04 This well was reperforated and frac'd in the Dakota zone.			
•	Frac did not go as planned	due to excessively high pump pressur	res.
8-25-04	Ran cast iron bridge plug to 7095'.		
0-23-04	- The Control of the		
	Perforated and frac'd Tocito zone.		
8-26-04	Cleaned out to top of cast iron bridge plug at 7095'.		
	Landed tubing on doughnu	at at 6661'.	1.01.6.8 h
10-7-04	First delivered Tocito to sales line through Williams Field Services meter # 35862 at 3:25 p. m.		
10-18-04	Well is currently producing as a single Tocito well with the Dakota zone temporarily abandoned under cast iron bridge plug set at 7095'.		
	We request approval to leave Dakota zone temporarily abandoned at this time.		
	Plans for additional work on the Dakota zone are being discussed and will be submitted in Spring 2005.		
If you have any questions please call 505-334-4323.			
NOTE: The format is issued in lieu of U.S. BLM Form 3160-5			
18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT			
11 + 1 a /			
SIGNED: Robert 7 Vingre TITLE: Superintendent DATE: October 18, 2004			
ROBERT L. VERQUER			
APPROVED BY: TITLE: DATE:			DATE
CONDITIONS OF APPROVAL, IF ANY ACCEPTED FOR I			ACCEPTED FOR RECORD
			OCT 0 - 0004
			OCT 2 6 2004