Form 3160-5 (August 1999)

■ Subsequent Report

☐ Final Abandonment Notice

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY	NOTICES AND REPORTS ON WELLS	
	form for proposals to drill or to re-enter a	
ahandanad wall	Lies Form 2160-2 (APD) for each proposals	

),	Le	ase	Sei	ial	No	).			
14	4_	2		_	_	2	_	 _	_

6. If Indian, Allottee or Tribe Name

Other

		<u> </u>		Navajo			
SUBMIT IN TR	IPLICATE - Other instr	uctions on revers	e side	7. If Unit or CA/Agreement, Name and/or No	).		
1. Type of Well			1	Horseshoe Gallup			
Oil Well 🔲 Gas Well		<i>f</i> :		8. Well Name and No.			
2. Name of Operator Vulcan	Minerals + Energy	į, k	y <b>J</b> UN 2000	124 HGU			
- % NMOCD		ĮĘ.	) r	9.—API Well No.			
3a. Address 1000 R10	Brazos Rd.	3b. Phone No. (inclu		30045 10 291			
Azrec, A	lm 87410	334-6178		10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec		Horseshoe Gallup					
Sec. 25, T. 3	IN., R. 17W.,		Commercial St.	11. County or Parish, State			
660/S-E				San Juan NM			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/	(Resume) Water Shut-Off Well Integrity			

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

**New Construction** 

Plug and Abandon

Plug Back

Recomplete

Water Disposal

Temporarily Abandon

See attached plugging procedure !

Casing Repair

Change Plans

Convert to Injection

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1		
NMOCO CONTract Plugging	Title		
Signature NM O C 9	Date	6/4/03	
THIS SPACE FOR FEDE	FRAL OR STAT	re office use	
Approved by Original Signed: Stephen Mason	Title		Date JUN 0 4 2003
Conditions of approval, if any, are attached. Approval of this notice does not vertify that the applicant holds legal or equitable title to those rights in the sub which would entitle the applicant to conduct operations thereon.	warrant or oject lease Office		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

API WELL # Well Name Well # Operator Name Type Stat County UL Sec Twp N/S Rng W/E Feet NS Ft EW Order\_No
30-045-10291 HORSESHOE GALLUP UNIT 124 PLAYA MINERALS & ENERGY INC O A San Juan P 25 31 N 17 W 660 S 660 E

api\_number status csg\_1 csg\_1q csg\_1d csg\_2 csg\_2q csg\_2d csg\_3 csg\_3q csg\_3d liner\_size liner\_quan tubing t\_set\_dept csg\_perf 30-045-10291 CO 7 5/8 107 125S 5 1/2

1585 50S 2 3/8 1495 1423-1510

Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scrapper if required,

RIH Set CIBP 1325 ', cap with 174 'cement .

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ <u>157</u> ' + - 50' under surface casing shoe or Mesa Verde base whichever is lower..

Establish Circulation; circulate cement to surface inside and outside casing

Cut off well head and install P&A marker

Cut off anchors 2' below ground

Clean and level location