District I Sold CONS. DIV DIST. 3

District II 811 5 7

State of New Mexico AUG 08 2014 Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

811 S. First St., Artesia, NM 88210 District III

Oil Conservation Division 1220 South St. Francis Dr. Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Santa Fe, NM 87505

			Rele	ease Notific	cation	n and Co	rrective A	ction				
						OPERATOR						
Name of Company Elm Ridge Exploration Co LLC						Contact Amy Archuleta						
Address Po Box 156 Bloomfield NM 87413						Telephone No. (505) 632-3476						
Facility Nat	ne Lybro	ok South #	Facility Type Oil Well									
Surface Ow	nor DI M		BLM API No. 30-043-20845									
Surface Ow	HCI DLIVI		AFT NO. 50-045-20845									
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	1	/South Line	Feet from the		est Line	County		
J	19	23N	06W	1975'	SOUT	CH	1978' EA			SANDOVAL		
Latitude 36.209335 Longitude -107.50705  NATURE OF RELEASE												
Type of Rele	ase Oil, Fr	ac Fluid, sand		Release: 400 bb, Frac sand and bls of oil.		s of Volume Recovered: Approx: 120 bbls						
Source of Release: Wellhead valve burst						Dt & Hr of Occurrence: 7-31-14 Dt & Hr of Discovery: 8-1-14 6:00 AM 11:00PM						
Was Immediate Notice Given?   ☐ Yes ☐ No ☐ Not Required												
By Whom? RICHARD GRAVES						Date and Hour 8-1-14 8:00 AM (Open hours)						
Was a Watercourse Reached?  ☐ Yes ☐ No						If YES, Volume Impacting the Watercourse. 200 bbls of fluid						
If a Watercourse was Impacted, Describe Fully.* Approximately 200 bbls of frac fluid, frac sand, and water with traces of oil was sent down the wash after the pipeline ruptured on the road and the location was flooded. It was raining and the ground was already wet allowing the fluid to flow down the wash.												
Describe Cause of Problem and Remedial Action Taken.*SEE ATTACHED												
Describe Area Affected and Cleanup Action Taken.* SEE ATTACHED  I hereby certify that the information given above is true and complete to the best of my knowledge and understand the pursuant to NMOCD rules and												
regulations a public health should their or or the enviro	ll operators or the envi operations h nment. In a	are required to a remark to a required to a	to report are acceptance adequately OCD accep	e is true and comp nd/or file certain a ce of a C-141 report investigate and a otance of a C-141	release nort by the remediate	notifications and le NMOCD m te contaminati	nd perform correct arked as "Final & on that pose a thi	ctive acti leposid reat to gr	ons for rel opt of ound wate	eases which Outling Ou	may en rator of ater, hu	ndanger f liability ıman health
Signature:						OIL CONSERVATION DIVISION  Approved by Environmental Specialist:						
Printed Name: Amy Archuleta												
Title: Sr. Regulatory Supervisor						Approval Dat	ie: 15/12/14		Expiration	Date:		

\* Attach Additional Sheets If Necessary

Date: 8-8-14

E-mail Address: aarchuleta@elmridge.net

Phone: 505 632-3476 x 201

HNCS 1422425348

Conditions of Approval:

Attached

Describe Cause of Problem and Remedial Action Taken.\*WPX fractured their Chacon #207H well and we believe the sand from the frac job collected in our poly line and caused it to plug up. The poly line is rated for 125 PSI. The over pressured line ruptured in two places and a 2" wellhead valve burst causing the fluid to spray all over location. As soon as we were notified we called a crew and water trucks to location to suck up the liquid that was sitting on location and constructions crews were also setting sandbags to stop any other fluid from going down the wash. WPX also had a crew on location and down the wash assisting with stopping the fluid.

Describe Area Affected and Cleanup Action Taken.\* The location road, well location and a nearby wash were affected. We had two crews out digging up contaminated soil and spraying simple green on location. WPX had Animas Environmental taking samples from the wash and Elm Ridge had Envirotech take samples from the location and the two places the pipeline ruptured. We still currently have a crew on location cleaning up the contaminated soil.