Submit One Copy To Appropriate District Office	State of New Me		Form C-103 Revised November 3, 2011
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
District II 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-045-11651
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NIVI 8/303 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Gallegos Canyon Unit
PROPOSALS.) 1. Type of Well: □Oil Well ☑ Gas Well □ Other			8. Well Number 211
2. Name of Operator			9. OGRID Number
BP America Production Company 3. Address of Operator			10. Pool name or Wildcat
1199 Main Ave, Durango, CO 81301			Basin Dakota
4. Well Location			
Unit Letter G: 1650 feet from the North line and 1650 feet from the East line			
Section 32 Township 29N Range 12W NMPM County San Juan 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
ASSESSMENT OF STREET	5304'	KKD, KI, GK, elc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	TENTION TO: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB		
OTHER: Description Location is ready for OCD inspection after P&A			
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/OUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection. All work was completed on 9/23/2019			
SIGNATURE Sabre Compliance Specialist DATE January 28, 2020			
TYPE OR PRINT NAME Sabre J. Beebe E-MAIL: _sabre.beebe@bpx.com_ PHONE: 970-779-9398 For State Use Only			
APPROVED BY: DATE 8/28/2000 Conditions of Approval (if any):			
AV NMOCD			
		F	FEB 1 0 2020

DISTRICT 111_





Form Information

Form Name: Submitter Name: Submission Date: Server Receive Date:

Compliance Follow Up Form
Julian Martinez (julianmartinez)
Jan 24, 2020 2:30:35 PM MST
e: Jan 24, 2020 2:30:44 PM MST
20200124-18130769938

Reference Number: Location:

1258 S Main Ave, Aztec, NM 87410, USA Jan 24, 2020 2:26:16 PM MST [View Map]

Information

Name

Date

Optional - Type Part of the Run Number or Lateral to

Filter for Next Question

Location Name (Other)

Location API (Other)

Select State

Work type

Action Complete

Photo of first corrective action completed

julianmartinez

Jan 24, 2020

GCU 211

Gallegos Canyon Unit 211

3004511651

New Mexico

Plug & Abandonment Work

Equipment Stripping



Completed work description Corrective Action 1 Photo of second corrective action completed Equipment strip off complete - Photo to the North



.

Completed work description of corrective action 2 Photo of third corrective action completed





Completed work description of corrective action 3 Photo of fourth corrective action completed

Equipment strip off complete - Photo to the South



Completed work description

Completed work description of corrective action 4

Completed work description

Summary of all work completed

Equipment strip off complete - Photo to the West Plug and abandonment - equipment strip off complete

Plug and abandonment - equipment strip off complete

Plug and abandonment - equipment strip off complete