Submit One Copy To Appropriate District Office	State of New Mex	xico	Form C-10	3
District I	Energy, Minerals and Natur	ral Resources	Revised November 3, 201 WELL API NO.	1
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONCERVATION	DIVICION	30-045-24171	
811 S. First St., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Suna 1 0, 11111 07	505	6. State Off & Gas Lease No.	
87505 SLINDRY NOTICE	S AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSAI DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	LS TO DRILL OR TO DEEPEN OR PLU	G BACK TO A	Gallegos Canyon Unit	
1. Type of Well: Oil Well G	as Well Other		8. Well Number 188 E	
2. Name of Operator			9. OGRID Number	
BP America Production Company  3. Address of Operator			000778 10. Pool name or Wildcat	_
1199 Main Ave, Durango, CO 81301			Basin Dakota	
4. Well Location				_
	om the North line and 1620 feet t	from the East line		
	ON Range 12W NMPM	County San Juan		_
	11. Elevation (Show whether DR, 5304)	RKB, RT, GR, etc.)		
12. Check Appropriate Box to In		eport or Other Da	ata	П
		į		
NOTICE OF INTE	ENTION TO: PLUG AND ABANDON	REMEDIAL WORK	SEQUENT REPORT OF:  C D ALTERING CASING	ı١
	CHANGE PLANS	COMMENCE DRII	<del></del>	,
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗆	
OTHER:	п	⊠ Location is re	ady for OCD inspection after P&A	
	liance with OCD rules and the terms	of the Operator's pit	permit and closure plan.	_
<ul> <li>✓ All pits have been remediated in comp</li> <li>✓ Rat hole and cellar have been filled an</li> <li>✓ A steel marker at least 4" in diameter at</li> </ul>	d leveled. Cathodic protection holes and at least 4' above ground level has	have been properly a	bandoned. It shows the	
<b>OPERATOR NAME, LEASE N</b>	NAME, WELL NUMBER, API NU	MBER, QUARTER	<b>QUARTER LOCATION OR UNIT LETTER</b>	<u>Ł,</u>
<u>SECTION, TOWNSHIP, AND</u> <u>MARKER'S SURFACE</u>	RANGE. All INFORMATION HA	AS BEEN WELDED	OR PERMANENTLY STAMPED ON THE	
The location has been leveled as nearly production equipment.	y as possible to original ground conto	our and has been clear	ed of all junk, trash, flow lines and other	
Anchors, dead men, tie downs and rise	ers have been cut off at least two feet	below ground level.		
			remediated in compliance with OCD rules and	the
All metal bolts and other materials hav			we been removed from lease and well location. red onsite concrete bases do not have to be	
removed.)	- 1 14 1 OCD1			
<ul><li>✓ All other environmental concerns have</li><li>✓ Pipelines and flow lines have been about</li></ul>		.10 NMAC. All fluid	s have been removed from non-retrieved flow li	nes
and pipelines.			10 1 2 2	
except for utility's distribution infrastructur		ice poles and lines hav	e been removed from lease and well location,	
		ffice to schedule an ir	spection. All work was completed on 9/19/20	19
SIGNATURE Sabre J. Bes	title Com	pliance Specialist	_DATE _ <u>January 28, 2020</u>	
TYPE OR PRINT NAME Sabre J. Bee	<u>be_</u> E-MAIL: _sabre.beebe@bpx	c.com_ PHONE: 97	0-779-9398	
For State Use Only		3 28.5	•	
APPROVED BY:	TITLE C	on Olimes /	Mice DATE 8/28/2000	5
Conditions of Approv (if any):	AV	The state of the s	MOCD	
-	AV		4	
		FFR	1 0 2020	

DISTRICT III

## BP L48 San Juan



## Form Information

Form Name: Submitter Name: Submission Date:

Submission Date: Server Receive Date: Reference Number:

Location:

Compliance Follow Up Form

Julian Martinez (julianmartinez) Jan 23, 2020 11:51:21 AM MST Jan 23, 2020 11:51:28 AM MST

20200123-18130623503

35 Rd 5793, Farmington, NM 87401, USA Jan 23, 2020 11:51:05 AM MST [ <u>View Map</u> ]

## Information

Name

Date

Optional - Type Part of the Run Number or Lateral to

Filter for Next Question

Location Name (Other)
Location API (Other)

Select State Work type

**Action Complete** 

Photo of first corrective action completed

julianmartinez

Jan 23, 2020 GCU 188E

Gallegos Canyon Unit 188E

3004524171 New Mexico

Plug & Abandonment Work

**Equipment Stripping** 



Completed work description Corrective Action 1
Photo of second corrective action completed



Strip off equipment complete - Photo to the North

Completed work description of corrective action 2 Photo of third corrective action completed





Completed work description of corrective action 3 Photo of fourth corrective action completed

Strip off equipment complete - Photo to the South



Completed work description

Completed work description of corrective action 4

Completed work description

Summary of all work completed

Strip off equipment complete - Photo to the West Plug and Abandonment - Strip off equipment complete

Plug and Abandonment - Strip off equipment complete

Plug and Abandonment - Strip off equipment complete