Submit One Copy To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resourc	Form C-103 es Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	20 045 24172
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	- Ganegos Carryon Cint
1. Type of Well: ☐Oil Well ☐ Gas Well ☐ Other	8. Well Number 211 E
2. Name of Operator BP America Production Company	9. OGRID Number 000778
3. Address of Operator	10. Pool name or Wildcat
1199 Main Ave, Durango, CO 81301	Basin Dakota
4. Well Location	
Unit Letter <u>C</u> : 900 feet from the North line and 1740 feet from the West line Section 32 Township 29N Range 12W NMPM County San Juan	
Section 32 Township 29N Range 12W NMPM County San Juan 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
5441'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	. WORK ALTERING CASING
	CE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/C	EMENT JOB
	on is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE	
MARKER'S SURFACE	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other	
production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the	
terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location,	
except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection. All work was completed on 10/10/2019	
5.1.021	
SIGNATURE January 28, 2020 TITLE Compliance Specialist DATE January 28, 2020	
TYPE OR PRINT NAME Sabre J. Beebe E-MAIL: _sabre.beebe@bpx.com_ PHONE: 970-779-9398	
For State Use Only	
APPROVED BY: TITLE (SIMPliance Hice) DATE 8/28/2020	
Conditions of Approval (if any):	
NMOCD	
FEB 1 0 2020	

DISTRICT 111

BP L48 San Juan



Form Information

Form Name: Submitter Name:

Submission Date: Server Receive Date:

Reference Number:

Location:

Compliance Follow Up Form

Julian Martinez (julianmartinez) Jan 24, 2020 2:38:04 PM MST Jan 24, 2020 2:38:15 PM MST 20200124-18130772575

101 Animas St, Aztec, NM 87410, USA Jan 24, 2020 2:34:40 PM MST [<u>View Map</u>]

Information

Name

Date

Optional - Type Part of the Run Number or Lateral to

Filter for Next Question Location Name (Other)

Location API (Other)

Select State Work type

Action Complete

Photo of first corrective action completed


julianmartinez Jan 24, 2020 GCU 211E

Gallegos Canyon Unit 212E correction well name GCU 211E 3004524173

New Mexico

Plug & Abandonment Work

Equipment Stripping




Completed work description Corrective Action 1
Photo of second corrective action completed




Equipment strip off complete - Photo to the North

Completed work description of corrective action 2
Photo of third corrective action completed





Completed work description of corrective action 3 Photo of fourth corrective action completed





Completed work description

Completed work description of corrective action 4

Completed work description

Summary of all work completed

Equipment strip off complete - Photo to the West Plug and abandonment - Strip off complete Plug and abandonment - Equipment Strip off complete Plug and abandonment - Equipment Strip off complete