Submit I Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103	
District I 1625 N. French Dr., Hobbs, NM 88240			ources	L API NO.	October 13, 2009
District II	OIL CONSEDA	OIL CONSERVATION DIVISION		30-039-29488	
1301 W. Grand Avc., Artesia, NM 8821 District III	1220 South St. Francis Dr.		5. Inc	dicate Type of Leas	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6 St	STATE te Oil & Gas Lease	FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505		,	E-346		5 140.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			TO A Rosa	7. Lease Name or Unit Agreement Name Rosa Unit	
1. Type of Well: Oil Well Gas Well Other				8. Well Number Rosa #357A	
2. Name of Operator Williams Production Company,	LLC		9. OC 12870	GRID Number	
3. Address of Operator				10. Pool name or Wildcat	
P.O. Box 640 Aztec, NM 87410			Basin	Fruitland Coal	
4. Well Location					
	1368_feet from the				
Section 36	Township 3. 11. Elevation (Show wh			NMPM	County San Juan
	6370' GR			W. 1974 **	等中华基本 ·
12. Chec	k Appropriate Box to Inc	dicate Nature o	f Notice, Repor	t or Other Data	
NOTICE OF	INTENTION TO:		SUBSEQU	IENT REPORT	ΓOF:
PERFORM REMEDIAL WORK		_	DIAL WORK		RING CASING
	☐ CHANGE PLANS ☐ MULTIPLE COMPL		ENCE DRILLING (G/CEMENT JOB	OPNS.□ P AND	JA LI
			O/OZIMZIVI OOD		
OTHER:		☐ OTHER	R: Completion	\boxtimes	
	muleted operations (Clearly				Iding estimated date
13. Describe proposed or co	work). SEE RULE 19.15.7.	state all pertinent	details, and give p	ertinent dates, inclu	
13. Describe proposed or co of starting any proposed	work). SEE RULE 19.15.7. recompletion.	state all pertinent 14 NMAC. For M	details, and give p	ertinent dates, inclu	
13. Describe proposed or co of starting any proposed proposed completion or	work). SEE RULE 19.15.7. recompletion. prep. POH with rods and pump	state all pertinent 14 NMAC. For M	details, and give p	ertinent dates, inclu	
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506'	state all pertinent 14 NMAC. For M	details, and give p	ertinent dates, inclu ns: Attach wellbore	e diagram of
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing.	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifole	v state all pertinent 14 NMAC. For M	details, and give p ultiple Completion	ertinent dates, inclu ns: Attach wellbore	e diagram of
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMC 8-4-11 – MIRU AWS #781. Test pipe	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold on, all test good.	v state all pertinent 14 NMAC. For M	details, and give p ultiple Completion	ertinent dates, inclu ns: Attach wellbore	e diagram of
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMC 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500# , 3	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold on, all test good.	v state all pertinent 14 NMAC. For M	details, and give p ultiple Completion	ertinent dates, inclu ns: Attach wellbore	e diagram of
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMC 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold 30 min, all test good.	v state all pertinent 14 NMAC. For M	details, and give p ultiple Completion	ertinent dates, incluses: Attach wellbore	ow, 5 min and 1500#
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMO 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3 8-5-11 – Orientate and TIH with whips 8-6-11 – Mill window 2651' – 2663' 8-7 thru 8-8-11 – Drill curve 2663' – 3	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold 30 min, all test good.	v state all pertinent 14 NMAC. For M	details, and give p ultiple Completion	ertinent dates, incluses: Attach wellbore	ow, 5 min and 1500# CEIVED NO. 10151.3
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMO 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3 8-5-11 – Orientate and TIH with whips 8-6-11 – Mill window 2651' – 2663'	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold 30 min, all test good.	v state all pertinent 14 NMAC. For M	details, and give p ultiple Completion	ertinent dates, incluses: Attach wellbore	ow, 5 min and 1500# CEIVED NO. 10151.3
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMO 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3 8-5-11 – Orientate and TIH with whips 8-6-11 – Mill window 2651' – 2663' 8-7 thru 8-8-11 – Drill curve 2663' – 3	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold 30 min, all test good.	v state all pertinent 14 NMAC. For M	details, and give p ultiple Completion	ertinent dates, incluses: Attach wellbore	ow, 5 min and 1500# CEIVED NO. 10151.3
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMO 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3 8-5-11 – Orientate and TIH with whips 8-6-11 – Mill window 2651' – 2663' 8-7 thru 8-8-11 – Drill curve 2663' – 3	work). SEE RULE 19.15.7. recompletion. s prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold 30 min, all test good.	d, mud cross valves,	details, and give pultiple Completion	ertinent dates, incluses: Attach wellbore	ow, 5 min and 1500# CEIVED NO. 10151.3
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMO 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3 8-5-11 – Orientate and TIH with whips 8-6-11 – Mill window 2651' – 2663' 8-7 thru 8-8-11 – Drill curve 2663' – 3 Spud Date:	work). SEE RULE 19.15.7. recompletion. a prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold 30 min, all test good. stock Rig R on above is true and complet	d, mud cross valves, Release Date:	details, and give pultiple Completion	ertinent dates, incluses: Attach wellbore Religions (250#100000000000000000000000000000000000	ow, 5 min and 1500# CEIVED NO. 10151.3
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMC 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3 8-5-11 – Orientate and TIH with whips 8-6-11 – Mill window 2651' – 2663' 8-7 thru 8-8-11 – Drill curve 2663' – 3 Spud Date:	work). SEE RULE 19.15.7. recompletion. A prep. POH with rods and pump RIH and set RBP @ 2506' D location rams, blind rams, choke manifold 30 min, all test good. Stock Rig R on above is true and complet	d, mud cross valves, Release Date:	details, and give pultiple Completion floor valve and upper knowledge and be	ertinent dates, incluses: Attach wellbore Relief.	ow, 5 min and 1500# CEIVED LONS. DIV. DIST. 3
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMO 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3 8-5-11 – Orientate and TIH with whips 8-6-11 – Mill window 2651' – 2663' 8-7 thru 8-8-11 – Drill curve 2663' – 3 Spud Date: I hereby certify that the informatical signature of print name Larry Higg For State Use Only	work). SEE RULE 19.15.7. recompletion. a prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold 30 min, all test good. stock Rig R on above is true and complet TITLE_PetinsE-mail address:la	d, mud cross valves, Release Date: re to the best of my crmit Supervisor	details, and give pultiple Completion floor valve and upper knowledge and be	ertinent dates, incluses: Attach wellbore Relations: Attach wellbore Relations: Attach wellbore Relations: Attach wellbore Relations (Section 1987) Relations (Section 1987	Ow, 5 min and 1500# CEIVED LCONS. DIV. DIST. 3 SETTINGE 68 L8
13. Describe proposed or co of starting any proposed proposed completion or 8-1-11 – MIRU HWS #15 for sidetrack 8-2-11 – POH with production tubing. 8-3-11 – Reset RBP @ 2700' RDMC 8-4-11 – MIRU AWS #781. Test pipe high, 10 min. Test 7" casing 1500#, 3 8-5-11 – Orientate and TIH with whips 8-6-11 – Mill window 2651' – 2663' 8-7 thru 8-8-11 – Drill curve 2663' – 3 Spud Date: I hereby certify that the informatical signatures of print name Larry Higg	work). SEE RULE 19.15.7. recompletion. a prep. POH with rods and pump RIH and set RBP @ 2506' location rams, blind rams, choke manifold 30 min, all test good. stock Rig R on above is true and complet TITLE_PetinsE-mail address:la	d, mud cross valves, Release Date: re to the best of my crmit Supervisor_ arry.higgins@willia Deputy Oil & E Dis	details, and give pultiple Completion floor valve and upper knowledge and be	ertinent dates, incluses: Attach wellbore Relations: Attach wellbore Relations: Attach wellbore Relations: Attach wellbore Relations (Section 1987) Relations (Section 1987	ow, 5 min and 1500# CEIVED LONS. DIV. DIST. 3

Rosa Unit #357A - Page 2

8-9 thru 8-11 - Drill horizontal lateral 3351' - 5167' TD lateral @ 5167' at 1700 hrs

 $\frac{\textbf{8-12-11}}{\text{Liner top @ 2669'}}. \text{ Top perf @ 2719'}, \text{ bottom perf @ 5056'} \text{ Retrieve RBP @ 2700'}$

8-13-11 - Release rig @ 0800 hrs. RDMO

 $\underline{\textbf{8-22-11}}$ – MIRU HWS #15. Land tubing as follows, top down, 98 jts, 2-7/8", 6.5# J-55 EUE 8rd tubing, 2 28" ID SN @ 3206', 1 jt tubing, EOT @ 3232'. Install 200' $\frac{1}{2}$ " capillary tubing

<u>8-23-11</u> - Run pump & rods as follows, bottom up, 2-1/2" x 1-1/2" x 8' x 9' RHAC pump w/gas anchor, 3 1-1/4" sinker bars, 124 ¾" rods, 8', 6', & 2' pony rods, 1-1/4" x 22' polished rod w/10' polished rod liner. RDMO