Submit 3 Copies To Appropriate District Office	State of New Mex			Form C-103
District 1	Energy, Minerals and Natura	al Resources	WELL API NO.	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION	DIVISION	30-	045-07780
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. France	,	5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 875	/	STATE [6. State Oil & Ga	FEEs Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	70013333	o. said on a sa	3 20430 110.
87505 SUNDRY NOT	ICES AND REPORTS ON WELES	10 11 18 18 18 18 18 18 18 18 18 18 18 18	7. Lease Name or	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLI	SALS TO DRILL OR TO DEEPEN OF PLUC CATION FOR PERMIT" (FORM C-101) FOR	G BACK TO:A 🥈 🥳		lughes B
PROPOSALS.) 1. Type of Well: Oil Well X (Gas Well 🔲 Other	<005	Well Number	7
2. Name of Operator	Pro Pro	95.45	59. OGRID Numb	ì
BP America Production Compared 3. Address of Operator	iy - Attn: Mary Corley		10. Pool name or	000778 Wildcat
P.O. Box 3092 Houston, TX 77	1253	180670717079 90°	Blanco Mesavero	
4. Well Location	<u> </u>	L'ENTO, L'ORENTE	<u> </u>	,
	1170 feet from the South			
Section 29	Township 29N Range 08V 11. Elevation (Show whether DR, I		San Juan	County
	6424' (
Pit or Below-grade Tank Application	or Closure			
Pit type Workover Depth to Gro	undwater <u>>100°</u> Distance from nearest f	resh water well <u>>100</u>	00° Distance from nea	rest surface water >1000'
Pit Liner Thickness:12 mil	Below-Grade Tank: Volume	bbls; Const	ruction Material	
12. Check	Appropriate Box to Indicate Na	ture of Notice,	Report or Other	Data
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS MULTIPLE COMPL	COMMENCE DRI		P AND A
FULL OR ALTER CASING [MOLTIPLE CONIPL	CASING/CEMEN	130В Ц	
		OTHER:	1	
	oleted operations. (Clearly state all peork). SEE RULE 1103. For Multiple			
RP America Production Comp	any request permission to recon	nnlete the subject	of wall into the Ω	tara Chaora Dool and
-	ole with the existing Blanco Mes	•		
~ <u>-</u>) and Otero Chacra (82329) Poo	-	_	
	The working and overriding roy			
•	itional notification is required. I			
	llocated based on the subtraction le. That production shall serve			
	well. The balance of the produ			
future production decline estin				
	nhole in the subject well from th	he proposed Poo	ls with not reduc	e the value of the total
remaining production				
	t per BP America – San Juan Ba e closed according to closure pla		orkover Pit Cons	truction Plan issued
date of 11//11/2004. The will be	DA-182			
I hereby certify that the information	above is true and complete to the bes	st of my knowledge	e and belief. I furthe	er certify that any pit or below-
grade tank has been/will be constructed or	r closed according to NMOCD guidelines 🗆	, a general permit	or an (attached) altern	ative OCD-approved plan □.
SIGNATURE May Out		r. Regulatory Ana		E 03/09/2005
Type or print name Mary Corley For State Use Only	E-mail address: co			ne No. <u>281-366-4491</u>
APPROVED BY:	TITLE	ITY OIL & GAS IMS	PECTON, DIST. (%)	DATEMAR 1 4 2005
Conditions of Approval (if any):	<i>v</i> ,			

Hughes B 7 API #: 30-045-07780 Complete into the Chacra and DHC with the Mesaverde February 14, 2005


Procedure:

- 1. Perform pre-rig site inspection. Check for: size of location, Gas Taps, other wells, other operators, running equipment, wetlands, wash (dikes req.), H2S, barriers needed for equipment, Landowner issues, location of pits (buried lines in pits), Raptor nesting, critical location, check anchors. Check ID wellhead, if earth pit is required have One Call made 48 hours prior to digging.
- 2. Perform second site visit after lines are marked to ensure all lines clear marked pit locations. Planning and Scheduling to ready location for rig.
- 3. RU slickline unit or wireline unit. Pressure test lubricator and equipment. RIH and set **two** barriers (CIBP, tbg collar stop w/plug, or plug set in nipple) for isolation in tubing string.
- 4. Check and record tubing, casing, and bradenhead pressures. Ensure production casing has double casing valves installed. Double valve all casing strings.
- 5. MIRU workover rig. LO/TO all necessary equipment including but not limited to: meter run, Automation, Separators and water lines.
- 6. Blow down well. Kill with 2% KCL water ONLY if necessary.
- 7. Check all casing strings to ensure no pressure exist on any annulus. The operations of removal of wellhead and installation of BOP's will be performed under a dispensation for one (1) barrier on the backside.
- 8. Nipple down Wellhead. NU BOPs and diversion spool with 3" outlets and 3" pipe to the blow tank. Pressure test BOPs to 200 psi above BHP. Monitor flowing casing pressure with gauge (with casing flowing to blow tank) throughout workover.
- 9. Install stripping rubber, pull tubing hanger up above pipe rams, and shut pipe rams. Remove stripping rubber. Strip tubing hanger out of hole. Re-install stripping rubber.
- 10. TOH and LD 2-3/8" production tubing currently set at 4983'. Using approved "Under Balance Well Control Tripping Procedure".
- 11. TIH w/ scraper for 4-1/2". Check the distance between the top of the blind rams and the length of the bottom hole assembly that is being run. If the BHA is too long then the well has to be top killed and monitored prior to opening bind rams. RIH to PBTD at 5,361'. POOH.
- 12. Set bridge plug at 4,500'. Fill casing w/ 2%KCl and test to 2,500 psi w/ rig pumps.
- 13. Prepare for explosive operations. Follow Schlumberger Explosive SOP including radio silence, suspension of welding operations, and isolation of electrical devices from the work area. Perform Pre-job Safety Meeting to review JSA and procedures.
- 14. RIH with 3-1/8" casing guns w/lubricator. Perforate Chacra formation w/ 4 SPF.

- 15. NU Frac isolation equipment. Install and monitor production casing and treating pressure during entire job in frac van via pressure transducers on production casing and treating line. Spearhead 500 gal 15% HCL, establish injection rate, and proceed with fracture stimulation according to Schlumberger schedule. Maintain surface pressures les than 3,000 psi during frac job. Flush frac with foam. Fill out GWSI scorecard.
- 16. Flowback frac immediately. Flow well through choke manifold on 1/4", 1/2" and 3/4" chokes increasing drawdown until well dies or stabilizes. This is to aid in reducing sand flowback. Recommend 8 hours of flow for each choke size.
- 17. Rig up air package/unit, pressure test all lines (Testing procedure to be supplied from air company), TIH with tubing and bit for 4-1/2" casing. Cleanout fill to top of BP set at 4,500'. Perform well test on Chacra for regulatory and document well test in DIMS.
- 18. Cleanout fill, cement retainer, and BP set at 4,500'. Cleanout to PBTD at 5,361'. Blow well dry.
- 19. Rabbit tubing and RIH with 2-3/8" production tubing (with muleshoe, F-nipple with plug, 4 ft pup, X-nipple with plug).
- 20. Land 2-3/8" production tubing at +/-5,200'. Lock down hanger.
- 21. Pressure test tubing to 500 psi with air unit, make sure tubing spool valves are open. Care should be taken during pressure testing of the tubing due to potential problem caused if tubing parts close to surface or above the hanger. Check all casing string for pressure. The operations of removal of wellhead and installation of BOP's will be performed under a dispensation for one (1) barrier on the backside.
- 22. ND BOP's. NU Wellhead. During Master valve placement ensure the top of hanger has spacer nipple in place to bottom of bonnet flange so plunger equipment will not hang up through tree. Pressure test Wellhead.
- 23. RU WL unit. Run gauge ring for 2-3/8" tubing. Pull plugs and set tubing stop for plunger. Communicate plunger equipment status to IC room personnel.
- 24. RD slickline unit.
- 25. Test well for air. Return well to production and downhole co-mingle Chacra and Mesaverde.

Hughes B 7

Sec 29, T29N, R8W API # 30-045-07780



updated: 2/10/05 CFR

District I

1625 N. French Dr., Hobbs, NM 88240

811 South First, Artesia, NM 88210

State of New Mexico Energy, Minerals & Natural Resources Department

Form C-102 Revised August 15, 2000

District II

OIL CONSERVATION DIVISION

Submit to Appropriate District Office State Lease - 4 Copies

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV 2040 South Pacheco, Santa Fe, NM 87505 2040 South Pacheco Santa Fe, NM 87505

Fee Lease - 3 Copies AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

¹ API Number 30-045-07780	² Pool Code 82329	³ Pool Name Otero Chacra
⁴ Property Code 000702	⁵ Property Name Hughes B	⁶ Well Number 7
⁷ OGRID No. 000778	⁸ Operator Name BP America Production (° Elevation Company 6424' GR

¹⁰ Surface Location

UL or lot no.	Section	Township	Range	Lot Idn	Feet from	North/South	Feet from	East/West	County
М	29	29N	W80		1170	South	850	West	San Juan
			11 Botto	m Hole	Location If	Different I	rom Sur	face	
UL or let no.	Section	Township	Range	Lot Idn	Feet from	North/South	Feet	East/West	County
12 Dedicate		¹³ Joint o	r Infill		¹⁴ Consolidation C	Code		19	Order No.

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A

	NON-STANDA	ARD UNIT HAS BEEN .	APPROVED BY THE	DIVISION
				¹⁷ OPERATOR CERTIFICATION I hereby certify that the information contained
				herein is true and complete to the best of my
				knowlegfe/find belief) Buy orley Mary Corley
				Signayure // Mapy Corley
				Printed Name Sr. Regulatory Analyst
				Title 3/9/2005
				Date
				¹⁸ SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat
				was plotted from field notes of actual surveys made by
				me or under my supervision, and that the same is true
				and correct to the best of my belief.
				On File
−850' → ≎				Date of Survey
.				Signature and Seal of Professional Surveyor:
1170			·	
				Fred B Kerr 3950
				Certificate Number

Future Production Decline Estimate

Mesaverde Daily Rates

Gas Volume

Mônth

Jan-2004 Feb-2004 Mar-2004

Gas Volume

Month

Apr-2010 May-2010

Mar-2010

Feb-2010

Jun-2010 Jul-2010

Aug-2010 Sep-2010

Oct-2010 Nov-2010 Dec-2010 Jan-2011

145

Jan-2005 Feb-2005

149

Aug-2004

Oct-2004 Nov-2004 Dec-2004

Sep-2004

Mar-2011 Apr-2011

May-2011 Jun-2011 Jul-2011

Feb-2011

= -dt	142	146	142	10	-0.027779564	-0.002777956
In(Qf/Qi) :	Of=	ë	rate=	time=	dt=	decline=

Apr-2004 May-2004

Jun-2004 Jul-2004

Gas Volume	1	138	138	137	137	136	136	136	135	135	134	134	134	133	133	133	132	132	132	131	131	130	130	130	129	129	129	128	128	128	127	127	127	126		125
Month	늘	Feb-2007	Mar-2007		aĶ		Jul-2007		Sep-2007		Nov-2007	Dec-2007	Jan-2008		Mar-2008	Apr-2008	IS.	Jul-2008	Aug-2008		Oct-2008	Nov-2008	Dec-2008	Jan-2009	Feb-2009	Mar-2009	Apr-2009	May-2009	Jun-2009	Jul-2009	Aug-2009	-de	oct-200	Nov-2009	8	Jan-2010

146 145 145 145

Apr-2005 May-2005

Mar-2005

Jun-2005 Jul-2005 118

Nov-2011 Dec-2011 Jan-2012 Feb-2012 Mar-2012

Aug-2011 Sep-2011 Oct-2011 Apr-2012 May-2012

Jun-2012 Jul-2012 Aug-2012

141

141

141

Aug-2005 Sep-2005 Oct-2005 Jan-2006 Mar-2006 May-2006 Jun-2006 140

Aug-2006

Sep-2006 Oct-2006

Jul-2006

Nov-2006

Dec-2006

Sep-20	Oct-20'	Nov-20	Dec-20,	Jan-20′	

$\overline{}$
<u>o</u>
ြင္ပ
ă

Hughes B 7 Future Production Decline Estimate

Mesaverde Daily Rates

Feb-2013 Mar-2013 Apr-2013 May-2013

Month

Jun-2013 Jul-2013

Aug-2013 Sep-2013 Oct-2013

Nov-2013

Dec-2013 Jan-2014 Feb-2014 Mar-2014

Eas	101	<u>ت</u> ما	না	<u> </u>	_	_	_			_	\overline{a}	തി	ക	م ا	ക	~	~	<u> </u>					(0	<u>ش</u>	<u>~</u>	(OI	اما	<u> </u>	101	10	 1	+ 1	₩	ഹി	ച	~
Gas Volume	102	102	102	102	101	101	101	100	100	100	100	66	66	66	6	96	86	86	26	97	97	97	96	96	96	96	95	36	95	96	94	94	94	93	6	03
Month	Feb-2016	Mar-2016	Apr-2016	May-2016	Jun-2016	Jul-2016	Aug-2016	Sep-2016	Oct-2016	Nov-2016	Dec-2016	Jan-2017	Feb-2017	Mar-2017	Apr-2017	May-2017	Jun-2017	Jul-2017	Aug-2017	Sep-2017	Oct-2017	Nov-2017	Dec-2017	Jan-2018	Feb-2018	Mar-2018	Apr-2018	May-2018	Jun-2018	Jul-2018	Aug-2018	Sep-2018	Oct-2018	Nov-2018	Dec-2018	lan-2010
Γø	ल	13	13	12	[2]	[2]	-	-	—	0	10	9	10	60	6	<u></u>	<u></u>	8	[7	7	7	7	9	9	9	2	ाञ	2	4	4	4	4	രി	ल	<u>~</u>
as Volume			11			11	11	11	11	11		11	11	10	109	109	108	108	108	107	107	107	107	106	106	106	105	105	105	104	104	104	104	103	103	103

Apr-2014

May-2014

Jun-2014

Sep-2014

Oct-2014

Jan-2015

Apr-2015

Apr-2015

Apr-2015

Apr-2015

Jun-2015

Oct-2015

Jun-2015

Oct-2015

Dec-2015

Jun-2015

Dec-2015

Jun-2015

Dec-2015

Jun-2015

Dec-2015