

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

<b>Name of Company:</b> Energen Resources, Inc.	<b>Contact:</b> Ed Hasely
<b>Address:</b> 2010 Afton Place, Farmington, NM 87401	<b>Telephone No:</b> 505-324-4131
<b>Facility Name:</b> Jicarilla 107 #5 (API No. 30-039-22053)	<b>Facility Type:</b> Gas Pipeline

<b>Surface Owner:</b> Jicarilla	<b>Mineral Owner:</b> Jicarilla	<b>Lease No.:</b> Jicarilla 107
---------------------------------	---------------------------------	---------------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	33	26N	4W	1720	North	1495	West	Rio Arriba

Latitude 36.44572 Longitude -107.26043

**NATURE OF RELEASE**

<b>Type of Release:</b> Produced Water	<b>Volume of Release:</b> 8 bbls	<b>Volume Recovered:</b> None
<b>Source of Release:</b> Open Top Tank	<b>Date and Hour of Occurrence:</b> 7/11/13	<b>Date and Hour of Discovery:</b> 7/11/13
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Bryce Hammond	
<b>By Whom?</b> Kellie Campbell	<b>Date and Hour:</b> 7/11/13 at 2:30 pm	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse.</b> NA	


**If a Watercourse was Impacted, Describe Fully.\*** NA

**RCVD JUL 18 '13  
OIL CONS. DIV.  
DIST. 3**

**Describe Cause of Problem and Remedial Action Taken.\*** The bottom of the steel pit tank corroded and allowed approximately 8 barrels of produced water to leak into the bermed area.

**Describe Area Affected and Cleanup Action Taken.\*** The produced water was all contained inside the berm around the pit tank on location. No fluids were recovered. The impacted soils inside the berm were turned over and broken up to prevent a crust from forming.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> 	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Ed Hasely	<b>Approved by District Supervisor:</b> 	
<b>Title:</b> Sr. Environmental Engineer	<b>Approval Date:</b> 7/31/2013	<b>Expiration Date:</b>
<b>E-mail Address:</b> ed.hasely@energen.com	<b>Conditions of Approval:</b>	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> 7/17/13 <b>Phone:</b> 505-324-4131 / 505-330-3584(cell)		

\* Attach Additional Sheets If Necessary

25K1321241832