

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Huntington Energy, L.L.C.	Contact: Catherine Smith
Address: 908 N.W. 71 st St., Oklahoma City, OK 73116	Telephone No.: (405) 840-9876
Facility Name: Canyon Largo Unit NP #347	Facility Type: Oil Well

Surface Owner: Bureau of Land Management	Mineral Owner: Bureau of Land Management	API No.: 30-039-23575
--	--	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	I	24N	7W	2645	North	690	East	Rio Arriba

Latitude: 36.3428 Longitude: -107.5196

NATURE OF RELEASE

Type of Release: Fire	Volume of Release: Unknown	Volume Recovered:
Source of Release: Fire	Date and Hour of Occurrence: 3/4/14, 11:45 am	Date and Hour of Discovery: 3/4/14, 11:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell, New Mexico Oil Conservation Division	
By Whom? Catherine Smith, Huntington Energy, L.L.C.	Date and Hour: 3/4/2014 at 12:19 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD MAR 11 '14	

If a Watercourse was Impacted, Describe Fully.*

**OIL CONS. DIV.
DIST. 3**

Describe Cause of Problem and Remedial Action Taken.*

Prior to testing the casing per regulations, the hole was being displaced w/2% KCL wtr via the casing and out the tubing to load hole completely with water. When bottoms up was realized at the pit, the mud pump backfired, igniting the gas and setting the approx. 28 bbls oil on fire in the above ground steel pit (approx. 4 bbls burned). After a head count of all personnel on location was complete, the BOP's were checked to insure the pipe rams were SI and the TIW valve was SI on the tubing, securing the well. All fire extinguishers on location were depleted in an effort to put out the fire. Local fire departments were contacted and deployed to location. Three personnel on location required medical attention.

Describe Area Affected and Cleanup Action Taken.*

The fire was contained to the rig equipment and area under the rig equipment.
Rid location of damaged equipment from the fire. Ron Lackey, Huntington Energy company representative, will be on location for clean-up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Catherine Smith</i>	OIL CONSERVATION DIVISION	
Printed Name: Catherine Smith	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory	Approval Date: <u>5/7/14</u>	Expiration Date:
E-mail Address: csmith@huntingtonenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/6/2014 Phone: (405) 840-9876		

* Attach Additional Sheets If Necessary

#DCS 141273 1422