

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Enervest Operating	Contact Michael Dame HSE Associate
Address 2700 Farmington Ave, Building K, Suite #1	Telephone No. 505-325-0318
Facility Name Jicarilla A #007	Facility Type Gas Well

Surface Owner Jicarilla Apache Tribe	Mineral Owner Enervest Operating	API No.30-039-08097
--------------------------------------	----------------------------------	---------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	17	26N	05W					Rio Arriba

Latitude 36.48411 Longitude -107.38872

**NATURE OF RELEASE**

Type of Release. Condensate	Volume of Release Est-20BBLS	Volume Recovered. Unknown
Source of Release. Production Tank had hole in bottom of it	Date and Hour of Occurrence. Unknown	Date and Hour of Discovery. July 24 <sup>th</sup> , 2015. 1:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? To Hobson Sandoval (EPOC for Jicarilla Tribe)	
By Whom? Michael Dame	Date and Hour. July 24 <sup>th</sup> , 2015 1:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



OIL CONS. DIV DIST. 3  
JUL 27 2015

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The problem and cause of this release was a leak happened to produce from the bottom of the 300 BBL production tank on location. The remedial action that is being taken is to dig out and haul off all impacted soil. When all contaminated soil is cleaned out, we will haul in clean dirt that is ok will the permission of where from the EPOC for the Tribe.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area was inside the firewall of the production tank and all the condensate was contained. The action of cleanup will be to clean out all contaminated dirt and haul off to local approved land farm. And haul in new clean dirt, when all contaminated soil is taken care of. There will soil sampling as well as lab analysis done by Envirotech Laboratory.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Michael Dame	Approved by Environmental Specialist: 	
Title: HSE Associate	Approval Date: 8/3/15	Expiration Date:
E-mail Address: mdame@enervest.net	Conditions of Approval:	
Date: 7-27-2015 Phone: 505-325-0318	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

#NCS 15215 54890