submitted in lieu of Form 3160-5
UNITED STATES

UNITED STATES	
DEPARTMENT OF THE INTE	RIOR
BUREAU OF LAND MANAGE	EMENT

Sundry Notices and R	eports on Wells			
	,		5.	Lease Number SF-078878
1. Type of Well GAS		7005 OCT 32 PM 1 25	6.	If Indian, All. or Tribe Name
2. Name of Operator		RECZIVED 070 FARMINGTON NM	7.	Unit Agreement Name
BURLÍNGTON RESOURCES O	IL & GAS COMPANY			Canyon Largo Unit
			- 8.	Well Name & Number
3. Address & Phone No. of Op		00	0	Canyon Largo Unit #194
PO Box 4289, Farmington, 1	NM 87499 (505) 326-970	UU 	9. 	API Well No.
4. Location of Well, Footage, Sec., T—N, R—W, NMPM	Sec., T, R, M		10.	30-039-20716 Field and Pool
Unit A (NENE), 810' F	'NL & 1150' FEL, Sec. 2	25, T25N, R7W NMPM	11.	Ballard Pictured Cliffs County and State Rio Arriba, NM
Type of Submission: ☑ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment	Type of Action:	☐ Change of Plans ☐ New Construction ☐ Non-Routine Fracturing ☐ Water Shut-off ☐ Conversion to Injection	□ Ot	MOV 2005 PECEIVED
13. Describe Proposed or Com It is intended to Plug & Abandon	•	ng to the attached procedure and well	bore dia	grams.
14. I hereby certify that the for	house Mel	ect. <u>Thompson</u> Title <u>Regulatory</u>	Associ	ate II Date <u>11/1/05</u>
(This space for Federal or State C APPROVED BY Original Sign CONDITION OF APPROVAL,	if any:			DateNOV 0 2 2005
Title 18 U.S.C. Section 1001, makes it a crime for any the United States any false, fictitious or fraudulent states				

Canyon Largo Unit #194 – Pictured Cliffs PLUG AND ABANDONMENT PROCEDURE

810' FNL & 1150' FEL; NE, Section 25, T25N, R7W Latitude: N 36.37573, Longitude: W 107.52045

AIN #4427101

10/05/05

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

All cement will be ASTM Type III, mixed at 14.8 ppg with a 1.32 cuff's yield.

- Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and BR safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line and blow down well; kill with water as necessary. ND wellhead and NU BOP. Test BOP. Tally and prepare a 1-1/4" IJ tubing workstring. Round-trip 2.875" wireline gauge ring to 2544'.
- 2. Plug #1 (Pictured Cliffs perforations and Fruitland, Kirtland and Ojo Alamo tops, 2544' 1770'): TIH and set 2.875" wireline CIBP at 2544'. TIH with workstring and tag CIBP. Load casing with water and circulate well clean. Pressure test casing to 500#. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 21 sxs cement and spot a balanced plug inside casing above CR to isolate the Pictured Cliffs perforations and to cover the Fruitland, Kirtland and Ojo Alamo tops. TOH and LD tubing.
- 3. Plug #2 (Nacimiento top and 8.625" Surface casing, 280' Surface): Perforate 2 squeeze holes at 280'. Establish circulation out the bradenhead valve with water. Mix and pump approximately 115 sxs Type III cement down the 2.875" casing to circulate good cement out bradenhead valve. Shut well in and WOC.
- 4. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Recommended:	Area Engineer	Approved:	Ming Sup	erintende	ľ
Engineer	Office - (326-9779) Cell - (486-0046)	Sundry Required: Approved:	YES	NO	_

Lease Operator: Robin Danek Cell: 320-0546 Specialist: Sheldon Montoya Cell: 320-2857 Foreman: Terry Nelson Cell: 320-2503

1. 1

Canyon Largo Unit #194

Current AIN #4427101

Ballard Pictured Cliffs

810' FNL, 1150' FEL, Section 25, T-25-N, R-7-W, Rio Arriba County, NM

Lat: 36.37573 / Long: 107.52045 API #30-039-20716

Today's Date: 10/5/05

Spud: 9/29/73

Completed: 10/11/73

Elevation: 6804' GL

6815' KB 12.25" hole

Nacimiento @ 230'

7.875" hole

Ojo Alamo @ 1820'

Kirtland @ 2035'

Fruitland @ 2328'

Pictured Cliffs @ 2594'

6.75" hole

8.625", 24#, K-55 Csg set @ 124' Cmt with 106 cf (Circulated to Surface)

Well History:

No Workover of Record

TOC @ 1200' (T.S.)

Pictured Cliffs Perforations: 2594' - 2672'

2.875" 6.4#, J-55 Casing set @ 2734' Cement with 341 cf

TD 2734' **PBTD 2724**'

Canyon Largo Unit #194 Proposed P&A

AIN #4427101

Ballard Pictured Cliffs

810' FNL, 1150' FEL, Section 25, T-25-N, R-7-W, Rio Arriba County, NM

Lat: 36.37573 / Long: 107.52045 API #30-039-20716

Today's Date: 10/5/05

Spud: 9/29/73

Completed: 10/11/73

Elevation: 6804' GL

6815' KB 12.25" hole

Nacimiento @ 230'

7.875" hole

Ojo Alamo @ 1820'

Kirtland @ 2035'

Fruitland @ 2328'

Pictured Cliffs @ 2594'

6.75" hole

8.625", 24#, K-55 Csg set @ 124' Cmt with 106 cf (Circulated to Surface)

Plug #2: 280' - 0'
Type III cement: 115 sxs

Perforate @ 280'

TOC @ 1200' (T.S.)

Plug #1: 2544' - 1770' Type III cement: 21 sxs

Set CIBP @ 2544'

Pictured Cliffs Perforations: 2594' – 2672'

2.875" 6.4#, J-55 Casing set @ 2734' Cement with 341 cf

TD 2734' PBTD 2724'