

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BP	Contact: Steve Moskal
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497
Facility Name: Northeast Blanco Unit 031	Facility Type: Natural gas well
Surface Owner: Federal (BOR)	Mineral Owner: Federal
API No. 3004513331	

LOCATION OF RELEASE

Unit Letter N	Section 7	Township 30N	Range 07W	Feet from the 770	North/South Line South	Feet from the 770	East/West Line West	County: San Juan
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	------------------

Latitude 36.822061° Longitude -107.615697°

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 70.6 mcf	Volume Recovered: none
Source of Release: 1" Ball valve on wellhead piping	Date and Hour of Occurrence: 2/17/17; 9:40 PM	Date and Hour of Discovery: 2/18/17; 11:50 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Gas release due to mechanical failure 1" ball valve on wellhead piping. No environmental impacts as gas was vented directly to atmosphere.		
Describe Area Affected and Cleanup Action Taken.* Broken ball valve vented directly atmosphere. No action necessary outside of repairing ball valve and piping. Root cause determined that the ball valve was likely over-torqued during installation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONS. DIV DIST. 3

MAR 02 2017

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Steve Moskal	Approval Date: 3/2/2017	Expiration Date:
Title: Field Environmental Coordinator	Conditions of Approval:	
E-mail Address: steven.moskal@bp.com	Attached <input type="checkbox"/>	
Date: February 28, 2017	Phone: 505-326-9497	

NVF1706132701

* Attach Additional Sheets If Necessary