Form 160-5 UNITED STATES				FORM APPROVED		
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMEN SUNDRY NOTICES AND REPORTS ON W Do not use this form for proposals to drill or to abandoned well. Use Form 3160-3 (APD) for such substitutions on page 15 cm. SUBMIT IN TRIPLICATE - Other instructions on page 15 cm.				OMB No. 1004-0137 Expires: July 31, 2010		
BORLAG OF LAND MANAGEMENT				5. Lease Serial No.	11, 2010	
A GOTTONIA				SF-078882		
SUNDRY NOTICES AND REPORTS OF				6. If Indian, Allottee or Tribe Name		
noto and Do not us		,				
abandoned	well. Use Form 3160-3 (A		roposals.			
	UBMIT IN TRIPLICATE - Other inst	tructions on page 2.		7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well			Canyon Largo Unit			
Oil Well X Gas Well Other				8. Well Name and No. Canyon Largo Unit 415		
2. Name of Operator				9. API Well No.		
	Company LP		30-039-25379			
			le area code)	10. Field and Pool or Exploratory Area		
PO Box 4289, Farmington, NM 87499		(505) 32	6-9700	Basin Dakota		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)				11. Country or Parish, State		
Surface Unit G (S	SWNE), 1795' FNL & 1625' F	FEL, Sec. 19, T2	5N, R6W	Rio Arriba ,	New Mexico	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						
TYPE OF SUBMISSION TYPE OF A				TION		
X Notice of Intent	Acidize	Deepen		Production (Start/Resume)	Water Shut-Off	
A Notice of Intent	Alter Casing	Fracture Treat		Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction		Recomplete	X Other	
subsequent Report	Change Plans	Plug and Abando		Temporarily Abandon	The Other	
Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal		
13. Describe Proposed or Completed Op					e duration thereof	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)						
Burlington Resources requests permission to perform a MIT on the subject well per the attached procedure and wellbord schematic.						
OIL CONS. DIV DIST. 3 BLM'S APPROVAL O ACTION DOES NOT					CE OF THIS	
Notify NMOCD 24 hrs prior to beginning operations MAY 1 1 2017		2017	ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS			
			ON FEL	DERAL AND INDIAN LANDS	S	
14. I hereby certify that the foregoing is	true and correct. Name (Printed/Tyne.	d)				
1. I more of overally man more recogning to the date outsook. Framo (1 trinow 1 food)						
Dollie L. Busse			Title Staff Regulatory Technician			
Signature Vallie Busse			5/3/	2017		

entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

NMOCDITY

Office FFO

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would

Approved by

ConocoPhillips CANYON LARGO UNIT 415 Expense - MIT

Lat 36° 23' 14.1" N

Long 107° 30' 16.56" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COP safety and environmental regulations.
- 2. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure.
- 4. Note: Well still has 2-3/8" tubing landed at 6715'. Load well with 2 % KCl water & corrosion inhibitor, as necessary. Perform MIT (Mechanical Integrity Test) above the cement @ 6792' to 560 psig for 30 minutes on a 2 hour chart with 1000 lb. spring. If the test passes, SI the well. RD pump truck and MOL. If the test fails, contact the Rig Superintendent and Wells Engineer.

