Form 3160-5 (June 2015) E SUNDRY Do not use t abandoned w SUBMIT IN	OMB Expires 5. Lease Serial No. NMSF078213 6. If Indian, Allotte	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMSF078213 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well	8. Well Name and N TIGER 6	8. Well Name and No. TIGER 6			
Oil Well Gas Well C     Oil Well Gas Well C	9. API Well No.				
HILCORP ENERGY COMPA	com Phone No. (include area code)	30-045-29581-00-S1 10. Field and Pool or Exploratory Area			
		505-324-5188			
4. Location of Well <i>(Footage, Sec.,</i> Sec 35 T30N R13W NWNW 36.774458 N Lat, 108.18154	290FNL 860FWL			11. County or Parish, State SAN JUAN COUNTY, NM	
12. CHECK THE A	APPROPRIATE BOX(ES) TO IN	NDICATE NATURE O	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> <li>Final Abandonment Notice</li> </ul>	<ul> <li>Alter Casing</li> <li>Casing Repair</li> <li>Change Plans</li> </ul>	<ul> <li>Deepen</li> <li>Hydraulic Fracturing</li> <li>New Construction</li> <li>Plug and Abandon</li> <li>Plug Back</li> </ul>	<ul> <li>Production (Start/Resume)</li> <li>Reclamation</li> <li>Recomplete</li> <li>Temporarily Abandon</li> <li>Water Disposal</li> </ul>	<ul> <li>Water Shut-Off</li> <li>Well Integrity</li> <li>Other</li> </ul>	
Attach the Bond under which the w following completion of the involv testing has been completed. Final , determined that the site is ready for Hilcorp Energy Company rea to return the well to production wellbore schematic.	uests permission to temporarily a on once gas prices rise. Please se	nd No. on file with BLM/BIA a multiple completion or reco after all requirements, includi abandon the subject we	<ul> <li>Required subsequent reports must mpletion in a new interval, a Form 3 ng reclamation, have been complete</li> <li>Il with the intent</li> </ul>	be filed within 30 days	
	Electronic Submission #482646	COMPANY, sent to the g by JOHN HOFFMAN on	Farmington	1	
Signature (Electronic	Submission)	Date 09/10/20	Date 09/10/2019		
	THIS SPACE FOR FE				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease			UM ENGINEER Con willfully to make to any department	Date 09/11/2019 or agency of the United	
(Instructions on page 2)	VISED ** BLM REVISED ** B		I REVISED ** BLM REVIS	ED **	



## Hilcorp Energy Company TIGER 6 Temporarily Abandon API #: 3004529581

## PROCEDURE

	Hold a pre-job safety meeting prior to beginning all operations or during a change in operational scope or initiation of SIMOPs. Properly document all operations via the JSA process. Insure that all personnel onsight abide by HEC safety protocol, including PPE, housekeeping, and procedures. Verify cathodic protection is off and wellhead instrumentation is properly disconnected from wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations. Verify there is no H2S present prior to beginning operations. If H2S is present, take the necessary actions to insure that the operation is safe prior to beginning operations. Observe and record pressures across all strings daily, prior to beginning operations. Notify NMOCD and BLM 24 hours in advance of beginning operations
2.	MIRU service rig and associated equipment, ND casing risers
3. 1	LOTO pumping unit, remove HH and bridle, PU on PR and unseat pump. POOH LD rods and pump.
4. 1	ND tree and NU BOPs. Pressure and function test BOPs to 150/1500 psi.
5. I	PU on tbg, release hanger, scan and visually inspect tbg and POOH
6. I	PU junk mill and RIH to 1700', POOH LD junk mill
7. 1	RIH w/ CBIP on tbg and set at 1620', PT CIBP and casing to 600 psi, POOH w/ setting tool.
8. 1	NDNU tree - verify tree and wellhead are equipped with functional pressure gauges. RDMO
9. (	Contact BLM and NMOCD to schedule witnessed MIT. PT csg to 600 psi.

